

SAT. 27th FEB. 82.

	P/CAR NO	MILEAGE
	51178	53200.
	51203	283350.
	51179.	26940.
	51940	—
	52057.	—
	50398.	42120.
	50940	524600.
	50926.	119780.
	51567	4/R.
	50929.	124370.
Rt. 64257 } Full		
n 64448 }		
n 64609 m/t.		

FULL IN TANKS. NO 1 1,000 NO 2. 2,100. TOTAL. 3,100.

KILL. B.A ROBERTS M. PRICE.

CAR'S - FUELLED ETC:-

51178. 51203. 51179. 51940. 50398.

56335. 56351. 56358. 52057. 56164.

50940/56273. 50926/51567 50929/56361.

LOCO'S FUELLED ETC:-

40093. 25133.

A7480. "A" EXAM CARRIED OUT.

40094 " " " "

Stock Exam.

81032. 25857. 24109. 15935. 25372. 24887.

25375. 80515.

51940. EXHAUST MANIFOLD JOINTS ON NO 2 LOCB.
BLOWING NEW JOINTS FITTED.

40093 A.W.S. NO 2 END. ISOLATED. FAULT FINDING
FOUND RESET BUTTON. CONTACTS OUT OF
POSITION RESET CLEANED & TESTED.

25372 PLAT BATT'S CHARGES ALSO NEW DYNAMO
BOLT. FITTED.

SAT 27-2-82

CA Foulkes P. Cox

cars full on water etc

51179 } T/CAR RUST BATT PUT ON CHARCOE MISO
56358 } ATTENTION TO 4 HOATERS Glow Plugs Changed
4 HOATERS MADE TO WORK.

51192 CAME TO STATION REPORTED BUZZ ON
IN VAN NOT WORKING REPAIRED

51940 CAME OUT TO WANDUDHO AN RADS
FILLED WITH WATER REPORTED ENGINE CUTTING
OUT BOLTS ON.

25133 OUT OF COURSE HOARDER TANK FILLED

40093 CAME OUT TO LOCO DRIVEN REPORTED HORN
HORN SUCH TRACING FAULT FOUND BROKEN
SPRING AND BUILT IN VALVE SEATING. CLEANED.

SUNDAY FEB 28TH 82

	P/CAR	MILEAGES
	51198	121380
	50398	42360
	51179	27000
	57940	
	52057	

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51198 51179 50398
 56337 56358 56164
 57940
 52057

LOCOS ETC: 40093 40079 40094 47536.

~~STATIONARY~~

57940 FLAT BATTERS. PUT ON CHARGE CIRCUIT TESTED ALL BATT CELLS
 TOPPED UP. ALSO DRAGON AIR HEATER REPAIRED. BURNER
 HEAD REMOVED & CLEANED.

56164 FLAT BATTERS. PUT ON CHARGE CIRCUIT TESTED, NR9 DYNAMO
 WIRE RENEWED. HEATERS REPAIRED.

57575 CALLED TO STATION. FLEX AIR PIPE BURST RENEWED
 & TESTED.

MON 1 - 3 - 82

CHAPOUXES D. TRIGES

		P/CAR	MILES
		51202	21370
		50940	24810
		51179	27000
		51940	=
		52057	-
		50398	42360

RUEL IN TANKS NO1 400 NO2 1800 TOTAL 2,200

CARS RUEL ON WATER etc.

50398 - 51179 - 51940 - 51202 - 50940
 56164 56358 52057 56349 56273

Locos

47487 - 25133 - 40093 - 40094 - 40079 25205

CONCRETE STOCK

Bsu SL SL SL SL SL SL
 34682 - 24840 - 24126 - 24843 - 15987 - 25309 - 24846 - 35

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51200 60402
56359 56158.

LOCOS 25119. 25183 25205.

A. EXAMINATION CARRIED OUT ON 25205.

50399 CALLED TO STATION L.H. HEATER NOT WORKING
NEW GLOW PING FITTED & TESTED.

40094 DR REPORTED RED TAIL LAMP NOT WORKING N^o 2
END. A. SIDE. NEW BULB & LAMP HEADER
REPAIRED.

25205 MAIN AIR PIPE TO TRAP VALVE FRACTURED IN
BRAZING PIPE REMOVED & REPAIRED. REPAIRED.

25119. AIR BRANES SMALL ADJUSTERS, ADJUSTED TO
1 1/2" & BRANES TESTED.

RAIL TANKER 64257 UNLOADED 7.435 GALS

D. HILL. M. PRICE.

CARS. PULLED ETC:-

50398. 50932
56164. 51563.

50398. CALL TO LLANDUDNO. DRIVER REPORTED UNABLE TO START
AND INS. EXAM & FOUND PLAT BATTY. CAR BROUGHT
ON SITE. PUT ON CHARGES ETC:-

47536. CALL TO STATION. DR REPORTED WIND SCREW
WIPOR UNCOUPLED. N^o 1 END. DR'S SIDE. ARM.
REPLACED ADJUSTED & TESTED.

50933. N^o 1 WING EXHAUSTOR & ALTERNATOR BOLTS
MISSING NOW BOLTS FITTED & ADJUSTED.
N^o 2 WING ALTERNATOR BOLTS OFF PULLEY. BOLTS
REPLACED & ADJUSTED

51183 CALL TO LLANDUDNO. N^o 6 FUSE BLOWN NOW
FUSE FITTED & TESTED

TUE 2 - 3 - 82

CHARLES D. TRIGGS

	P/CHG	MILES
	50927	73540
	51179	27230
	50940	825100
	50398	42400
	50402	U/R
	50938	793010
	50572	U/R
	50551	N/F
	50562	N/F
	50590	87590
	51566	48770
	50933	N/F

FUEL IN TANKS NO1 6000 NO2 2,800 TOTAL 8,800

CHAS FUEL OIL WATER ETC.

50927 - 51179 - 51566 - 50938 - 50402 - 50398 - 50940
 56214 56358 50933 56411 56158 56164 56273

50562 - 50572
 59227 51226
 50590 50551.

Locos Rg - Ins 40093 - 40094 - 25205
 50938 FUEL BATT PUT ON CHARGE ATTENTION TO HEATERS
 56358 - FUEL BATT PUT ON CHARGE.
 50398 - FUEL BATT PUT ON CHARGE
 50590 - FUEL BATT PUT ON CHARGE ALSO ATTENTION TO HEATERS
 50551 - FUEL BATT PUT ON CHARGE ALSO RELAIRES AND
 ATTENTION TO ENGINE LIGHT CONTROL PANEL SYSTEMS &
 FAULTY WAMP HOLDERS REMOVED AND CLEANED AND MADE
 TO WORK.
 50933 ATTENTION TO HEATERS MADE TO WORK ALSO ENGINE
 PANEL LIGHT BULBS FITTED
 50940 ATTENTION TO HEATERS MADE TO WORK.
 50402 ATTENTION TO HEATERS MADE TO WORK

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 57174
56350

Locos FUELLED ETC: 47258 47100 25042. 25733.

CALLED TO STATION:

50927 NO NIGHTING CONTROL IN GUARDS VAN N^o 4 FUSE
BROWN NEW FUSE FITTED.

25042 LOSS OF POWER. FIELD DIVERLT MOTOR OVER
SHOT. EXAMINED. WIRE BROKEN ON BRAKE SOLENOID
REPAIRED & FIELD DIVERLT. STATIC TESTED.

57174 N^o 1 ENG EXHAUSTER & ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

D. HILL. M. PRICE.

CARS FUELLED ETC:

51200 51178
56359. 56325.

50940. CALL TO STATION. N^o 1 ENG LOW IN COOLANT AND WILL
NOT RUN. TOPPED UP & TESTED.

Loco's FUELLED ETC:-

40148. 47487.

40148 WINDSCREEN WIPER N^o 2 AND DR'S SIDE REPAIRED.

51178. N^o 1 ENG EXHAUST MANIFOLD. JOINTS CHANGED.
ENG RUN UP & TESTED.

47487. WORTH FAULT BRIGHT. FLAC RESET & TESTED
ALSO LUB OIL ON MAINS & BLOCK "B" BANK.
CLEANED & ROCKER COVERS SCREWED UP.

51179. CALL TO BLANDFORD N^o 2 ENG STARTER MOTOR
STUCK IN PULWITZER REMOVED RUN UP & TESTED

WED 3-3-82

Aboukles D. TIGGS

	P/CAR	MILES
	50927	73670
	50402	U/R
	51200	13360
	51174	152720
	50933	N/P
	51566	49050
	50804	N/P
	50765	N/P
	51178	53730

Fuel in Tanks No1 5,400 No2 1,600 TOTAL 7,000

CARS Fuel oil water etc.

50927 - 50402 - 51200 - 51174 - 50933 - 50804 - 51178
 56214 56158 56359 56350 51566 50765 56335

Locos! 47487 - 40094 - 25042

"A Exam" 40093 ^{1460?} COMPLETED AT 112830 MILES.

CONCRETE STEEL.

34682 - 24840 - 24126 - 24843 - 15987 - 25309 - 24846 - 35776

SU 24840 HAS PART DUE TO DYNAMO BEARING BEARING NOT FITTED.

B. A. ROBERTS . M. PRICE .

CARS FUELLED ETC.: 57920
56504.

LOCOS FUELLED ETC.: 25220 25042 . 40126 . 40094 .

H7440 CALLED TO COLWYN BAY . LOCO FAILED ON FLINER
TO H/HEAD . LOW LUBS OIL PRESSURE . EXAMINED LUBS
OIL PIPE BY LUB OIL FILTER FRACTURED . LOCO ISOLATED
& HAULED TO H/HEAD TO SAVE DELAY .

57920 DRAGONAIR HEATER SMOKING BADLY & FILLING COAK
WITH FUMES . HEATER BURNER REMOVED & STRIPPED
& CLEANED . REPAIRED & HEATER TESTED .

56504 FRAT BATT'S PUT ON CHARGE . BATTERY CELLS TOPPED
UP & NO 3 DYNAMO FUSE RENEWED .

D. HILL . M. PRICE .

CARS FUELLED ETC.:-

50927 51178.

56214 56335.

Loco's FUELLED ETC.:-

47462. CALL TO STATION. DR REPORTED UNABLE TO SHUT CAB
WINDOWS 2ND MAN'S SIDE REPAIRED.

50927. AIR LEAK FROM U.P. VALVE BOX FORWARD U.P. VALVE STUCK
REMOVED STRIPPED CLEANED REPLACED & TESTED.

50497 } CALL TO STATION. NEI WNG 50497 SHORT OF COOLANT RAD
50443 } TOPPED UP & TESTED. 50443 BUZZER NOT WORKING
ADJUSTED. IN CAB.

50940. CALL TO GLANDUANO. DR UNABLE TO START NO 1 ENG.
FOUND STATOR MOTOR STUCK IN FLYWHHEEL. REMOVED & TESTED.

THUR 4-3-82

CARROLLS D. TRIGGS.

P/CAR	MILES
51920	37080
50927	73700
51178	53850
50765	N/P
50804	N/P
50501	2970
50448	92040
50933	N/P
51566	49340
50940	525530
51174	15362

FUEL IN TANKS NO1 4,300 NO2 1,600 TOTAL 5,900

CARS FUEL OIL WATER ETC.

51920 - 50927 - 51178 - 50940 - 51174 - 50765 - 50933 59150
 56504 56214 56335 56273 56350 50804 51566 50448

Locos:- 25133.

50940 ATTENTION TO MACHINERY LIGHTS FUELING PAVILION CURR
FOUND LAMPHOLDER RAILWAY RAILROADS

B.A. ROBERTS. M. PRICE.

CARS FURRED ETC. 57199
56353

LOCOS FURRED 25042. 25220 47207. 40058
40093.

57566. CALLED TO STATION HEATER NOT WORKING. NEW
GLOW PLUG FITTED.

25220 SANDERS MAKING TO WORK.

D. HILL. M. PRICE.

CARS FURRED ETC:-
51920. 50398.
56504. 56164.

LOCOS FURRED ETC:-
47249. 47501.

50403. CALL TO STATION. HEATERS NOT WORKING
R.H. GLOW PLUG CHANGED - L.H. HEATER 1/2 AMP
FUSE IN PANEL BLOWN. NOW FUSE FITTED. HEATERS
TESTED. REPAIRS CARRIED OUT @ LLANDUDNO.

50398. NO. 1 ENGINES EXHAUST MANIFOLD JOINTS
BLOWN OUT NEW JOINTS FITTED & TESTED

56164. HEAT BATT'S PUT ON CHARGES CIRCUIT CHANGED.
NO. 9 BATT'S FUSE BLOWN. NOW FUSE FITTED & TESTED.

47432 CALL TO STATION. DRIVER REPORTED D.T.H.
TRIPPED. CIRCUIT RESET & TESTED.

56325. CALL TO STATION HEATERS NOT WORKING
UNABLE TO REPAIR @ STATION. SET WORKS
TO LLANDUDNO. CIRCUIT CHANGED NO. 6 FUSE
BLOWN NOW FUSE FITTED & TESTED.

PR1 5-3-82

Charles D. Riggs

2111.8 2520.1 1.1

P/CAR	MILES
50398	43000
50933	N/F
51566	49620
51199	11060
51920	37110
52051	390840
51936	U/R
50927	73840
51174	18332

FUEL IN TANKS NO1 2,400 NO2 1,500 TOTAL 3,900

CHAS RIVER OIL WATER LOG

50398-51566-51199-51920-52051-50927 51174
 56164 50933 56353 56504 51936 56214 56350

Locos River ^{Bonus} 25042-47501-47249-40093

47249 A Exam Complicated Miles U/R. Blocks OK. LWB OK.
 Suck Tank Topped up. (400 Gms of Fuel.)

COACHING STICK

BRZ S1 S1 CR S2 S2 S2 BS1
 35176-24846-25309-15987-24843-24126-24840-34682

52051:- Driver Reported Unable to Start - No1 Engine Bound to Main
 and local, bleeding fuel system therefore run up

B.A. ROBERTS, M. PRICE.

CARS FUELED ETC; 50405.
56163.

LOCOS FUELED ETC; 40093. 40029. 47207
25322.

A-EXAMINATION ON D 47207.

56504. HEATER NOT WORKING. FUEL PIPE TO TANK BROKEN
(IN STATION) REPAIRED.

56163. FLAT BATTERS PUT ON CHARGE N°3 DYNAMIC FINE
RENEWED, ALSO R.H. OUTSIDE JUMPER CABLE
FOUND DAMAGED. REMOVED FOR SAFETY.
N.I.S @ CHESTER.

25322 N°2 - N°3 EXHAUST MANIFOLD JOINTS BURNING
NEW JOINTS FITTED.

51178 CALLED TO STATION N° AIR-ABLE WENT NEW
BULB FITTED.

SAT 6-3-82

CHAPULTEPEC DISTRICTS

	P/CAR	MILES
	51188	77630
	51566	49910
	50933	N/F
	51920	57150
	50405	U/R
	50469	-
	50499	-
	51199	11180
	51177	24810
	51182	N/F

FUEL IN TANKS No1 No2 TOTAL

CARS FUEL OIL WATER ROT

				50469				
51920	-	50405	-	51188	-	51566	59174	51199
56504	56163	56348	50933	50499	56353	56341	56361	51177

Locos Fuel has 25220 25042 - 47207 - 40093 - 47450

CONCRETE STEEL

BEZ	SL	SL	SL	SL	UL	SL	BSC	
80840	-	24680	-	24043	-	25422	-	24881
								16066
								24454
								35048

51566! - NO1 ENGINE UNABLE TO START DUE TO RAULTY STRUCTURAL MOTOR FINAL DRIVE ISOLATED.

51920 ATTENTION TO DRAGON AND HUNTER AND LOW IN FUEL BY BLEEDING FREE OF AIR ALSO PANEL BULBS FITTED LAMP REPAIRS DONE

50405: ATTENTION TO PANEL LIGHT CURTAIN REPAIRS MADE TO NO1

51182: DRAIN REPAIRS UNABLE TO MARK AIR PRESSURE TRENCH PAULI TO FLEXIBLE AND PIPE VALVE STROKE REPAIRED

B.A. ROBERTS, M. PRICE.

CARS FUELED ETC. 50938
56411.

LOCOS FUELED. 40093. 25322. 40197. 40093

40047 BROUGHT ON SITE BY DRIVER. HEADER TANK
NOW. TOPPED UP & GAUGE GLASS WASHERS
SCREWED UP.

56164 CALLED TO MANDUDNO W/WIPER UNCOUPLED
ARM REFITTED & ADJUSTED.

57182 CALLED TO MANDUDNO. NO AIR & AXLE
LIGHT. CABLE UNCOUPLED ON N° FTDR
REFITTED & TESTED.

25322 SANDERS MADE TO WORK.

SUN 7-3-82

CAFOULDES P. Cox

	P/CMA	MILES
	50469	—
	50499	—
	51178	54560
	51177	25040
	50938	803590
	51199	11180

CARS ON WATER etc

51178 - 51177 - 50938 - 51199 50469 51182
 56335 56361 56411 56353 50499 56341

Loco's 40093 - 40197 - 47438
 (47438 (650 fuel))

COVERING STEEL

BRN SE SN SW CA SA SL BRN.
 30682-24840-24146-24843-15987-25309-24846-35176

56335 - ATTENTION TO AIR HORN SYSTEM VALVE CLEANED SERVICED AND HORN ADJUSTED. TO WORK

59174 - FIRST BATT DUE TO LIGHTING AND HORN BATTERIES LEFT ON ALL NIGHT PUT ON CHARGE

51199 ATTENTION TO HAND BRAKE LIMIT CONTROL SWITCH MADE TO WORK.

Monday 8th March 82.

	P/CAR NO	MILEAGE.
	51182	NOT FITTED.
	51920.	37520.
R/T 64448. M/T.		

FUEL TANKS. No 1 3,600 No 2 5,000. TOTAL 8,600.

B.A. ROBERTS. D. HILL. M. PRICE.

CARS. PULLED ETC:-

50938. 51199. 51177. 51182. 51920.

56411 56353. 56361. 56341. 56504.

50469/59174/50499.

Locos PULLED ETC:-

25220. 25042. 40093. 40197. 47449.

Stock EXAM.

35176. 24846. 25309. 15987. 24843 24126.

24840. 34682.

56504. FLAT BATT'S. PUT ON CHARGE ETC:- ALSO DRAGON. AIR HEATER MADE TO WORK.

50469. NO 1 ENGINES WILL NOT RUN FUEL SYSTEM FOUND AIR LOCKED BLED + TESTED.

50499 NO 1 ENGINES THROTTLE MOTOR STUCK WILL NOT REV. UP. MOTOR OILED + TESTED.

51920. NO 2 ENGINES EXHAUSTOR + ALTERNATOR BOLTS MISSING. NEW BOLTS FITTED + ADJUSTED.

34682 MK1. FLAT BATT'S PUT ON CHARGE. CIRCT CHECKED. FOUND NO 9 FUSE BLOWN. NOW FUSE FITTED + TESTED.

MON 8-3-82

CHARLES P. Cox

Rube / MS

51182 - 50933 - 51920
56341 51566 56504

Locos 25042 - 25220

51199 - CAME OUT TO STATION DRIVER REPORTED UNABLE
LIGHT BULB WANTED NEW LAMP FITTED.

52046 - CAME OUT TO MANDUDNO STATION TO SAVE DELAY
DRIVER REPORTED UNABLE TO GET FORWARD OR
REVERSE HANDLE IN CONTROLLER ON ARR AT STATION FOUND
GROSS IN SIDE CONTROLLER FLOW BLOWN WINDOW - REPAIRS
AT MANDUDNO STATION REMOVING AND CLEANING CONTROLLER

47472 - CAME OUT TO STATION DRIVER REPORTED LOSS OF
POWER AND BARTH FAULT RELAYS TRIPPED AND WERE
NOT RESET BARTH SWITCH PUT TO FAULT, TRACING FAULT
AT DANBOR STATION TO SAVE DELAY. FAULT FOUND TO
BE BURNING PLATE IN R.T.M CONTROL START SWITCH IN
NO 2 END CAB SHORTING ON LIVE TO BARTH REMOVED
AND REPAIRED ALL SWITCHES RELAYS RESET ALSO TRAIN
HEATING ARE TESTED AND OK.

51566 - DRIVER REPORTED UNABLE TO START NO 1 AND 2
ENGINES TRACING FAULT TO FOUND NO 1 AND 2 STARTER
MOTORS FAULTY NO 1 AND NO 2 FINAL DRUMS ISOLATED
FOR FURTHER ATTENTION WHEN RATED AT CHESTER.

50933 - DRIVER REPORTED UNABLE TO START NO 2 ENGINE
FOUND AIR LOCK IN RUBER SYSTEM DUE TO RUBER TANK BUMP
TANKS FILLED AND SYSTEM BLEEDING FREE OF AIR ENGINES
RUN-UP.

D 7/19/95

Called to Hlandudra car

50405 Driver unable to get
Power Blowing fuses to be

dragged from Hlandudra Tomorrow

40003 Fuelled oil water
and Exhausters topped up

25261 Fuelled oil water and
Exhausters topped up 47207

Fuelled oil water and Exhausters
topped up called to station

Car 51188 no 1 Engine cutting out
Both Radiators topped up

Cars Fuelled etc

51188 50398

Tuesday, 9th MARCH 82

	P/LAR	MILMGS
	50938.	803900.
	51199.	11330
	50522.	—
	50465.	—
	51182	N/FITTED.
	52046.	4/R.
	50939.	439580
	50398	43900.
	51566.	50360
	50933	—

ROLINTANKS NO.1 2,300 NO.2 5,000 TOTAL. 7,300.

BALBOURTS J. Hill M. PRICE

CARS FUELLED ETC.:

50938. 51199. 51182. 52046. 50398.
 56411 56353. 56341. 50939. 56164.
 51566/50933. 50522/59206./50465.

Loco's FUELLED ETC.:

25220. 25042. 47472. 40197.
 40007.

Stock EXAM.

80823. 24680. 24043. 25422. 24881 16066.
 24434. 35048.

40197. Dr Reported. FIRE BELL'S. RINGING + NO FIRE.
 FAULT FINDING. NOW PROBS FITTED AROUND FIRE AND
 + TESTED. ALSO. LOAD REGULATOR TO LEXAM.
 2 NEW TIPS. FITTED + TESTED + BOB PLATES.
 DRAINLED OF OIL ETC.:

50465. Dr Reported. L.H. HMTATOR NOT WORKING 25 AMP FUS
 IN PANEL BROWN. NOW TIPS FITTED + TESTED.

59206. FLAT BATT'S. PUT ON CHARGES CIRCT CHECKED ETC.:

50522. R.H. HMTATOR MADE TO WORK.

50938. NO.1 ENGINE EXHAUSTOR + ALTERNATOR BOLTS OFF
 PULLEY ALL REPLACED.

56411 TWO TONS HORN ADJUSTOR + TESTED.

TUE 9-3-84

BA Foulkes P Cox.

50939 Called out to station driver reported heater not working unable to get to work unit taken out of service new heater wanted faulty fuel sling on inside heater. Bad fumes inside coach.

50405 Called out to Wandsworth station unit failed over night reported unable to start engines hauled onto shed tracing for fault no control fuse blown found short in right hand side engine light. lamp replaced all repaired cure tested ok.

Fuel bus 2nd

51193
56602

51182 Attention to heaters also air horn made 56341 to work.

50932 Attention to marker light. Cure repaired 51569

25220 Called out to yard attention to boiler made to work. out of cover attention.

D Triggs

47438 fuelled oil water and exhausters

topped up 25322 fuelled oil water

and exhausters topped up 40197

Fuelled oil water and exhausters

topped up called to London

windscreen wiper arm uncoupled 51179

replaced and adjusted

Cars fuelled etc

51182

25051 fuelled oil water

and exhausters topped up

WED. 10TH MARCH 82.

P/CAR NO	MILEAGE.
51188.	78160.
50398.	44140.
51569.	u/r.
50932.	730.
52046.	40000.
50939.	39640.
51182.	n/r.
50504.	—
50445.	—
51193.	9520.

FUEL IN TANKS No 1 1,000. No 2 5,000 TOTAL 6,000.

B. A. ROBERTS. D. HILL. M. PRICE.

CAR'S FUELED ETC:-

51188. 50398. 51569. 52046. 51182.
 56348. 56164. 50932. 50939. 56341.
 50504/59155/50445. 51193/56502.

LOCO'S FUELED ETC:-

25057. 47449. 40197. 40167.

STOCK EXAM.

35176. 25309. 15987. 24843. 24126. 24840.
 34682. 24846.

56502 DRAGON AIR HEATER NOT WORKING BURNER.
 HEAD REMOVED CLEANED. FOUND BLUETO.
 LEAD'S. BURNT NOW LEAD'S WANTED. CAR TO
 CHESTER FOR REPAIRS.

51188. DRIVER REPORTED. VACUUM LEAK THROUGH D.P.D.
 VALVE. SET RUN UP & TESTED NO FAULT FOUND.

50445. DRIVER REPORTED. No 1 MAINS CUTTING OUT. EXAM
 FOUND FAN BOLTS MISSING. ALSO FOUND FAN
 MOTOR. HOLDING STUDS BROKEN. MOTOR REMOVED
 3 NEW STUD'S. FITTED. MOTOR REPAIRED NEW
 BOLTS FITTED. RAD TOPPED UP AND RUN UP & TESTED

25057. DR. REPORTED. BOILER NOT WORKING. RUN UP &
 TESTED SUSPECT. ARCH. DEFECTIVE. CREW MAIN'T
 INFORMED.

WED 10-3-82

WABOLUES P. COX.

25057 OUT OF COURSE ATTENTION DRIVER REPORTED LOSS OF CONTROL POWER. TRACING FOR FAULT FOUND 31 STARTER CONTACTOR BURNT AND STUCK IN. REMOVING AND CLEANING CONTACTOR TIPS AND RE TESTING CIRC. RESTORED FOR POWER OK.

51198 CALLED OUT TO STATION REPORTED BUZZER NOT WORKING IN VAN. ADJUSTED TO WORK.

FVBC POINT LUL :- 51193 - 51194
56502 56345

LOCOS, 25042

56502 DISEMPOWER HEATER HT CABLES BURNT INSIDE HEATER.

D Yriggs

25261 Fuelled oil water and

Exhausters Topped up 40003 Fuelled

oil water and Exhausters Topped

up 25057 Fuelled oil water

and Exhausters Topped up

called To Bangor Driver unable

To start no. Engine car 51194

Starter motor Defective set Taken out

of service Engine & final drive Isolated
for further attention

Cars Fuelled etc

51199

THURSDAY. 11TH MARCH. 82.

P/CAR NO	MILEAGE.
51199.	11730.
50977	—
51569.	95800.
50932.	1030.
51193.	9520
51194.	92820.
50465.	—
50522	—
50398.	44290

FUEL INTAKES NO 1 1,000 NO 2 3,700. TOTAL. 4,700.

B.A. ROBERTS. D. HILL. M. PRICE.

CAR'S. FUELLING ETC:-

51199. 50977. 51569. 51193. 51194.
 56353. 56260. 50932. 56502. 56345.
 50465/59206/50522. 50398/56164.

LOCO'S FUELLING ETC:-

40167. 47187 25057. 40197. 47255.

STOCK EXAM.

80P23. 246fo. 24043. 25422. 24881 16066
 24434. 35048.

47187. "A" EXAM CARRIED OUT. BOILER FITTED.
 50398. R.H. MARKER. LIGHT NOT WORKING. EXAM + FOUND
 BULB BLOWN. NEW BULB FITTED & TESTED ALSO.
 D.S.D. ISOLATED, DEISOLATED. & TESTED UNABLE TO ISOLATE
 50977. NO 2 ENGINE & EXHAUSTOR + ALTERNATOR BELTS.
 MISSING NEW BELTS. FITTED. & ADJUSTED
 59206. PLAT BATT'S. PUT ON CHARGES CIRCUIT TESTED.
 FOUND. NO 3 DYNAMO FUSE BLOWN. ALSO WIRE
 TO FUSE UNCOUPLED. REPLACED & TESTED
 47255 A.W.S. ISOLATED, NO 1 END. FAULT FINDING.
 FOUND. WIRE TO RESET BUTTON UNCOUPLED
 REPLACED. TIPS CLEANED. A.W.S. DEISOLATED.
 & TESTED. NEW SEAL FITTED
 246FO MK. PLAT BATT'S CHARGES ETC:-

THUR 11-3-82

CARBURES P. Cox.

FUEL INS 40082-40167

46197 CAME OUT TO YARD DRIVER REPORTED FINE BARS
RINGING AT TIMES CAR TESTED UNABLE TO FIND ANY FAULT.
WAS CHECKED BY YARD.

51201 } FUEL INS ATTENTION TO 2 HORIERS WOULD NOT FIRE
56347 } UP BLOW PUS SERVICES 2 MAKE TO WORK. PLUM
WAS 2 HORIERS ON T/CAL MAKE TO WORK AND LOCK
IN FUEL SYSTEM AND BLOW PUS SERVICES

50977 CAME OUT TO LLANDUDNO STATION REPORTED
ENGINE WILL NOT START AFTER SHUTTING DOWN FOUND
TO HAVE AIR LOCK IN FUEL SYSTEM BLEEDING PROBS
OBTAIN ENGINES RUN-UP.

56260 CAME OUT TO STATION REPORTED NO HORIERS PERMIT
HORIER MAKE TO WORK.

D Friggs

47255 Fuelled oil water

and exhausters topped up

25042 Fuelled oil water and

Exhausters Topped up 40007 Fuelled

oil water and Exhausters Topped up

Called to Llandudno car 51199

driver unable to start no 1 Engine Starter

major Defective Engine x final

drive Isolated set brought on

shed. cars fuelled etc

51199

FRIDAY. 12TH MARCH. 82.

P/EAR NO	MILEAGE.
51193.	9750.
50977.	—
51569.	412.
50932.	1330.
50561.	—
50589.	—
51200.	14860.
51199.	11860.

FUEL IN TANKS N^o1 1,000. N^o2 1,800. TOTAL. 2,800.

B. A. ROBERTS. D. HILL. M. PRICE.

CARS. RULLED ETC:-

51193. 50977. 51569. 51200. 51199.
 56502. 56260. 50932. 56359. 56353.
 50561/59240/50589.

Loco's RULLED ETC:-

47449. 40197. 25057. 47255. 40167.

Stock Exam.

35176. 24846. 25309. 15987. 24543. 24126.
 24840. 34682.

47449. 40197. 40167. "A" Exam's Carried out.

50561 PLAT BATT'S CHARGED ETC:-

59240. Heaters NOT WORKING N^o6 FUSE BLOWN NOW
 FUSE FITTED. Heaters TESTED

FRI 12-3-82

D. TROOS P. COA.

47445 Fuelled oil water and
Exhausters topped up

40009 Fuelled oil water and
Exhausters topped up

25042 Fuelled oil water
and Exhausters topped up

called to Hlandudra car 51175
Heater making to work

FRI 12-3-82

CARROUKES

CARS RVR Ins. etc. 51175 - 50409
56333 56152

47449 CRANED OUT TO STATION DRIVE ROBERTS OIL
LEAKING FROM UNDER HOOD SUSPECT BURNING BED PLATE
DRAIN PILL DRAINED OFF ON "A" 8 AM. 02.30 HRS.

LOOS RVR Ins. 25057 - 47491 - 40012

DAILY EXAM OF LEAKING STOCK ETC

82 81 81 84 01 81 834
80823-24043-25422-24881-16066-24454-35048

24043 BITE FAULT ON HEATING CURE RECEIVED FROM
POUND CONTRACTOR THIS FAULT WAS NOT CEMENTED CURE RECEIVED

50409 REPORTED LOSS OF AIR RECEIVED FAULT TO UNLUBRICATED
VALVE SICKING VALVE SICKING CEMENTED

SAT 13TH MARCH 82.

P/CAR NO MILLAGES.

50940.	527210.
50399.	279610.
50525.	—
50473.	—
50409.	117720.
51175.	177170.
50932.	1630.
51569.	—
50977.	—

R/T. 68205. Full.

FUEL IN TANKS. NO 1 1,000. NO 2 700. TOTAL. 1,700.

BA ROBERTS, D HILL M. PRICE.

CARS PURCHASED ETC:-

50940 50399. 50409. 51175. 50932. 50977.
 56273. 56159. 56152. 56333. 51569. 56260.
 50525/59181/ 50473.

Locos. PURCHASED ETC:-

47491 40012. 40197. 25057. 40164 40167.
 40126.

56273 PLAT BATT'S CHARGED ETC:-
 50525. NO 2 ENG MAIN POLLS JOINTS CHARGED.
 50409. NO 2 ENGINES ~~REPAIRED~~ SEIZED. ISOLATED.
 51175. NO 1 ENG PAN BELTS MISSING NEW BELTS FITTED.
 25057 "A" W/AM CARRIED OUT.

D Briggs P box

447448 Fuelled oil water
and Exhausters Topped up

25057 Fuelled oil water
and Exhausters Topped up

40003 Fuelled oil water and
Exhausters Topped up

Called to Llandudno car no 2

Engine cutting out air locked Bleed
and run up cars Fuelled etc

51202 51183

50792 50759

SUNDAY MARCH 14TH 82

	P/CAR	M/AGES
	50398	44750
	50409	117960
	50525	—
	50473	—
	51202	215360
	50759	—
	50792	—
	51183	5640

D.F. HILL. M. PRICE.

CARS FUELMED ETC: 50398 50409 50525 51202
 50759 51183 50473 56349
 50792 56344.

LOCOS FUELMED ETC: 40012 47563. 40164 40167

STOCK EXAM. 35776 24846 25309 15987 24843
 24126 24840 35119.

35119 FLAT BATTERIES PUT ON CHARGE WIRE TESTED. BATTERY TERM
 LIDS LOOSE SCREWED UP + NO3 DYNAMO FUSE RENEWED

47479 CAMEL TO STATION E.T.H NOT WORKING. E.T.H LEAKING
 FAULT RELAY TRIPPED RESET + TESTED

47563 COOLANT HOSE PIPE RENEWED ON A-BANK PRESSURE
 CHARGED

50473 NO. 1 ENG EXHAUST MANIFOLD TIGHTENING
 RENEWED.

MONDAY, MARCH 15TH 82.

	P/CAR NO	MILEAGE.
	51175.	17735
	50402.	UNROADABLE.
	51197.	5700.
		9050.
68205. M/T		

FUEL IN TANKS. NO1 5,600. NO2 3,000 TOTAL. 8,600.

D. TRIGGS. B.A. ROBERTS. P. COX.

CARS. FUELLED ETC:-

51175. 50402. 51197. 56398. 50409.
 56330. 56158. 56339. 56164. 56152.
 50525/59181/50473 51202./56349.
 50759/50792 51183/56344.

LOCO'S FUELLED ETC:-

47479. 25057. 25113. 40197. 40167. 40164. 40012.

- 50402. NO1 LNG MANIFOLD JOINTS CHANGED.
- 56158. PLAT BATT'S PUT ON CHARGE ETC:- L.H. GLOW PLUG CHANGED.
- 51197. NO1 LNG. EXHAUSTOR & ALTERNATOR BELTS OFF REPLACED.
- 56339. WINDSCREEN WIPER. REPAIRED.
- 47479. A.W.S. NO1 LNG ISOLATED. FAULT FINDING RESET BUTTON. TIPS NOT MAKING TIPS CLEANED RESET. & TESTED.
- 25113. SANDERS. MADE TO WORK BOTH BODIES.

D.F. HILL. B. PRITCHARD

CARS FUELLED. 57194 50940
56345 56273.

LOCOS FUELLED ETC. 47439. 40167. 40012.

57948 CALLED TO STATION BOTH ENGS CUTTING OUT, ROADS
TOPPED UP & TESTED.

57933 CALLED TO STATION HEATER NOT WORKING. NEW GLOW
PLUG FITTED - TESTED.

50398 CALLED TO WHANDUENO NO 6 FUSE BROWN NEW
FUSE FITTED.

56330 FLAT BATTERS PUT ON CHARGE. CIRCUIT TESTED, ALL
BATTERY CELLS TOPPED UP. NO 9 DYNAMO FUSE RENEWED

57194 NO 1 ENG EXHAUSTER & ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

Tuesday 16th March 82.

	P/CAR NO	MILES
	51569.	—
	50932	2160
	51175	177440.
	51197.	9050.
	51202.	215360.
	51183	5740
	50792.	—
	50759.	—
	50940.	27720.
	50561	—
	50589.	—
R/T 68205. M/T.	50409.	118050
	51194.	93260.

FUEL IN TANKS NO1 4/500. NO2 3,000 TOTAL. 7,500.

S. TRIGGS. B. A. ROBERTS. P. COX.

CAR'S FUELLED ETC:-

50409. 51194. 51202. 51183. 50792. 50940.
 56152. 56345. 56349. 56344. 50759. 56273
 50561
 51569. 51197. 51175. 59240.
 50932. 56339. 56333. 50589.

LOCO'S FUELLED ETC:-

47564. 40012. 40197 40055.

STOCK DAM BUILT.

35062. 16114. 25415. 25884. 25259.
 25375. POSIS.

50940. NO TRAIN LIGHTS FROM VAN. NO6 FUSE CHANGED.

56273 FLAT BATT'S. CHARGED ETC:-

50561. NO2 WND + R/DR ISOLATED FAN BELTS MISSING ALSO 2.
 STUD'S. IN FAN MOTOR BROKEN. NEW STUD'S + BELTS FITTED.
 WND + R/DR DEISOLATED + TESTED

50924. FLAT BATT'S. CHARGED NO3 FUSE FUSE CHANGED &
 R. H. WATER GLOW PLUG CHANGED.

40055. WINDSCREEN WIPER DR'S SIDE NO2 WND NOT WORKING.
 VALVE REMOVED CLEANED REPLACED & TESTED.

MKI 25259. DYNAMO BELTS MISSING NEW BELT FITTED.

D.F. HILL. B. PRITCHARD

CARS FUELLED ETC: 51179
56358'

LOCOS FUELLED ETC: 25253, 25057, 47328 40055
40197

56164 CALLED TO STATION L.H. HEATER NOT WORKING.
NEW GLOW PLUG FITTED.

51581 CALLED TO STATION. NO.1 ENG WONT START. FUEL
SYSTEM AIR LOCKED. SYSTEM BLED & TESTED

25253. FRAT BATTERIES PUT ON CHARGE. CIRC TESTED
AMM BATTERY CELLS TOPPED UP.

47328. DR REPORTED ENG ROOM OILY & ENG BLOCK.
COVERED IN OIL. SEVERAL ROCKED COVERS
MOOSE ETC. SEREWED UP. & ENG ROOM CLEANED

51179 NO.1 ENG EXHAUST MANIFOLD JOINTS BLOWING NEW
JOINTS FITTED.

WED 17-3-82

CAF FOLKES D. TRIGGS. P. COA.

	P/CR	MILES
	51194	93300
	50409	118100
	51179	29150
	51569	U/R
	50932	2460
	50561	—
	50589	—
	50938	5290
	51202	215510
	51197	9050

R/T 68205 m/t
R/T 64200. Full

FUEL IN TANKS No1 2,900 No2 3,000 Total 5,900

CALLS RUEL OIL WATER ETC.

51194-50409-51179-51569-50938-51202-51197 59200
56345 56152 56358 50932 56411 56349 56339 50589

WOLOS:- 47488 - 47110 - 40197

CONCHING STEEL BOX
BRN SL CL SL SL NAV.
35048 - 21434 - 16066 - 24881 - 24043 - 80823

50589 DRIVER REPORTED NO POWER WHEN IN FOREWARD
TRACING FOR FAULT FOUND TO BE FAULTY AIR PRESSURE
CONTROL SWITCHES CONTACTOR TIPS CLEANED MADE TO WORK.

59200 RUF BAIT PUT ON CHARGE.

51569: DRIVER REPORTED UNABLE TO START DRYDOME BOUND
STABIL PINION STUCK IN R/WHEEL. REPT. BRG RM-UP

40197 OUT OF COURSE ATTENTION NO GMS SUMP ON
R/T IN SUMP

D. HILL P. PRITCHARD.

CARS FUELLED ETC:-

51188.

56348.

47267.

Locos. FUELLED ETC:-

25057.

47581 CALL TO STATION. BLUE FAULT LIGHT BRIGHT. EXAM + FOUND.

EARTH FAULT FLAG TRIPPED. RESET + TESTED FOR POWER O.K.

51188. NO1 ENG EXHAUSTOR + ALTERNATOR BELTS OFF PULLEY ALL

BELTS REPLACED + ADJUSTED.

56348. HEATERS NOT WORKING NO6 FUSE CHANGED ALSO L.H

GLOW PLUG CHANGED HEATERS TESTED.

47267. DR REPORTED. NO1 ENG DROP LIGHT WINDOW WILL NOT OPEN.

EXAM + FOUND "X" SPRING BROKEN PANEL REMOVED NOW SPRING

FITTED PANEL REPLACED + TESTED.

56348. CALL TO Llandudno. DRIVER REPORTED HEATERS NOT WORKING.

NO6 FUSE CHANGED + TESTED.

25057. B.H. SETTLING TANK GAUGE LEAKING. NEW GAUGE FITTED + TESTED.

B. A. ROBERTS, B. PRITCHARD, P. COX.

CARS FUELLED ETC: 50792 57183 50932

50515 50754 56344 57569

59185

50463

LOCOS FUELLED ETC: 47110 47564

51202 CALLED TO STATION NO AIR + AXLE LIGHT
NEW BULB FITTED

47438 CALLED TO STATION OIL PRESSURE FAULT LIGHT
BRIGHT. OIL CHECKED + RELAY RESET.

56344 FLAT BATTERS PUT ON CHARGE CIRC TESTED

47110 NO1 BOGIE NO1 TIM WHEEL BRAKE SLACK ADJUSTER
SEIZED. REMOVED + REPAIRED - REPLACED.

50515 NO1 ENG EXHAUSTOR BELTS MISSING NEW BELTS
FITTED.

THUR 18-3-82

CHAFOULKES D. TRIGGS P. Cox.

P/ena	MILES
50515	-
50463	-
51183	6130
50792	-
50759	-
50932	2760
51569	-
51188	79680
50938	5290
50398	45410
51179	29400

R/T 68205 Rmpt.
" 64200 Full

FUEL IN TANKS NO1 1,700 NO2 3000 TOTAL 4,700

CARS FUEL OIL WATER ETC.

51183-50792-50932-51188-50938-50398 51179 50515
56344 50759 51569 56348 56411 56164 56358 59153
50463

Locos Fuel lbs 47564 - 40197

40197 "A Exam" Brake Blocks to Change.

COACHING STEEL

NDV S2 SL SN SL S7 CW BSL
50515-25375-25259-25256-25884-25415-16114-35062

47403:- Called out to station driver reported noise from engine room found to be from Elec Pan when Pan starts up. Also Blower Motor Relay found tripped reset.

D.F. HILL. B.A. ROBERTS. R.E. PRITCHARD P. COX.

CARS FUELED ETC:

50927.	50470	51199
56214.	59180	56353.
	50524	

LOCOS FUELED ETC: 47267 40004. 25057.
47191. 47110.

50759. CARRIED TO LHANDUANO ENDS CUTTING OUT RAILS
TOPPED UP TESTED. ALSO VAC EXHAUST POTS
FINNED.

40055. FISHED IN STATION. ENG SHUT DOWN, SHORT OF
COOLANT. BROUGHT ON SITE TOPPED UP & TESTED

51197 CARRIED TO LHANDUANO. BOTH HEATERS NOT
WORKING (2) NEW GLOW PLUGS FITTED.

51188 CARRIED TO STATION. NO TRAIN NIGHTS NO 4
FUSE BROWN RENEWED & TESTED.

40197 BOMME BROCKUS RENEWED

25057 BOTH BOGIE SANDERS MADE TO WORK.

50524 NO 1 ENG EXHAUSTER BELTS MISSING
NEW BELTS FITTED.

47191 BLOWER NOT WORKING ELECTRO LEADS BURNT
REPAIRED & ELECTROS REMOVED - CLEANED

40197 BAD RUB OIL WEAR ON CRANK CASE COVER
(A. BANK NO 1 CYL) COVER REMOVED & NEW
FOUNT CUT & FITTED.

FRI 19 - 3 - 82

CATFOULKES D. TRIGGS P. COX.

P/Car	Miles
51199	13120
50524	-
50470	-
51569	-
50932	3060
50938	5290
50927	75360
51188	79830
51179	29660

R/T 68205 m/T
 64200 Full

FUEL IN TANKS No 1 400 No 2 2,400 TOTAL 2,800

CARS RUL ON WATER LIT.

50524
 51199-51569-50938-50927-51188-51179 59180
 56353 50932 56411 56214 56348 56358 50470

Locos 47191 - 25253 ^{4m} 47110 40138

COACHING STOCK

NDU SU SE OL SL BK
 40823-24043-24881-16066-24434-35048

50470 RHT BATT UNABLE TO START ENGINES PUT ON CHARGE.
 50524 ATTENTION TO HEADS 2 WAYS TO WORK.

D. Hill. B. PRITCHARD.

CARS FUELLED ETC:-

50628.

56503.

LOCO'S FUELLED ETC:-

47083.

40184.

40138.

25057.

40004 47110.

47535. CALLED TO STATION. WIND SCREEN WIPER NO 1 AND
DRIVERS SIDE UNCOUPLED. REPLACED & ADJUSTED.

50628. NO 2 WAG MANIFOLD JOINTS BLOWN OUT NEW
JOINTS FITTED & TESTED

40004. DR REPORTED SAND PIPES & STAY DAMAGED NO 1 AND L.H.
SIDE ALSO FOUND AIR PIPES BROKEN. REMOVED REPAIRED.
SAND TRAPS. ROCKETED OUT & TESTED.

RAIL TANK. 64200. UNLOADED TOP'S INFORMED.

B. A. ROBERTS. B. PRITCHARD. P. COX.

CARS FUELLED ETC:-

50792

57183

51564

50754

56344

50932

LOCOS FUELLED ETC:- 40055. 40197.

57188 CALLED TO WHANDUDDNO NO 1 ENG EXHAUST PIPE
UNCOUPLED (3) NEW NUTS & BOLTS FITTED

50759 FLAT BATTERS PUT ON CHARGE CIRC TESTED

40055 SETTLING TANK GAUGE GLASS BROKEN. NEW
GAUGE GLASS FITTED

SAT 20-3-82

CHAFOULLES D. TRIGGS P. CAR

P/CAR	MILES
50628	65460
51183	6820
50792	-
50759	-
51585	101860
51581	-
50565	-
50577	-
51199	13120
51569	-
50932	3360
51182	N/P
51189	U/R
51184	105400

RUB IN TRAINERS No1 No2 TOTAL

CARS FUEL OIL WATER BR

51585

50628 - 51183 - 50792 - 51199 - 51569 - 51182 - 51189 - 51184 - 59581
 56503 56344 50759 56353 50932 56341 56343 56342 51581

56565
 59210
 50577

LOOS 1 1 3
 40138 - 25057 - 47110

56503 ATTENTION TO DEARBORN AIR TYPE HEATER BUENOR
 HEAD CLEANED BLEEDING VALVE SYSTEM HEATER MADE TO
 WORK.

56341 ATTENTION TO HEATER CUL TRACING VALVE NO 6 FUSE
 BLOWN DUE TO FAULTY GLOW PLUG HOW FUSE AND PLUG FITTED HEATER
 MADE TO WORK.

D. HILL. B. PRITCHARD
CAR'S FUELLED ETC:-

51193. 50932.
56502. 51569.

Loco's FUELLED ETC:-
40093. 40197 40138.

47515. CALL TO STATION. E.T.H NOT WORKING E.T.H.
MARTH FAULT RELAY TRIPPED RESET & TESTED.

50932. CALL TO STATION. DRIVER REPORTED VALUUM SLOW
CREATING. EXAM + FOUND. EXHAUSTOR BOLTS OFF PULLEY.
NO1 ENG & ALL BOLTS OFF CAR 51569. ~~CAR~~ CAR
TAKEN OUT OF SERVICE. BROUGHT ON SITE. EXHAUSTOR
& ALTERNATOR BOLTS REPLACED & ADJUSTED NO1 ENG 50932.
ALL BOLTS REPLACED. NO1 ENG 51569 & NEW BOLTS
FITTED EXHAUSTOR & ALTERNATOR. NO2 ENGINES ADJUSTED
& TESTED.

56353. CALL TO Llandudno. DRIVER REPORTED NO POWER
FROM T/CAR ENG. EXAM + FOUND NO6 FUSE
BLOWN. NEW FUSE FITTED & TESTED

51193. DRIVER REPORTED BAD AIR LEAK FROM U.P.
VALVE BOX EXAM + FOUND "FORWARD" U.P. VALVE
LEAKING VALVE REMOVED STRIPPED CLEANED
REPLACED & TESTED.

56502. PLAT BATT'S PUT ON CHARGED CIRCIT CHECKED
ETC:-.

40093. FLEX HOSE PIPE LEAKING ON "B" BANK. TUBO CHAMBER
NOW PIPE FITTED COOLANT TOPPED UP & TESTED

56152. CALL TO STATION L.H. INHATOR BLOW
PLUG CHANGED & TESTED