

TUE 22 - 3 - 83

CHAPMAN B. PRITCHARD

	P/ONS	MILES
	51203	32040
	50970	N/P
	50208	57590
	51919	U/R
	50535	000600
	52046	90460
	50939	118410
	51562	U/R
	50931	265060

65718 full.

FUEL IN TANKS NO1 6,600 NO2 2,100 TOTAL 8,700

CARS FUEL OIL WATER CHECKS ETC

51203 - 51919 - 50535 - 50970 - 50208
 56339 56334 56176 56264 56060

50939 - 50931
 52046 51562

5 YARD 3

WAGONS 40192 - 25178

- 50970 - DRIVER UNABLE TO START RAILWAGON DUE TO RAT BAIT (GOOD LIGENTS) PUT ON CHARGE
- 56176 - RAT BAIT PUT ON CHARGE AND HEATER MADE TO WORK
- 52046 - ATTENTION AND REPAIRS TO WINDSCREEN WIPER MADE UP FROM OLD PARTS AND MOTOR MADE TO WORK
- 56334 - ATTENTION TO HEATERS MADE TO WORK.
- 50535 - ATTENTION TO HEATERS 2 MADE TO WORK GLOW PLUGS CHANGED
- 51203 - ATTENTION AND REPAIRS TO TRAIN LIGHTING GIVE NOT FUSE BLOWN CABLE REPAIRED ALSO 2 HEATERS MADE TO WORK LEFT HAND HEATER FAULTY FUEL SWITCHER NEW HEATER WANTED BUT HEATER GOT TO WORK

B. A. ROBERTS. P. COX. M. PRICE.

CARS FUELLED ETC. 57947 57198

52062 56337

SIC

F11

F11

LOCOS FUELLED ETC. 25284 40141 08023

40185 F11

51203 CALLED TO LLANDUDNO NO. 1 ENG WONT START
STARTER MOTOR STUCK. RELEASED & TESTED

25284 LOSS OF POWER. NO FIELD DIVERSION. FAULT
TRACED TO NOOSE CONNECTION ON F.D.R. COIL
CLEANED & SECURED. ALSO POOR BRAKE ON
WOCO. ALL SNACK ADJUSTERS ADJUSTED &
BRAKES TESTED.

40141 NO. 1 BOGE W.H. LD SAND PIPE RENEWED.

51947 PANEL LIGHTS. NOT WORKING FAULT TRACED
TO NOOSE LOOP WIRE ON BULB HOLDER
REPAIRED & 2 NEW BULBS FITTED.

56176 CALLED TO STATION HAND BRAKE BUZZER STUCK
RELEASED & TESTED.

47439 CALLED TO STATION SERVICER ALL LOW. TANK
TOPPED UP & TESTED.

56337 PHAT BATTERIES PUT ON CHARGE. CIRC TESTED
NO. 3 DYNAMO FIELD FUSE BLOWN. ALL
BATTERY CELLS TOPPED UP.

WED 23-3-83

Choules B. Pritchard

JUST TO NOTE
VERY BAD EXHAUST FUMES IN SHED
 FROM HEATERS AND REQUIRES VERY BAD
 BURNING OF EYES FROM FUMES.

P/442	MILES
51947	30030
52062	U/R
51198	170950
50463	N/F
51201	26310
52046	90780
50939	118720
51182	N/F

FUEL IN TANKS No 1 6,600 No 2 800 TOTAL 7,400

MAKS FUEL OIL WATER CHECK ETC

51947 - 51198 - 51182 - 50939
 52062 56337 56341 - 52046

51201 - 50463
 56347 56453

(F)

Loco's : 25284

51947: ATTENTION TO HEATER GLOW PLUGS OR WOULD NOT FIRE UP MADE TO WORK.

50463: - CAME OUT TO LINDSAY STATION DOWN REPAIRED NO POWER
 REPAIR RUNNING FOUND NO 4 NO 6 AND NO 7 FUSES IN BLOWN ALSO UNIT
 RUI BATT RISKS REPAIRED WORKED ON TO START PUT ON CHARGE.

51947: RUI BATT PUT ON CHARGE.

51182: ATTENTION AND REPAIRS TO AIR LIGHTS CUR ALSO HEATERS 2 UNDER WOOD

56347: ATTENTION TO 2 HEATERS GLOW PLUGS CHANGED HEATERS UNDER TO WORK.

56341: ATTENTION TO BUZZER CUR MADE TO WORK SCREENS WIREWEG ON BUZZER
 UNIT REPAIRED WITH OLD PARTS.

52062: ATTENTION TO HEATER GLOW PLUG OR WOULD NOT FIRE UP MADE TO WORK.

B.A. ROBERTS. P. COX. M. PRICE.

CARS FUELLED ETC: 57197
57361

LOCOS FUELLED ETC: 40052 F11 40185 SK 25090 F11
25303 S/C 47157 S/C

57197. CALLED TO STATION NO 2 ENG CUTTING OUT
WHEN THROTTLE SHUT OFF, FUEL PUMP RACK
STOP SCREW SNAPPED OFF. READJUSTED
& TESTED.

47538. CALLED TO BANGOR. E.T.H NOT WORKING
THEYR TRIPPED. RESET & TESTED.

57197 NO VIBING EXHAUSTER & ALTERNATOR BELTS
MISSING. NEW BELTS FITTED.

25090 SANDERS NOT WORKING (BOTH BOGIES)
MADE WORKABLE. SANDBOXES FILLED.

25303 R.H. SIDE SETTLING TANK GAUGE GRASS
BROKEN. NEW GAUGE FITTED.

THUR 24-3-83

CHARLES B. PRITCHARD

P/Car	MILES
51197	19670
51198	171200
50203	138320
51186	71760
51203	32510
52046	91090
50939	119030
R/T. 65718 Full	
FUEL IN TANKS No 1 5,100	No 2 800
TOTAL 5,900	

CHAS FUEL OIL WATER GREASE ETC

51198 - 51197 - 51203 - 50203 - 51186 - 52046
 56337 56361 56339 56080 56357 50939

(B) (S) (S)
 Loco's 40192 - 25284 - 25090

- 50939: Driver reported brake failure front HOT WORKING - fire repaired also
 DOWNER BECAUSE VALVE STICK TO WORK VALVE CLEANED.
- 50203: DRIVER REPORTED LOSS OF CONTROL AIR FOUND B P VALVE STICKING
 VALVE CLEANED. PIRI ON VALVE SMOOTH
- 56361: FLAT BATT PUT ON CHARGE TO START UP HEATERS ETC.
- 25284: - CAME TO HOLO DRIVER REPORTED UNABLE TO START BECAUSE
 FOUND S2 WATER CONTAMINATION STUCK IN COMBATONS RESET HOLO P.W.M.P.
 REPAIR IN HOUSE MADE SUCCESS.
- 51198 ATTENTION TO 2 HEATERS 2 MADE TO WORK.

D. Hill. P. Cox.

CARS FUELLED ETC:-

51179

56358

Locos Fuelled ETC:-

25303 (F)

25060 (S)

47354 (3)

50208 CALL TO STATION. DR REPORTED WINDSCREEN WIPER UNCOUPLED WIPER ARM REPLACED ADJUSTED & TESTED REPAIRS CARRIED OUT @ LLANDUDNO.

25060. DR REPORTED WINDSCREEN WIPER NO 2 END 2ND MAN'S SIDE NOT WORKING REPAIRED & TESTED.

51179. DR REPORTED TWO TONE HORN NOT WORKING ADJUSTED.

56358. FLAT BATT'S CHARGED ETC. - ALSO HORNERS MADE TO WORK.

56341 CALL TO STATION. DR REPORTED NO AIR & AXLE LIGHT. IN "FOR" ON "REV" FOUND BULB BLOWN. NOW BULBS FITTED & TESTED.

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC. 50980 51197
56256 56361

LOCOS FUELLED ETC. 40192 SIC

47407 CALLED TO STATION DR REPORTED HORN NOT WORKING NO 2 END. EXAMINED FOUND TO BE ISOLATED. DEISOLATED & TESTED

52062 CALLED TO LLANDUDNO HEATER NOT WORKING NEW GLOW PLUG FITTED & TESTED

50980 NO 1 END EXHAUSTER & ALTERNATOR BELTS MISSING NEW BELTS FITTED

56256 FLAT BATTERIES PUT ON CHARGE CIRC TESTED. AMB BATTERY CELLS TOPPED UP.

Roll 25-3-83

CARBOURERS B. BRITANNIA

P/Unit	Miles
51179	N/P
51198	171469
51203	32750
51197	19890
50980	63590
52046	91410
50939	119340

R/T 65718 Full

FUEL IN TANKS NO1 3,900 NO2 800 TOTAL 4,700

CHRS FUEL OIL WATER RTR.

51197 - 50980 - 52046 - 51179 - 51198 - 51203

56361 56256 50939 56358 56337 56339

(Water) 'A'
Locos 25060 - 25284 - 40192

40192: A EXAM COMPLETED AT 9,300 MILES 20 GALLONS SUMP OIL PUT IN ENGINE SUMP. BRASS BLOCKS PART WORN.

25060: OUT OF COURSE ATTENTION HEADER TANK LOW BROUGHT ON SHED HEADER TANK FILLED.

D. Hill. P. Cox.
 PUFFI CAR'S PULLED ETC.
 51196
 56336
 25300
 40177 (S) 25300 (F) 40129 (S)
 Loco's PULLED ETC.-

- 51196. FLAT BATT'S CHARGED WAG'S TESTED.
- 56336 HEATERS MADE TO WORK.
- 25300 SANDS MADE TO WORK. ALSO R. H. NO 1 AND SAND PIPE DAMAGED, REMOVED REPAIRED REPLACED
- 40080 CALL TO STATION. DR REPORTED WINDSCREEN WIPER ARM UNCOUPLED REPAIRED REPLACED ADJUSTED & TESTED
- 56361 CALL TO STATION. L.H. HEATER MADE TO WORK CROW PLUG EXCHANGED.

REPAIRS. H. PRICE.

CARS FURNISHED ETC. 53228 50930
 54055 57563

Locos FURNISHED ETC. 47440 F11

Stock EXAMINATION ~~4983~~ 4983 4921 35485
 16160 25991 25876 25841 25791 25981
 13342 35306

4454 CAMPED TO STATION E.T.H NOT WORKING, FOUND RESERVOIR BURNT OUT, E.T.H ISOLATED

47440 NO 1 & 2 JOINTS ON EXHAUST MANIFOLD BLOWING NEW JOINTS FITTED

25981 DYNAMO BELT MISSING NEW BELT CUT & FITTED.

54055 FLAT BATTERIES PUT ON CHARGE WIRE TESTED ALSO HEATERS REMAINED.

SAT 26-3-83

CAROLINE B. PRITCHARD

	P/CAR	MILES
	51186	72250
	51569	48860
	53932	48910
	50939	119650
	52046	91720
	51181	408280
	51179	24150
	51563	51790
	50930	N/P
	53228	930

FUEL IN TANKS NO1 3000 NO2 800 TOTAL 3800

CALL FUEL OIL WATER CRACK.

51186 - 51569 - 50939 - 51563 - 53228

54357 - 53932 - 52046 - 50930 - 54055

50939 - 51181 - 51179

52046 - 56346 - 56358

(S)

LOCOS 40192 -

51569: - UNABLE TO START ENGINES DUE TO FUEL BUT PUT ON
CHANGE FUEL FOUND BLEND REQUIRED

53932: - ATTENTION TO HORIZONTAL MADE TO WORK.

56358: - ATTENTION TO 2 HORIZONTALS MADE TO WORK.

50930: - CAME TO UNIT DOWNS REPAIRED VACUUM LEAKING OFF UNITS COVERED UP
FROM VACUUM PIPE WASHER MISSING. REPAIRED BETWEEN UNITS

B. A. ROBERTS. M. PRICE.

50716
CARS FUELLED ETC: 57193 57196 59275
54502 56336 50675.

WAGONS FUELLED ETC: 40177 F11 25284 S/C 25300 S/C
25123 F11 47357 F11 47076 S/C 40192 F11 25083 F11

53228 CANNED TO STATION DR REPORTED UNABLE
TO CREATE VACUUM (15") VAC PIPE WASHER
MINUS. NEW WASHER FITTED.

51569 CANNED TO STATION DR REPORTED BAD AIR
WEAK ON UNIT. EXAMINED FOUND MAIN AIR
COCK OPEN ON RESERVOIR.

57196 FLAT BATTERIES PUT ON CHARGE CIRCUIT TESTED
NO 9 BATTERY FUSE RENEWED.

25876 MW1 NO THROUGH CONTROL LIGHTING, FAULT
TRACED TO BURNT CONTACTS ON LIGHTING
SWITCH ALSO NO 6 FUSE BLOWN.

25123 BRAKE BLOCKS RENEWED BOTH BOGIES

25300 COOLANT HOSE PIPE TO PRESSURE CHARGER
BURST. NEW PIPE FITTED.

47381 REMAINS TO DR SEAT MOUNTING SCREWS
NEW SCREWS FITTED & REMAINS TO FLOOR.

SUN 27-3-83

Chafoukes

P/CHG	MILES
50980	64130
53648	122620
53706	101840
50675	52390
50716	53220
53228	1240
50930	N/A
51563	52090

CARS OIL WATER CHECK ETC.

51569 50980 53648 50675 - 53228 - 50930
 53932 56256 59569 59275 54055 51563
 53706 50716

(P) (P) boiler P (S) (P)
 loco's - 47453 - 47407 - 47351 - 25300 - 25123

47407! - Downer Reported engine speeds up when RTH system is coupled up to stock and switched on testing loco for fault. No fault found loco not fitted with hydrostatic system. Temp controlled with motor fan's for cooling.

59275! - Heat bath put on chimney

50980! - Reported loss of air pressure receiving railhead from Kewstle air line valve leaking off valve repaired engines run-up starting

Monday, 28th March 83.

		P/CAR NO	MILEAGE.
		51947	30980
		52062	78540
		51198	172280
		51569	49210
		53932	49260

R/T 65718 m/t.

Fuel in Tanks. No 1 5,500 No 2 4,000 TOTAL 9,500.

D. Hill M. Price.

CAR'S FUELLED ETC:-

51947.	51198.	51569.	50980.
52062.	56337.	53932.	56256.
53648.	50675.		
54569.	59275.		
53706.	50716.		

LOCOMOTIVES FUELLED ETC:-

47351 (S) ~~25284 (F)~~ 25284 (F) 40177 (S)
47381 (S)

25083. "A" EXAM CARRIED OUT. BOLDS FITTED.

51947. NO 2 AVG. BAN BOLTS MISSING NOW BOLTS FITTED RAD TOPPED UP & TESTED

56337. MOTORS MADE TO WORK.

56256.

50716. DR REPORTED UNABLE TO START NO 1 AVG EXAM + FOUND. NOW RELAY SWITCH CLEANED RESET. + TESTED, AVG RUN UP.

B. A. ROBERTS. B. PRITCHARD. P. COX.

CARS FUELLED ETC: 57119 57182
56334 54341

LOCOS FUELLED ETC: 47351 S/K 25300 F/1 25723 S/K
40141 S/K 40192 F/1 08023 F/1

56336 CARRIED TO W. LANDUDNO GUARD REPORTED TRAIN
NIGHTS WILL NOT STAY ON. ON & OFF RELAYS STICKING
ADJUSTED & CLEANED & TESTED.

53932 CARRIED TO STATION HEATER NOT WORKING. 25AMP
FUSE BROWN IN PANEL. NEW FUSE & GLOW PLUG FITTED

25300 SANDERS NOT WORKING. MADE TO WORK & N°1 BOGIE
W. H. SAND PIPE RENEWED.

57182 NEW GENCO BUZZER FITTED IN G/VAN.

54341 FLAT BATTERS PUT ON CHARGE CIRCUIT TESTED
DYNAMO BELLS ADJUSTED & HEATERS REPAIRED.

TUESDAY. 29TH MARCH 83.

	P/CAR NO	MILEAGE
	50716.	53470.
	50675	52640.
	51188.	135730.
	50980.	—
	51919.	62710.
	51947	31270.
	52062	78510.
	51182	N/F.
R/T 65718 m/T		

Fuel in Tanks No 1 5,500 No 2 2,800 TOTAL 8,300

C/H. D. Hill M. Pries.

CAR'S FUELLED ETC:-

51188. 50980. 51919. 51947. 51182.
54348. 56256. 56334. 52062. 54341.

50716/59275/50675

Loco's FUELLED ETC:-

40192 (S). 25123 (R). 25083 (R)

47534. CALL TO STATION. DR REPORTED LOCO LOW IN FUEL EXAM 100 GALLS ON GAUGE LOCO. BROUGHT ON SHED 250 GALLS PUT IN TANK LOCO WORKED TO M/EXHAUSTOR 20 MINS DELAY

51198. CALL TO STATION DR REPORTED L.H. HOATRE NOT WORKING. Glow Plug changed & TESTED.

51188. NO 2 LWB EXHAUSTOR & ALTERNATOR BELTS MISSING NEW BELTS FITTED & ADJUSTED.

51919. PLAT BATT'S. CHARGED ETC:-

51947. NO 1 LWB FUEL SYSTEM AIR LOCKED BUSH & TESTED

59275. PLAT BATT'S CHARGED NO 3 FUEL PUMP CHANGED ETC:-

50675. EXHAUST FLOW PIPE NO 2 LWB CHANGED.

54341. FUEL LIGHTS NO 2 & NO 3 CAR'S MISSING NOW

54341 cont:-

BULBS FITTED. ALSO AIR + AXLE LIGHT NO 3 CAR DEFECTIVE
PANEL REMOVED FOUND WIRE TO LAMP HOLDER BROKEN
REMADE + TESTED

40192. HORN STUCK NO 2 END. FOUND VALVE 2ND MAINS.
SIDE STUCK REMOVED STRIPPED CLEANED REPLACED
+ TESTED

B. A. ROBERTS. B. PRITCHARD P. COX.

CARS FUELLED ETC: 53208
54060

LOCOS FUELLED ETC: 40158 SIC 40044 SIC 25284 SIC
40177 FII

51182 CALLED TO WANDERING HANDBRAKE BUZZER STUCK.
SWITCH RESET + TESTED

47444 CALLED TO BANGOR DR REPORTED SERK TANK VERY
LOW IN OIL. TOPPED UP 3 GALS + TESTED.

53208 NO 1 ENG EXHAUST MANIFOLD JOINTS RENEWED

40044 AIR PIPE TO SNACK ADJUSTER BROKE OFF NO 1 BOILER
3 TIM W.H. SIDE. PIPE REMOVED REPAIRED + NEW
CONNECTION FITTED TO ADJUSTER.

25284 DR REPORTED LOCO LOW IN POWER. FUEL SYSTEM
EXAMINED. NEW FILTERS FITTED + CLEANED, ALSO
W/OAD REG + INTERLOCKS ON FIELD DIVENTS CLEANED
W/OCD RUN UP + TESTED.

54060 D.S.D NOT WORKING FAULT TRACED TO DIRTY CONTACTS
ON THROTTLE CONTROLLER. CLEANED + REPAIRED
TESTED.

WED 30TH MARCH 83

	P/CAR NO	MILEAGE
	51947.	31580.
	52062.	78510.
	51182.	N/F.
	50463	—
	53939	130400.
	52046	92480.
R/T. 65718 M/T	53208.	59160.
" 65809 Full.	53228	1730.
	50675.	52890
	50716	53720.

PULL INTAKES NO.1 5,500 NO.2 1,400 TOTAL 6,900.

D. HILL M. PRICE.

CAR'S PULLED ETC:-

- 51947. 51182. 50463. 53939. 53208.
- 52062. 54341. 56453. 52046. 54060.
- 53228/54055. 50675/59275/50716.

LOCO'S PULLED ETC:-

- 25284 (F) 25123 (S) 40044 (F)

47212. "A" EXAM CARRIED OUT.

~~56387~~ 56387 CAR TO STATION. DR REPORTED HORN NOT WORKING ADJUSTED & TESTED.

50463 NR1 LONG EXHAUSTOR BOLTS MISSING NOW BOLTS FITTED & ADJUSTED.

56453 PLAT BATT'S CHARGED ETC:- L.H. GLOW PLUG CHANGED

52062. AIR & AXLE & LONG LIGHT BULBS CHANGED ETC:-

53939. NR1 LONG EXHAUSTOR & ALTERNATOR BOLTS OFF PULLEY ALL REPLACED & ADJUSTED

59275 R.H. HORN MADE TO WORK.

50716 BOTH HORN MADE TO WORK.

~~56387~~ ~~221~~

B. A. ROBERTS. B. PRITCHARD. P. COX

CARS FUELLED ETC: 50931
51562

KOCOS FUELLED ETC: 40024 FI 40177 SK

51947 CALLED TO WANDUING ROAD WATER LEAK ON
Nº1 ENG WATER JACKET HOSE PIPE BURST ENG
& F/DRIVE ISOLATED.

40024 SANDERS MADE TO WORK.

50931 Nº1 ENG EXHAUSTER & ALTERNATOR BELTS HISSING
NEW BELTS FITTED.

54341 CALLED TO STATION HEATER NOT WORKING Nº6
FUSE BLOWN NEW FUSE FITTED

47456 CALLED TO STATION WINDER ARM UNCOUPLED
Nº2 END DR SIDE REFITTED & ADJUSTED

51919 CALLED TO STATION T/TONE HORN NOT WORKING
BOTH TRUMPETS ADJUSTED.

THURSDAY 31ST MARCH 83

P/CAR NO.	MILEAGE
50535.	—
53228.	1930.
51562	u/r.
50931	66900.
51198	172860
51186	73310
51203.	33970.
51947	31740.
52062.	n/w.

R/T 65809 FULL

Power in Trains No 1 5,300 No 2 700. TOTAL 6,000

S. HILL P. COX. M. PRICE

CAR'S FUELLED ETC:-

- 50535. 53228. 51562. 51198. 51186
- 56176. 54055. 50931. 54337. 54357.
- 51203. 51947.
- 54339 52062.

Loco's FUELLED ETC:-

25284 25123.

50535. DR REPORTED NO 1 ENG & R/D/R ISOLATED. PAN BELTS MISSING. EXAM & FOUND PAN MOTOR HOLDING DOWN STUDS BROKEN. (2) MOTOR REPAIRS STUDS DRILLED OUT NEW STUDS MADE & FITTED. NOW BELTS FITTED ENG & R/D/R DEISOLATED & TESTED.

51186. DR REPORTED ONLY ONE TONN FROM HORN ADJUSTED & TESTED.

54357. PLAT BATT'S CHARGED ETC:-

47565. CALL TO STATION. DR REPORTED BLUE FAULT LIGHT BRIGHT. FOUND EARTH FAULT. EARTH FAULT RELAY. RESET & TESTED

56256. CALL TO LLANDUDNO. DR REPORTED. WINDSCREEN.
WIPER ARM UNCOUPLED. REPLACED & ADJUSTED.
51203. NO. 1 WDG EXHAUST MANIFOLD JOINTS
BLOWING. NEW JOINT FITTED & TESTED.
54339. PLAT BATT'S PUT ON CHARGE ETC.

THUR 31-3-83

CHARLES B. PRITCHARD.

51182 CAME OUT TO STATION DRIVER REPORTED HEADERS HOT
54341 WORKING ON POWER CAR AND T/CAR ALSO BARR SYSTEM
TO CHECK 2 HEADERS MADE TO WORK AT LLANDUDNO STATION
UNIT TAKEN OUT OF SERVICE OUT OF COURSE ATTENTION
TO LEAK ON TRAM PIPE SIDE BROKEN VACUUM PIPE CLIP OFF
T/CAR AND ALSO ATTENTION TO HEADERS T/CAR ONLY ABLE
TO GET LEFT HAND SIDE TO WORK RIGHT HAND SIDE SUSPECT
FAULTY HEADER UNIT OR RELAY CONTROL SYSTEM.

CARS FUEL OIL WATER CHECK ETC. 51917
54496

51917 ATTENTION TO TRAM LIGHTING ARC TRIPPING FOR POWER
FOUND ON BUITION STUCK IN ON SWITCH IN VAN. REPAIRED POWER

Loco's: 40052

RAIL TANKER N° 65809 UNLOADED TOPS INFORMED

B. A. ROBERTS . P. COX .

CARS TURNED ETC: 51182
54341

LOCOS TURNED ETC: 40044 S/C 40194 S/C 25209 A
25284 AEX.

25284 A. EXAMINATION CARRIED OUT - BRAKE
BLOCKS RENEWED.

25209. R.H. SETTLING TANK GAUGE GLASS
RENEWED.

40194. FAMED @ SANDYCROFT LOCO HAULED ON TO
SITED LOW IN COOLANT. COOLANT TOPPED
UP & SEVERAL HOSE PIPE CLIPS SECURED
UP.

47070 CARRIED TO RHYL. LOCO SHUT DOWN. EXAMINED.
FOUND PLAT BATTERIES HAULED TO SHED
FOR FURTHER ATTENTION.

FRIDAY, 1ST APRIL 83

	P/CAR NO	M/LOAD
	51563	53050
	58930	N/F
	51188	136390
	50535	—
	53228	—
	51198	173140
	50931	887210
	51562	U/R
	51917	3390
	51182	N/F
	51200	69340
R/T 65809 M/T.	53980	—

FUEL IN TANKS. NO.1 5,200 NO.2 7,000 TOTAL 12,200.

D. HILL M. PRICE:

CAR'S FUELLED ETC

51563. 51188. 50535. 53228. 51198.
53930. 54348. 56176. 54055. 54337.

50931 51917 51182. 51200. 53980.
51562. 54496. 54341 54359. 54256.

LOCO'S FUELLED ETC:

25209. (S) 25083 (S) 25123 (S).

51563. DR REPORTED FLAT BATTERS. CHARGED ETC. -
ALSO NO.2 LMG ALTERNATOR BELTS MISSING
NOW BELTS FITTED & ADJUSTED.

50931. ALTERNATOR NOT WORKING. NOW PLUG FITTED - TESTED
54389. FLAT BATTERS PUT ON CHARGE ETC.

BATT 1 - 4 - 83

Choules B. Pritchard.

CANS FUEL OIL WATER ETC.

51196 - 51193 - 51188 - 53940 - 53929
54336 54502 54348 54273 54269

51188 } ATTENTION TO 4 HOMER AN MADE TO WORK.
54348 }

47070:- loco BONES MADE RHYL. HAWLED ONTO
WANDWINDO TO BROUGHT ON TO PT COND FOR BATT
CHARGING BATT SYSTEM FIRST BATT TRACING FOR PAULT
AFTER RECHARGING AND TOPPING UP CELL'S ENGINE CURRENT
80 TO 100 AMP'S THEN AFTER 5 MIN TO 0 BUT BATT VOLTS ONLY
75 VOLTS TO UNDER 100 VOLTS. AUXILIARY CHARGE AT 250
WHEN TEST FOR POWER ENGINE SHUTS DOWN 75 VOLTS
TRACING FOR PAULT FOUND WIRES BURNT OFF (2) TO MAIN
GENERATOR SELF FID CONTACTS CLEANED AND REMAINS
WIRE BURNT OFF A.V.R. FROM BROWL AND A.V.R. READJUSTED
TO 110 VOLTS. LOCO CO RUN-UP AND TESTED FOR POWER. OIL
ON TEST ON STOPS ETC.

B. A. ROBERTS. P. COX.

CANS FURNISHED ETC: 51176 50535 52062
54358 56176 51947

47439 CAMEL TO STATION NO 2 END DR SIDE DROP LIGHT
WINDOW. NIM NOT STAY CLOSE. CATCHES REPAIRED

54273 CAMEL TO WANDWINDO NO 6 FUSE BLOWN, RENEWED

50535 NO 12 ENG EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED

54358 BATT BATTERIES PUT ON CHARGE CIRL TESTED
NO 9 FUSE RENEWED.

52062 FORWARD GEAR E.P. VALVE BLOWING THROUGH
VALVE REMOVED STALPES - CLEANED REPLACED

SAT. 2nd APRIL. 83.

P/CAR NO	MILEAGE
51193	1370.
51196.	68310.
52062.	N/W.
51947	232200.
51917.	3620.
51182	N/F
51188.	136460
51562.	U/R.
50931	697400
53929	50060.
53940	N/F

R/T. 65809 M/T.

FUEL IN TANKS NO 1 41700 NO 2 71000 TOTAL 11700.

D. HILL. M. PRICE.

CAR'S PULLED ETC:-

51193	51196	52062	51917	51182.
54502	54326.	51947.	54496.	54341.
51188.	51562.	53939.	53940.	
54348.	50931.	54269.	54273	

LOCO'S PULLED ETC:-

25209. (R) 25123 (F) 25284 (S)

53939. NO 2 LONG EXHAUSTOR & ACTORNATOR BOLTS OFF PULLEY. ALL BOLTS REPLACED & ADJUSTED.

54496. PLAT BATT'S CHARGED ETC:-

53940. BAD AIR LOCK FROM FORWARD R.P. VALVE REPAIRED.

51193 NO 1 LONG MANIFOLD JOINTS CHARGED ETC:-

54502. PLAT BATT'S CHARGED ETC:-

B. A. ROBERTS, P. COX.

CARS FUELLED ETC: 51920
54502

WOCOS FUELLED ETC: 40024 S/C 25324 S/C

47492 RANDED TO RAYL. WOCO FAILURE. TOTAL LOSS OF POWER. ENG SHUT DOWN. C.C.B1 & CCB2 D.B.R TRIPPED. WOCO ITAUKED TO SHED. RELAYS RESET WOCO RUN UP TESTED. NO OTHER FAULTS FOUND. WOCO RELEASE TO TRAFFIC.

51182 CARRIED TO STATION DR REPORTED BATTERIES POOR. UNIT TAKEN OUT OF SERVICE. STOPPED FOR C & W ATTENTION.

51196 NO 2 ENG FAN BELTS MISSING NEW BELTS FITTED.

56502 FLAT BATTERIES. PUT ON CHARGE. CIRL TESTED NO 9 BATTERY CHARGE TUNSE RENEWED.

51174 CARRIED TO WHANDUWNO BOTH ENGS CUTTING OUT PLATS TOPPED UP & TESTED

SUNDAY APRIL 3rd 83

	P/CAR	MILEAGES
	51918	58660
	51563	53460
	50930	N/F
	52062	N/W
	51947	732510
	51917	3930
	51198	173560
	51182	A/F
	51562	UR
	50931	797420
	53228	2610
	50535	—

FUEL IN TANKS NO 1 NO 2 TOTAL

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51918 51563 51947 51917
 54495 53930 52062 54496
 51198 51182 51562 50358 53228 50535 50473
 54337 54341 50931 56113 54055 56176 50525
 50453 50444
 50520 50560

WAGONS FUELLED ETC: 47203 F11 47341 F11 47196 SIC
 40024 F11

50520 NO LONG EXHAUSTER BELTS MISSING NEW BELTS
 FITTED

56113 FLAT BATTERIES PUT ON CHARGE CIRC TESTED
 ALL BATTERY CELLS TOPPED UP.

Monday. 4th APRIL. 83

P/CAR NO MILEAGE.

53208.	60110.
53203.	140480.
52065.	35310.
51950.	54880.
51920.	84600.
51198.	173600.

R/T. 65809 m/t.

FUEL IN TANKS NO 1 3,900 NO 2 7,000 TOTAL 10,900
D. HILL. P. COX.

CAR'S FUELLED ETC:-

51920.	51198.	51562.	50358.	53228.
56504.	54337.	50931.	56113.	54055.
50535.	53208.	53203.	52065.	
56176.	54060.	54080.	51950.	

Locos FUELLED ETC:-

25324 (R) 40024 (R) 25123 (S)

52065 PLAT BATT'S CHARGED ETC:- ALSO NO 2 UNDER-
ALTERNATOR - LEVITATORS BOLTS MISSING NEW BOLTS FITTED.
51198. PLEX AIR PIPS ON BUFFER BEAM DAMAGED. CHARGED
54060. HORNERS NOT WORKING NO 6 PIPES CHARGED & TESTED

B.A. ROBERTS . M. PRICE.

CARS FUELLED ETC: 50535 - 53228 - 51152
51152 51174 56276 54055 52065
54341 54337

LOCOS. FUELLED ETC: 28204 - 28225 - 47433

53332 CAME TO WANDUONO BOTH ENGS CUTTING
OUT PLADS TOPPED UP & SEVERAL HOSE PIPE
CHMS SCREWED UP.

54333 PLAT BATTIS PUT ON CHARGE CIRL TESTED +
HEATERS REPAIRED

* 47433 HUBS ON PIPE JOINT ON HUB AND FILTER
DRAIN PIPE WEARING BADLY NEW JOINT CUT
& FITTED SUMP OIL TOPPED UP.

MON 4 - 4 - 83

CAPOULES B. PRITCHARD.

CARS Fuel oil WATER ETC.

53208 - 51193 - 51917 - 50358 - 50931
54060 54503 54496 56113 51562

51917 CAME OUT TO STATION DRIVER REPORTED NO 2 ENGINE
KNOCKING OFF BOUND SHORT OF SUMP OIL SUMP TOPPED UP
AT STATION

51562 CAME OUT TO STATION DRIVER REPORTED HEATER NOT WORKING
UNABLE TO GET TO WORK AT STATION. AIR LOCK IN FUEL PIPE.

47670 UNABLE TO START loco DUE TO HEADER TANK EMPTY WERE
WATER RUNNING

TUESDAY. 5TH APRIL 83

	P/CAR NO	MILAGE
	50535	—
	53228	2750
	52065	35380
	51950	54940
	53938	26550
	51918	58260
	53208	60110
	51182	N/F
	51920	84740
	51917	4210
	50358	—
	50931	17670
	51562	u/r.

R/T 65809 m/t

PULL IN TANKS NO 1 2,900 NO 2 7,000 TOTAL 9,900

D. HILL

P. COX

	CAR'S	PULLS	ETC:-	
51182	51920	51917	50358	51918
54341	56504	54496	56113	54495
50535	53228	52065	53938	53208
56176	54055	51950	54411	54060

50931 / 51562

LOCO'S PULLS ETC:-

25324 (S) 40024 (S) 25123 (F)

- 51182 NO 2 ENGINE EXP. EXHAUST BOX FRACTURED IN W.O.A. NOW BOX FITTED & TESTED.
- 50358 FLAT BATT'S CHARGED ETC:-
- 53208 DR REPORTED PANEL LIGHTS FOR NO 3 & 4 ENGS. + F/DR NOT WORKING. NOW BULBS FITTED - TESTED.
- 54496 FLAT BATT'S CHARGED ETC:-
- 51182 L.H. TRAYTOR MADE TO WORK GLOW PLUG CHANGED.
- 53938 NO 2 ENG. MANIFOLD JOINTS CHANGED.

B. A. ROBERTS. M. PRICE.

CARS FUELED ETC. 50463
56453

LOCOS FUELED ETC.
47100 SIC 25164 SIC

47070 CARRIED TO NEW YARD. LOCO SHUT DOWN
EXAMINED FLAT BATTERIES. LOCO ISOLATED
TO BE HAWKED TO CREWE.

53208 CARRIED TO STATION. HEATERS NOT WORKING.
NEW GLOW PLUG FITTED. ALSO NO. 1 ENG EXHAUST PIPE
UNCOURNED 3 NEW NUTS & BOLTS FITTED

50463. NO. 2 ENG EXHAUSTER BELTS MISSING NEW BELTS
FITTED. ALSO AHS FOUND ISOLATED DEISOLATED
& RESET BUTTON REPAIRED.

TUE 5-4-83

CHAUUKES B. PRITCHARD.

CARS RUEL OIL WATER CHECK ETC.

51919 - 51190 - 50625 . 50950 - 51182
54334 54223 56213 52065 54341

(F)
Loco's 25209

25209 - DRIVER REPORTED LOSS OF LUB OIL OVER ENGINE ROOM ROOF AND
BLEW ALSO BLOW FROM EXHAUST SYSTEM TRACING FOR LEAK FOUND
NO. 2 CYLINDER HEAD COVER COVER HOLDING STUD BROKEN LUB OIL LEAKING
FROM UNDER COVER UNDER WARMING PRESSURE UNABLE TO REPLACE EXHAUST
STUDS AND BOLTS SCREWED UP LOCO TO WORK ONE TRIP TO NEWTON HEATH. RJS
RETURNED ATTENTION TO BROKEN COVER STUD.

51190 - AN ALTERNATOR AND EXHAUSTOR BOLTS FOUND OFF PULLEYS ALL REPIRTED
AND ADJUSTED ALSO REPAIRS TO BUSSOR WEL.

Wed 6th APRIL 83

	P/CAR NO	MILEAGE
	51920	84820.
	53938	36700
	51918	58400
	51202.	41010.
	51188	137140
	51919.	63780.
	51182	N/A
	51950	55260
	52065.	35680.
	50625	10140
65809. M/T.	51190	56050

FUEL IN TANKS NO 1 1,900 NO 2 7,000 TOTAL 8,900

P. HILL P. COX

CARS FUELLED ETC:-

51920. 53938 51918. 51202. 51188
56504. 54411 54495 54349. 54348

51190. 51919. 51182. 51950 50625.
54223. 54334. 54341. 52065. 56213.

Locos FUELLED ETC:-

40047. (S). 25123 (S). 25324 (F).

25324. WIND SCREEN WIPER NR2 and 2nd mans side
REPAIRED + TESTED.

51202. NO 1 ENG EXHAUSTOR + ALTERNATOR BOLTS OFF
PULLY ALL BOLTS REPLACED + ADJUSTED.

54349. FLAT BATT'S CHARGED ETC:-

51919. DR UNABLE TO START NO 1 ENG FUEL SYSTEM. AIR
LOCKED BLEED + TESTED.

B.A. ROBERTS. M. PRICE.

CARS FUELED ETC: 53980
54256

WOCOS 47081 S/C 40167 S/C 25324 A EXAM.

25324 A-EXAM CALLED OUT.

53208 CALLED TO STATION ONE ENG NIGHT BULB & AIR
AXLE LIGHT BULBS RENEWED.

57918. CALLED TO MANDUINO N°1 ENG ON FULL REVS
WITH NO IDLE. THROTTLE LEVER UNCOUPLED ON
FUEL PUMP. REFITTED & TESTED.

Wed 6 - 4 - 83

CARPOULERS B. PRITCHARD

CARS RUL ON WATER CREEK ETC.

53980 - 51174 - 51950 - 51182
54256 54333 52065 54341

(S)

(S)

WOCOS :- 25123 - 40047

47081 - CALLED OUT TO YARD DRIVER REPORTED SUSPECT FLATS
ON WHEELS CHECKED WHEELS IN YARD FLATS NOT BAD LEFT
LOW IN SERVICE.

54333 - ASSISTING COW ON BRAKE TEST DRIVER REPORTED BRAKES
DRAWING WHEN DRAWING FROM T/COR SET UP ON WAG. 20.
GAUGE TO 21" ON IRON PIPE FAULTY GAUGE IN CARS OUT 2 1/2" INK

52065 - FLAT BAIT PUT ON CHARGE.

THURSDAY. 7TH APRIL 83.

P/CAR NO MILEAGE.

53980	64840
51193	480.
50931	48040.
51562	u/R.
53208	60610.
51174	37430.
52065	35980.
51950	55560.
51182	n/f.

R/T ~~67057~~ 67057 FULL

FUEL IN TANKS NO 1 600 NO 2 7,000 TOTAL. 7,600.

D. HILL. P. COX.

CAR'S FUELED ETC:-

53980.	51193.	50931	53208.	51174.
54256.	54502.	51562.	54060	54333
52065.	51182.			
51950.	54341.			

LOCO'S FUELED ETC:-

40047. (F) 40164 (S) 25123 (F)

54502 HEATER NOT WORKING. DRAGON AIR FOUND. FUEL SYSTEM AIR LOCKED BLEED + TESTED.

51174. FLAT BATT'S PUT ON CHARGED ETC:-

50931. NO 2 LING EXHAUSTOR & ALTERNATOR BOLTS MISSING. NEW BOLTS FITTED & ADJUSTED. ALSO NO 2 LING ALTERNATOR BOLTS OFF PULLEY REPLACED

51562. DR REPORTED ONLY ONE TONE FROM HORN ADJUSTED.

40164. DR REPORTED. DROP LIGHT WINDOW. 2ND MAIN SIDE NO 1 LING WILL NOT SHUT. PANEL REMOVED FOR ACCESS. TO "X" SPRING FOUND UNCOUPLED. NOW PINS FITTED. + TESTED.

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51203 51919
54339 54334

LOCOS 40091 F11 47182 S1C 40143 F11

40091 BAD WATER LEAK. HOSE PIPE RENEWED B. BANK
FREE END TURBO PIPE.

47010 CALLED TO STATION PARKER NOT WORKING. STACK.
SWITCH TRIPPED RESET & TESTED.

54334 FNAT BATTERIES PUT ON CHARGE CIRCUIT TESTED
NO. 3 DYNAMO FIELD FUSE RENEWED

THUR 7 - 4 - 83

OUTROULES B PRITCHARD.

CARS FUEL OIL WATER CHECK ETC.

51203 - 53980 - 51182 - 51950 - 51196 - 51194

54339 54256 54341 52065 54336 54345

(S)

51918

LOCOS 25152

54495

51196! CALLED OUT TO STATION REPORTED UNABLE TO SWITCH
LIGHTS ON FROM VARIOUS CARS HO4 FUSE BLOWN CIRCUIT
REMOVED

51182! DRIVER REPORTED LOSS OF AIR PRESSURE TRACKING FOOT LEVER
FOUND VALVE PLUGGY BETWEEN UNITS SEAL REPLACED.

FRIDAY. 8TH APRIL 83.

	P/Car No	MILEAGE
	51203	35110.
	53980.	66090.
	51918.	58690.
	51182	N/A.
	51950.	55860
	52065	36270.
	51196.	69330.
	51194	151290
R/T. 67057 Pull.		

PULL IN TANKS NO 1 400 NO 2 6,300 TOTAL. 6,700.

D. HILL. P. COX
CAR'S PULLED ETC:-

- 51203. 53980. 51918. 51182. 51950
- 54339. 54256. 54495. 54341 52065.
- 51196. 51194.
- 54336. 54345.

LOCO'S PULLED ETC:-
40143. (S) 25152 (F) 47352 (F) 40047 (S)

- 25152 SANDERS MADE TO WORK.
- 54495. PLAT BATT'S CHARGED ETC:-
- 51196. L.H. HEATER MADE TO WORK.
- 54345. HEATERS NOT WORKING NO 6 PULL CHARGED & TESTED.

B.A. ROBERTS. M. PRICE.

CARS FURNISHED ETC: 53939
54296

LOCOS 47365 S/C 40063 F11

53735 } CALLED TO BANGOR DR REPORTED NO PANEL
53695 } NIGHTS FOR REAL UNIT ALSO ENGS CUTTING
OUT. JUMPER CABLE DISLODGED BETWEEN
UNITS. REPLACED & ALL RATS TORRETS UP.

983473. CATFISH WAGON DERAILED ALL WHEELS ON QUAY BAY
EXAMINED & HOLYHEAD BREAKDOWN. CALL OUT
COMING TO MORROW MORNING.

53939. NO 1 ENG EXHAUSTER BELTS MISSING NEW BELTS
FITTED ALSO ALTERNATOR BELTS FITTED.

FRI 8 - 4 - 83

CARBOURERS B. PRITCHARD

CARS FUEL OIL CHECK. ETC.

53929 - 51191 - 53628 - 51179 - 51194
54269 56340 54353 54358 54345

51182 - 51950
54341 52065

(S) $\frac{3}{7}$ (F) $\frac{1}{1}$ WATER
LOCOS 25215 - 25120

51191. POWER OPERATED GEAR SLIP BOXES TOGGLED UP SINCE POST
IN SLEED NO SLIP BOUND

52065: CALLED OUT TO STATION DRIVER REPORTED LOOSE CURVE
FOUND TO BE RUBBER WATER HOPE PIPE FROM TOILET. OUT LET.
UNDER BOGIE

SAT 9TH APRIL 83

P/CAR NO	MILMGS
51919.	64670.
51174.	37910.
53929.	50979.
51191	21280
53628.	16310.
51179.	26440
51194.	151540.
51182	N/A
51950	56150
52065	36560

PULLIN TURNS NO 1 NO 2 TOTAL

D. HILL P. COX.

CAR'S PULLED UTC:-

51919.	51174.	53929.	51191.	53628.
54334.	54333.	54269.	56340	54353.
51179.	51194	51182.	51950.	
54358.	54345.	54341.	52065.	

Loco's PULLED UTC:-

47352. (S) 25215 (F)

- 51194. NR1 WING EXHAUSTOR + ALTERNATOR BOLTS OFF PULLY ALL BOLTS REPAIRED + ADJUSTED.
- 50628. NR1 WING EXHAUSTOR + ALTERNATOR BOLTS MISSING. NEW BOLTS FITTED + ADJUSTED.
- 54358. PLAT BATT'S CHARGED UTC:-
- 51182. CALL TO STATION DR REPORTED. F/DRIVERS. DOGS NOT GOING OVER. AIR LIGHT NOT GOING OUT. EXAM + FOUND FLEX AIR PIPE TO NO 2 R/SB. HOLE. CAR TAKEN OUT OF SERVICE. NOW PIPE WANTED.

SAT 9-4-83

WALTERS B. PITCHMAN.

CARS FUEL ON WATER CREEK BTC.

51174 - 51920 - 50463

54333 56504 56453

54333 - T/CAR TAKEN OUT OF SERVICE DUE TO FURT BATT BROUGHT ON SHED PUT ON BATT CAREER

~~50463~~ } UNIT TAKEN OUT OF SERVICE DUE TO NO FERT IN TANK
~~56453~~ } UNIT BROUGHT ON PIT ROAD 3 OUT OF 4 HOLES MADE TO WORK UNIT BACK INTO SERVICE 1005

~~51920~~ } UNIT BROUGHT ON SHED REPORTED MEMBERS NOT WORKING
~~56504~~ } POWER AND T/CAR 2 MADE TO WORK UNIT BACK INTO SERVICE FOR 1211

51182 ATTENTION TO HO2 FINAL DRIVE FLEXIBLE AIR PIPE HOLE IN PIPE OLD PIPE TAKEN OFF NEW PIPE FITTED BROOM RUN UP TESTED FOR AIR PRESSURE, FOUND NO 1 END FINAL DRIVE PISTON SEALS LEAKING AIR PAST PISTON WHEN IN "REV" FROM POWER CAR WITH SOME LOSS OF AIR F.H.D. A

	S	F	S	F * S *
LOCS FUEL NO	47352	- 25215	- 25202	- 40009-25120
F x				
40047				

ALL ABOVE LOCS FUELED AND WATERED.

SUNDAY 10-4-83

	P/CAR	MILEAGES
	51185	34980
	53424	51166
	51920	85010
	57919	64680
	51950	56470
	52065	36870

FUEL IN TANKS N^o1

N^o2 TOTAL.

D. F. HILL P. COX.

CARS FUELLED ETC; 51950 51185. 53424
 52065. 54352 54264
 51920 57919
 56504 54334.

LOCOS 47482 SIC 40009 F11 25120 S/C 25215. (F)

51185 N^o2 ENG EXHAUSTER BELTS MISSING - ALTERNATOR BELTS
 NEW BELTS FITTED.

56334 FLAT BATTERS PUT ON CHARGE. CIRC TESTED N^o9 DYNAMO
 FUSE BLOWN NEW FUSE FITTED.

25120. L.H. SOTTILING TANK GAUGE BROKEN. CHANGED.
 ALSO DR REPORTED R.H. SAND PIPE DAMAGED.
 N^o2 WND REMOVED + REPAIRED.

MONDAY. 11TH APRIL 83.

P/CAR NO	MILEAGE.
51920.	85010.
51188.	137460.
50535	—
51190.	56990
51947.	134050
52062.	73540.
51174.	38020.
R/T. 67057. Full	

FUEL IN TANKS NO 1 400 NO 2 3,800 TOTAL 4,200.

S. HILL. R. E. PRITCHARD.

CARS PULLED ETC:-

51920 51188. 50535. 51190. 51947.
56504. 54348. 56176. 54223. 52062.

51174 / 56333.

LOCO'S PULLED ETC:-

25120 (F) 40047 (S) 40009 (S) 25215 (S).

25288. CALL TO STATION. DR REPORTED NO 4 T/MOTOR SMOKING SUSPECT FLASH OVER. LOCO TAKEN OUT OF SERVICE STOPPED. LOCO ISOLATED T/MOTORS. D.S.D. 2" COCK. TO BE HAULLED TO CROWS.

51947. DR REPORTED UNABLE TO START NO 2 AND FOUND FUEL SYSTEM AIR LOCKED BLEED & TESTED.

25208. CALL TO COLWYN BAY. DR REPORTED LOCO LOW IN POWER TAKEN OUT OF SERVICE. BROUGHT ON SHED ALL CONTACTS CLEANED RUN UP & TESTED. LOCO TO HAUL 25288 TO CROWS BOTH LOCO'S TO HAVE "B" EXAMS.

B.A. ROBERTS P. COX.

CARS FURNISHED ETC: 53203 51182 51919 53628
54060 54341 54334 54353

LOCOS 25202 F11 25237 S/C 25120 A-EXAM

47482 CAMEL TO STATION DR REPORTED YELLOW
FAULT LIGHT BRIGHT @ 65 MPH & OVER.
UNABLE TO FIND FAULT. SUSPECT WRAH COIL
ON W.S. LEAD.

47563 CAMEL TO STATION K.T.H NOT WORKING. RELAYS
RESET & LUBICLÉ. TESTED.

56453 CAMEL TO STATION BUZZER NOT WORKING IN
DRIVING CAB. ADJUSTED & TESTED.

54060 FNA7 BATTERIES & HEATERS NOT WORKING. PUT ON
CHARGE CIRC TESTED ALL BATTERY LEADS TOPPED
UP & 2 NEW GLOW PLUGS FITTED TO HEATERS

25237 DWAR BRAKE HANDLE BROKEN NO. 1 END CAB.
REMOVED & DUNKED OUT & RETAPED & NEW HANDLE
FITTED. ALSO SANDERS MADE TO WORK & BURNING
GRAB SET UP & ADJUSTERS SHAKED ADJUSTED ADJUSTED

40143 CAMEL TO STATION. ENG SHUT DOWN. SHORT OF
COOLANT. WOCO HAULMED TO SITE. HEADER
TANK FINNETS & TESTED.

Tuesday 12th APRIL 83.

	P/CAR NO	MILEAGE
	53203.	141800.
	51174.	38270.
	51947.	334330.
	52062	76510.
	51919	64890.
	53628.	16560.
	51917.	5540.
R/T	67057 FULL	
"	65732 FULL	

KUOLIN TANKS NO 1 400. NO 2 2,500 TOTAL 2,900

D. Hill R. G. PRITCHARD

54223 CALL TO STATION. DR REPORTED L.H. HEATER NOT WORKING NOW GLOW PLUG FITTED HEATER TESTED. ETC:-

CAR'S ROLLLED ETC:-

51947. 51919. 53628 53203.
52062. 54334. 54353. 54080.

51174/54333 51917/54496

Loco's ROLLLED ETC:-

25120 (S). 25202 (S) 25221 (F). 56067 (F).
25230 (S). B/F.

- 51919. DR REPORTED. NO 1 LNG WILL NOT START FOUND. FUEL SYSTEM AIR LOCKED. BLED & TESTED.
- 25230. SANDERS MADE TO WORK BOTH BOGIES.
- 25221. DR REPORTED. EXHAUST PIPES BLOWING BAD IN LNG ROOM. EXAM & FOUND. JOINTS ON PRESSURE CHARGER BLOWN OUT NEW JOINTS FITTED.
- 54353 PLAT BATT'S PUT ON CHARGE CIRCT CHECKED ETC:-
- 51917. NO 2 LNG MANIFOLD JOINTS BLOWING. NEW JOINTS FITTED
- 54496 PLAT BATT'S PUT ON CHARGE ETC:-

B.A. ROBERTS. P. COX.

CARS FUELLED ETC. 53929
54269

WAGONS FUELLED ETC. FI1 SIC FI1
47151 47218 25237

53929 NO 1 ENG EXHAUSTER & ALTERNATOR BELTS
MISSING, NEW BELTS FITTED.

45077 CAME TO BRANGOR BRAKE FEED PLEX
PIPE BURST NO 2 END. NEW PIPE FITTED

51190 CAME TO WHANDUINO DR UNABLE TO
START NO 1 ENG. STARTER MOTOR STUCK
IN FLYWHEEL. RELEASED & TESTED.

Wed 13th APRIL 83.

	P/CAR NO	MILEAGE.
	51947	334640.
	52062	76510.
	51200.	71550.
	53723.	61080.
	53674.	14890
	51194.	152170.
	53929.	51480.
	51188.	137940.
R/T 67057 m/t		
" 65732 Full		

FUEL IN TANKS. NO1 4,000. NO2 6,100. TOTAL 10,100.

D. HILL. R. W. PRITCHARD.

CAR'S PULLED ETC:-

51947 51200 51188. 51194 53929.
52062. 54359. 54348. 54345 54269.

53723/59064/53674.

LOCO'S PULLED ETC:-

47331. (S). 56067 (S). 25120 (F). 25154 (F).

25237. A EXAM CARRIED OUT.

54080. CALL TO STATION. E.H. HEATER MADE TO WORK.

47331. DR REPORTED HOEN STUCK NO1 AND. VALVE REMOVED
ALSO SORE TANK LOW TOPPED UP.

51200 HEATERS NOT WORKING NO4 + NO6 FUSES BLOWN NOW
FUSES ~~REMOVED~~ FITTED - TESTED.

54359. PLAT BATT'S PUT ON CHARGE ETC:-

51188. NO2 DNR & HEATER & ALTERNATOR BOLTS OFF RAILWAY.
ALL BOLTS REPLACED & ADJUSTED.

52062 HEATER NOT WORKING. EXAM & FOUND HEATER PANEL
DEFECTIVE. UNABLE TO REPAIR NOW PANEL WANTED.

53723. PLAT BATT'S PUT ON CHARGE ETC:-

53674. R.H. HEATER MADE TO WORK

51194. DR REPORTED WIND SCREEN WIPER ARM UNCOUPLED
REPLACED ADJUSTED - TESTED.

B.A. ROBERTS. P. COX.

CARS FUELED ETC; 53206
54058

WOCUS FUELED ETC. 40168 F11 08023 F11 47331 F11

40168 SANDERS MADE TO WORK.

53929 CARRIED TO WHANDUINO HEATER NOT WORKING
25 AMP FUSE BROWN NEW FUSE FITTED

57188 CARRIED TO STATION BOTH ENGS OVERHEATING
ON BRANCA BOTH IRAS TOPPED UP.

47458 CARRIED TO STATION W/ WIPER ARM UNCOUPLED
DR SIDE NO 2 END. ARM REFITTED & TESTED

54334 CARRIED TO WHANDUINO 3 NEW ENG - AIR
- AXLE LIGHTS BULBS FITTED - REPAIRS
TO A & A. BULB HOLDER NO 3 CAR.

53206 NO 1 ENG EXHAUST MANIFOLD JOINTS
BLOWING. NEW JOINTS FITTED.

THURSDAY 14TH APRIL 83.

	P/Car NO	MILEAGE
	51185.	35590.
	50940	—
	50931	68890.
	51562	N/R.
	53674	15140.
	53723.	61080.
	53206	N/F
R/T. 67057 m/t	50625	11580.
ic 65732 Full	51188	138250.

RAILWAY TRAVEL: 2/500 NO 2 6/100 TOTAL 8,600.

D. HILL. R. E. PRITCHARD.

CARS FUELLED ETC:-

53206. 50625. 51188. 51185. 53940.
 54058. 54213. 54348. 54352. 54273.

50931/51562. 53674/59064/ 53723.

LOCO'S FUELLED ETC:-

56067. (F) 25237. (F) 40143 (F) 47087 (F).
 25311 (F)

53674. DR REPORTED FLAT BATT'S PUT ON CHARGES ETC:-
 ALSO BUZZER NOT WORKING ADJUSTED.

51188. DR REPORTED NO 1 LUNG EXHAUST EXP BOX TOP
 WELD BROKEN. NOW BOX FITTED + TESTED.

54264. CALL TO STATION. BUZZER ADJUSTED.

53723. HEATRE MADE TO WORK.

51185. NO 2 LUNG EXHAUSTOR + ALTERNATOR BELTS MISSING NOW
 BELTS FITTED + ADJUSTED.

54213. FLAT BATT'S PUT ON CHARGES ETC:-

47087. NO 1 CARS HEATRE REPAIRED.

25311 L. H. SETTLING TANK GAUGE CHANGED.

A. A. ROBERTS. P. COX.

CARS FUELLED ETC: 57918 50463 57175
54495. 56453 54350

LOCOS FUELLED ETC: SIC SIC F/1
25190 25120 40047

47538 CALLED TO STATION. EARTH FAULT RELAY TRIPPED
RESET & TESTED.

25190 DR REPORTED BRAKE EXAMINING. BRAKE BOWLS
RENEWED ALL ROUND. ALSO EXHAUST MANIFOLD
JOINTS BLOWING ON PRESSURE CHARGER
NEW JOINTS FITTED.

54445 FNAT BATTERIES PUT ON CHARGE CIRC TESTED
NO 3 DYNAMO FUSE RENEWED. ALSO DRAGON
AIR HEATER REPAIRED FUEL SYSTEM BLED

57918 NO 1 ENG EXHAUSTER & ALTERNATOR BELTS
OFF PULLEYS REPAIRED & ADJUSTED.

54269 CALLED TO WHANDUDDINO HAND BRAKE
BUZZER STUCK RELEASED & TESTED

56453 FNAT BATTERIES PUT ON CHARGE. CIRC
TESTED. NO 3 DYNAMO FIELD FUSE RENEWED

FRIDAY. 15TH APRIL 83.

	P/CAR NO	MILEAGE
	50463	—
	50931	59200.
	51562	N/R.
	53208	62000.
	51175.	N/R.
	51918	59330.
R/T. 67057 m/T	53723	61090.
" 65732 Full	53674	15390.

FULL INTAKES NO 1 1/100 NO 2 6/100. TOTAL. 7,200.

D. HILL R.E. PRITCHARD.

CARS PULLED ETC:-

50463. 50931. 53208. 51175. 51918.
56453. 51562. 54060. 54350. 54495.

53723/59064/53674.

LOCO'S PULLED ETC:-

56067. (A) 40047. (S) 25237. (S) 25167 (S).

40047. SANDERS MADE TO WORK.

54060. LEAT BATT'S CHARGED ETC:-

51175. NO 1 ENGINE EXHAUSTOR & ALTERNATOR BELTS
OFF PULLEY ALL BELTS REPLACED & ADJUSTED.
ALSO DR UNABLE TO START NO 1 ENG. FUEL SYSTEM AIR
LOCKED BLEND & TESTED.

54350. HOATERS MADE TO WORK.

53208. HOATER R.H. SIDE MADE TO WORK.

50463. NO 1 ENG MANIFOLD JOINTS BLOWING CHANGED ETC:-

25167. WINDSCREEN WIPER NO 1 AND 2ND MAN'S SIDE REPAIRED.

ALSO L.H. SAND PIPE NO 2 ENG REPAIRED.

53208. CALL TO STATION. TRAIN LIGHTS NOT WORKING.

NO 4 FUEL BLOWN. NOW FUEL FITTED & TESTED.

B. A. ROBERTS. P. COX.

CARS FURNISHED ETC. 53625 57183 57185
54213 54344 54352

LOCOS FURNISHED ETC. 25792 F11 40143 SK
25311 S/L

47856 CARRIED TO STATION. DR REPORTED LOCO ROUGH
PUTTING. EXAMINED UNABLE TO FAULT LOCO

25286 CARRIED TO STATION. LOCO FAILED. BRAKE
APPLICATION FOR NO APP. REASON. EXAMINED
D.S.D. VALVE STUCK. LOCO BROUGHT ON
SHED. D.S.D. VALVE REMOVED & STRIPPED &
CLEANED REPLACED & TESTED.

40143. W/WIPER CONTROL VALVE DEFECTIVE. REMOVED
& RENEWED.

53625 COMPRESSOR AIR PIPE UNCOUPLED ON
COMPRESSOR. PIPE REMOVED GIVES REPAIRED
& REFITTED & TESTED.

25311 L.H. SIDE. NO. 1 BOGIE WD BRAKE SHACK
ADJUSTED. NOT WORKING. REMOVED & REPAIRS
& REFITTED.

SAT. 16TH APRIL. 83.

P/CAR NO M/LOADS.

51185.	35950.
51183.	63340.
51174	39070.
51193.	1790.
51562.	M/R.
50931	59500
53625.	11980.
53723	61090
53674	15650.

D. HILL R.E. PRITCHARD.

CARS PULLED ETC:-

53625. 51185. 51183. 51174 51193.
54213. 54352. 54344. 54333. 54502.

51562/50931 53723/59064/53674.

LOCO'S PULLED ETC:-

25311 (F) 56067 (F) 25173 (F)

25173. DR REPORTED SANDERS NOT WORKING + R.H. NO2
BOGIE SAND PIPE DAMAGED. BOTH REPAIRED.

53625. NO 1 ENGINE EXHAUSTOR + ALTERNATOR BOLTS
OFF PULLEY ALL BOLTS REPLACED + ADJUSTED

51185. PLAT BATT'S CHARGED ETC:-

51183. HTRATORS NOT WORKING NO6 FUSE CHANGED + R.H.
GLOW PLUG CHANGED BOTH TESTED.

54333. HTRATORS MADE TO WORKING GLOW PLUG CHANGED.
L.H. SIDE

51193. NO2 ENGINE PAN BOLTS MISSING. NEW BOLTS
FITTED + ADJUSTED.

54502. DRAGON AIR HTRATOR MADE TO WORK PULS SYSTEM
AIR LOCKED BRED + TESTED.

59064. PLAT BATT'S CHARGED ETC:-

54495. CALL TO STATION. DR REPORTED. BUZZER NOT WORKING
ADJUSTED. TESTED.

B. A. ROBERTS - P. COX

CANS FUELLED ETC. 51181 53929
54346 54213

LOCOS FUELLED ETC. 40196 S/C 40143 F11 25167 F11
25256 S/C

47577 CANNED TO BANGOR DR REPORTED SEWAGE TANK
M.T. 2 1/2 GALLONS SUPPLIED & TESTED

53674 CANNED TO STATION NO 1 ENG WON'T START
FRAT BATHS. TAKEN OUT OF SERVICE. PUT
ON CHARGE. AMM ALTERNATOR BELTS REPAIRED
& ADJUSTED

54495. CANNED TO WHANDUDDNO. HEATER NOT WORKING
(DAGONAIR) FUEL SYSTEM BLOWN & HEATER
TESTED.

54346 FRAT BATHS PUT ON CHARGE CIRC TESTED
AMM BATTERY CELLS TOPPED UP

25167 L.H. SIDE SETTLING TANK GAUGE GLASS
BLOWN. NEW GAUGE GLASS FITTED.