

LOG BOOK

From 10-12-84

REGISTER OF CHAINS, ROPES & LIFTING JACKS
CHESTER, BIRKENHEAD & NORTH WALES.

NEW TELEPHONE No For CREWE MAINTENANCE FROM 7-1-85
053-8243

DERBY RECORDS OFFICE: -056-3335

CHESTER G.P.O. 0244^{CODE}-318060 CHESTER DIESEL MAINTENANCE

CANOP INMIBISOL CLEANING SOLVENT

" WD 40.

MONDAY. 10TH Dec. 84

D. Hill. P. COX B. ARBORN 12.00 M. PRICE 16.00

CAR'S FUZZLED ETC.

53625./54213. 51179/54358 51193/54356

LOCO'S FUZZLED ETC:-

25283 (S) 40118 (V) B.F. 25072 (F) 47348 (F)

47218 "A" EXAM CARRIED OUT 1 BRAKE BLOCKS CHANGED.
ALSO 2 BRAKE SLACK ADJUSTERS REMOVED REPAIRED
REPLACED & ADJUSTED.

51179 CALL TO STATION. DR REPORTED HEATERS NOT WORKING.
NO6 FUSE BLOWN. NEW FUSE FITTED & TESTED.

47348. FLAT BATTERIES. PUT ON CHARGE. LOCO RUN UP & TESTED
AFTER RECHARGING. ALSO CILLS TOPPED UP.

25213 & 25245. COUPLED IN MULTI & TESTED FOR POWER ETC.

47436 CALL TO YARD. STEAM TANK LOW TOPPED UP & TESTED

51203. DR REPORTED. ENGINES. CUTTING OUT LUB OIL &
COOLANT TOPPED UP & TESTED NO FAULT FOUND.

47406 CALL OUT STATION. TO EXAM LOCO. CAB WINDOW
DR SIDE NO2 END. BROKEN BY FLYING STONES
LOCO 47218 COUPLED UP IN TANDEM TO ASSIST
CREW MAINT. INFORMED.

25072 SANDERS MADE TO WORK.

51193 NO1 ENG EXHAUSTER ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

Tue 11-12-84

CARBOURERS REPRITCHED.

P/CHG	MILES
53625	109030
51179	M/F
51203	h
53309	h
53338	h
51193	h
51186	h
51188	h
51190	h
51203	h

R.T 67125 Full
 " 67159 Full.

Fuel in Tanks No1 800 No2 4,000 TOTAL 4,800

CARS Fuel Oil Water etc.

51179 - 51203 - 53309 - 53625 51203
 54358 54339 53338 54213 54339

51193 - 51186 - 51188 - 51190
 54356 54357 54348 54353

53317-59131-53324

(P) (S)

Locos 47348 - 25059

51188 INFORMATION AND EXHAUSTION Boils off Pumps
 in Repritch etc

53324 ATTENTION TO HEADS ONLY / Working R.H side
 CRP TO Glow PVC MISSING No. 1 S TO Reference.

47411 CANNOT GO TO STATION REPRITCH SMALL AND Pumps
 coming from Bogie's of loco found BRADWOOD DISTANCE
 BRANDS RELEASED AND REPRITCHED. OR IN STATION.

B. A. ROBERTS, P. COX.

CARS FUELLED ETC. 51185
54352.

LOCOS FUELLED ETC. 40150 A-EXAM. 47064 (S)
25283 (F) 25072 (S) 40118 (S)

40150 A-EXAM COMPLETED.

53320 CALL OUT. L.H. HEATER NOT WORKING. NEW GLOW
PLUG FITTED.

D. HILL, M. PRICE.

CARS FUELLED ETC.:-

53337 53203
53320 51575 / 59581 / 51584. 54080

LOCOS FUELLED ETC.:-

47367 (F).

53337 } REPAIRS CARRIED OUT HEATER NOT WORKING. 53337 NOW
53320 } GLOW PLUG FITTED & TESTED. ALSO
NO 1 ENGINE PAN START MISSING. 53337. ENGINE &
P/DK ISOLATED. ALSO BOTTOM HALF OF SHUT-DOWN.
SOLINOID PLUS ARM TO FUR PUMP MISSING.
NO 2 ENGINE & P/DK ISOLATED FUR IN LUB OIL SYSTEM.
CAR TO CHARTER FOR REPAIRS.

STATION.

45106 CALL TO E.T.H. NOT WORKING E.T.H. EFR TRIPED ROBOT
& TESTED.

51575. NO 2 ENGINE EXHAUST & ALTERNATOR BELTS MISSING. NOW
BELTS FITTED & ADJUSTED.

51584 NO 2 ENGINE THROTTLE STICKING @ TIMING MOTOR
STRIPPED & REASSEMBLED. TESTED.

53203. NO 1 ENGINE EXHAUST MANIFOLD JOINTS BLOWING. NOW JOINTS
FITTED & TESTED. ALSO AIR MANIFOLD REMOVED FOR
ACCESS TO EXHAUST. NOW JOINTS FITTED.

WED 12-12-84

Carburettor Replacements

P/Car	Miles
51193	R/P
53203	"
51188	"
51186	"
51200	"
51196	"
51190	"
51185	"
53309	"
53338	"
51575	—
51584	—

R.T 67125 Empty
R.T 67159 yard full

Fuel in Tanks Hol 5,300 No2 6,200 Total 11,500

CARS FUEL OIL WATER ETC

51193 - 53203 - 51188 - 51186 53309
 54356 54080 54348 54357 53338
 51200 - 51196 - 51190 - 51185 51575
 54359 54336 54353 54352 59581
 51584

Loco's Fuel lbs (S) (P) (P) (S)
 47367 - 47064 - 40150 - 25059

- 51584 Replaced unable to start No 2 engine Faulty engine & motor return water to wall also attention to heater only 1 lb.
- 51575 Attention to heaters 2 water to wall.
- 53203 Attention to waterer hose pipe lamp fitted

B.A. ROBERTS. P. COX.

CARS FUELLED ETC. 53208
54060

LOCOS FUELLED ETC: 40118 (F) 25072 (F) 25236 (F)
47438 (F)

47445 CALL OUT STATION. ETH. NOT WORKING. EXAMINED
FOUND EITHER TRIPPED RESET & TESTED.

25236. R.H. SIDE SETTING TANK GAUGE GLASS BROKEN
NEW GAUGE GLASS & WASHERS FITTED.

53208. NO 2 ENG EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED

51191 CALL OUT STATION T/TONE HORNS NOT WORKING
BOTH HORNS ADJUSTED

25072. NO 2 BOGIE. L.H. LEADING SAND PIPE & STAY DAMAGED
NEW SAND PIPE FITTED & STAY REPAIRED.

D. HILL. M. PRICES.

CARS FUELLED ETC:-

5202. 51191 53694/59054/53733
54349. 54340

25072 CALL TO YARD. DR REPORTED LIGHTING C.B TRIPPING
WHEN LIGHTING SWITCH PUT ON. RESET. & TESTED
FOUND WIRE TO CAB LIGHT SWITCH NO 2 WND SUSPECTIVE
REPAIRED & TESTED.

59054 FLAT BATTERY PUT ON CHARGE ETC:-

51181 CALL TO STATION. DR REPORTED NO 2 ENGINE CUTTING OUT.
FUEL SYSTEM FOUND AIR LOCKED SYSTEM BLED & TESTED.

45156 CALL TO STATION. MAIN AIR FLOW PIPE NO 2 WND BURST
NEW PIPE FITTED & TESTED.

53694. NO 2 ENGINE EXHAUSTOR & ALTERNATOR BOLTS OFF PULLEY
REPLACED & ADJUSTED.

54340. R.H. MARKER LIGHTS NOT WORKING. FOUND WIRE BROKEN.
REPAIRED. & TESTED.

THUR 13-12-84

CARBOULERS REPAIRS

	P/LN2	MILES
	51196	N/P
	51200	"
	51191	"
	53338	N/P
	53309	"
	51202	"
	51185	"
	53203	"
	51190	"
	53733	—
	53694	—

R.F 67159 ~~Empty~~

FUEL IN TANKS NO1 4,200 NO2 6,200 TOTAL 10,400

CARS FUEL OIL WATER BR.

51196 - 51200 - 53338 - 51191
 54336 54359 53309 54340 53733
 59054 *
 51202 - 51185 - 53203 51190 53694
 54349 54352 54080 54353

here's fuel us (F) (P) (S)
 47367 - 25059 - 25288

- 53203 ATTENTION TO AIR HORNS ONLY / MAKE TO WORK UNABLE 2 TO WORK. NO PARTS FOR HORN ON HAND
- 51200 NO LUBRICANT EXPANSION VALVES OFF PULLEYS REPAIRED
- 51202 REPAIRS LEAK OF AIR PRESSURE IN FORWARD DIRT UNDER VALVE SEATING 2nd VALVE SERVICED. ALSO FRONT BRUSH FITTED

D. HILL. P. COX

CARS FUELLED ETC:-
53228/54058.

Locos FUELLED ETC:-
47198 (S) 47064 (S)

47438. CALL TO YARD DR REPORTED. EARTH FAULT LIGHT
BRIGHT. FLAG RESET & TESTED.

47198. EXHAUST MANIFOLD JOINTS. "A" SIDE ON TURBO.
CHARGER BLOWING. NEW JOINTS FITTED & TESTED.

54058. HEATERS NOT WORKING ROUND BATTERIES. LOW PUT
ON CHARGE HEATERS TESTED AFTER CHARGING.

51181 CALL TO STATION. TRAIN LIGHTS NOT WORKING FROM
VAN. NO.4 FUSE BLOWN. NEW FUSE FITTED & TESTED.

51190. CALL TO STATION. ONLY ONE TONE FROM HORN.
ADJUSTED & TESTED.

B.A. ROBERTS. M. PRICE.

	51181	51188	53726
CARS FUELLED ETC:	54345	54348	59105
			53682

LOCOS FUELLED ETC:

45746. CALL OUT TO BANGOR. DR REPORTED LOCO WEAK
ON POWER EXAMINED. P. M. RELAY STICKING
& CONTACTS DIRTY. CLEANED & EASED. LOCO TESTED
ON RETURN. TRIP. OK.

53345. FAN BATTERIES PUT ON CHARGE. CIRC TESTED & REPAIRS
TO BOTH HEATERS.

53682 NO.2 ENG EXHAUSTER & ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

51188 NO.1 ENG FAN BELTS MISSING. NEW BELTS
FITTED.

51187 CALLED OUT TO STATION, BUZZER NOT WORKING
IN GUARDS VAN. GEN'S BUZZER UNIT ADJUSTED.

RRI 14-12-84

Choules Re-Planned.

P/CAR	MILES
53726	—
53682	—
51196	N/R
51200	"
51181	"
53309	"
53338	"
51188	"
51185	"
51190	"
53931	"
51562	"

R.T 67159 Full

FUEL IN TANKS Mol 3,000 No2 6,200 TOTAL 9,200

CARS FUEL OIL WATER ETC.

51188	- 51190	- 51185	- 51181	
54348	54353	54352	54345	53726
				59105
53309	53931	- 51200	- 51196	53682
53338	51562	54359	54336	

Loco's fuel for 47367 - 25288 - 25059 - 40194

53682: DOWN REAR END UNABLE TO START WHENEVER FOUND TO
HAVE FIRST BATT FOR ON GEARBOX BECOMES RUN-UP.

53309: ATTENTION TO HEATERS UNABLE TO GET L.H. TOWARD.

53338: ATTENTION TO HEATERS 2 MADE TO WORK.

D. Hill. P. Cox

CARS FUELLED ETC. -

51183 / 54344

LOCO'S FUELLED ETC. -

47308 (F) 47064 (F)

51187. CALL TO STATION. NO 2 ENGINES. KNOCKING OFF FOUND PUMP SYSTEM AIR LOCKED. BLED & TESTED.

51183. NO 2 ENGINES EXHAUST FLEX PIPES HOLED. NEW PIPES FITTED.

47406. CALL TO YARD DR REPORTED VERY BAD BRAKE ON LOCO OR TRAIN. LOCO EXAM NO FAULT FOUND. TRAIN BRAKES. DEFECTIVE SOUT R.S.T. II REPORT.

47308. WINDSCREEN WIPER. JAB SIDE NO 2 WIND NOT WORKING. CONTROL VALVE REPAIRED & TESTED.

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC. 51187 53208 51580
54332 54060 59586
53938 51186 51589

LOCO'S FUELLED ETC. 52411 54357
25325 (S)

25288. CAME OUT NEW YARD. PORANE PIPE PRESSURE ON OVERCHARGE CONTINUALLY. EXAM FOUND SET II AUTO CHARGE BUTTON STUCK IN NO 1 END. RENEWED & TESTED.

53931 CAME OUT WHANDUDDNO DR REPORTED ENGS CUTTING OUT RAILS TOPPED UP & TESTED.

54411 FLAT BATTERS PUT ON CHARGE CIRC TESTED. NO 9 DYNAMO FUSE RENEWED.

51589 NO 1 ENG THROTTLE MOTOR STICKING ON FULL REVS. MOTOR STRIPPED CLEANED & LUBED.

SAT 15-12-84

CHROULLES R.E. PITCHARD

P/Unit	MILES
51190 ✓	N/P
51188 ✓	4
51186 ✓	4
53938 ✓	4
53338 ✓	4
53309 ✓	4
53931 ✓	4
51562 ✓	4
51187 ✓	4
51185 ✓	4
53208 ✓	4
51580 ✓	—
51589 ✓	—

R.T 67159 Full

FUEL IN TANKS NO1 2,200 NO2 6,200 TOTAL 8,400

CHANG FUEL OIL WATER, ETC

53338 - 51190 - 51188 - 51186 - 53938
 53309 54353 54348 54357 54411
 53208 - 51185 - 51562 - 51187 - 51580 - 59586 - 51589
 54060 54352 53931 54332

51580: DANGER REPORTED UNABLE TO START Engines Found
 TO HAVE FUEL BAIT PITCHARD ALSO ATTENTION TO 2
 HOURS 2 MADE TO WORK.
 59586: FUEL BAIT PITCHARD ALSO ATTENTION TO 2
 HOURS 2 MADE TO WORK
 51589: ATTENTION TO 2 HOURS 2 MADE TO WORK.
 51187: ATTENTION TO 2 HOURS MADE TO WORK (Bait) (See Section)
 54332 ~ ~ ~ 2 MADE TO WORK.

B. A. ROBERTS. M. PRICE.

53228 51199 51198 57184
CARS FUELLED ETC: 54055 54334 54337 54342

LOCOS FUELLED ETC: 25042 (S) 25276 (S) 25325 A. Ex
47064 (S) 47223 (F)

51580 CALLED TO HAND NO DR REPORTED. N°6 FUSE
BLOWN & BUZZER RINGING CONTINUALLY. R.H.
PUSH BUTTON IN GUARDS VAN DEFECTIVE. BUTTON
STRIPPED & REPAIRED & REPAIRED & NEW N°6 FUSE
FITTED & TESTED.

25325. A. EXAMINATION CARRIED OUT. BRAKE BLOCKS
RENEWED.

25042 SANDERS NOT WORKING. ALL SANDERS MADE TO
WORK.

SUN 16-12-84

CARBOURERS REPAIRS

	P/MLR	Miles
	51184	MF
	51198	"
	51185	"
	53931	"
	51562	"
	51175	"
	51180	"
	51191	"
	53206	"
	53228	"
	53309	"
	53338	"
	59586	—
	51580	—

RT 67159 RUN

FUEL TANKS No 1 1,300 No 2 6,200 Total 7,500

CARS Fuel oil Water Grease etc.

51184 - 51198 - 51175 - 51180
54342 54337 54350 54355

51191 - 53206 - 53228 - 53338
54340 54058 54055 53309

53931 - 51185 - 59580 - 59586 - 51589
51562 54352

51184 > Driver Reported No 1 Btg Win No 1 Run Found Road Car Missing Now Car Fitted

51580 - PWT BATT FOUND TRAM LIGHTS STILL ON PWT ON CHARGE

59586 - PWT BATT AS ABOVE PWT ON CHARGE

53338 - FOUND ALL BELTS OFF AND NO 2 AUTOMATIC MISSING
AN BELTS EXHAUSTION AND AUTOMATIC FITTED

(P)

(S)

Locos 25325 - 25042

54337 - ATTENTION TO AIR HOORN MADE TO WORK

MON 17-12-84

	P/CAR	MILEAGE.
	51198	NF
	51184	"
	53203	"
	51589	—
	51580	—
R.T. 67159 FULL		

FUEL IN TANKS N^o1 9.00 N^o2 6.200 TOTAL 7.100.

B. A. ROBERTS. M. PRICE.

	51198	51184	53203		
CARS FUELLED ETC.	54337	54342	54080		
51580	53309	53931	51185	51191	53206
51586	53338	51562	54352	54340	54058
51589	53228				
	54055.				

LOCOS FUELLED ETC. 25325 (S) 25276 (F) 25042 (F)
47064 (F)

54080 DR REPORT NO HEAT IN DRIVING CAB. EXAM L.H. HEATER VENT PANELS ETC REMOVING. TO REMOVE MATERIAL BLOCKING AIR FLOW INTO CAB. PANELS REPLACING & HEAT TESTING

MON 17-12-84

WHFOULKES P. E. PRITCHARD

WAS RUL LMS 53208 - 53625 53324
54060 54213 59131
53317

51198:- CANCELLED OUT TO STATION ATTENTION TO
TRAIN HEAVIES NO 4 ROSE FOUND BLOWN. CURR
REPAIRED 2 HEAVIES MADE TO WORK

53317: ATTENTION TO TRAIN LIGHTING CIRCUIT RELAY REPAIRED
STICKING CONTACTS. ADJUSTED TO WORK.

51184:- CANCELLED OUT TO WANDJUDMO STATION ATTENTION
TO HEAVIES REPAIRED KNOCKED OFF. MADE TO
WORK. BR. RULITY RUL SINGOR INSIDE HEAVY
UNIT.

Locos RUL LMS 25178

25178 CANCELLED OUT TO YARD DRIVER REPORTED UNABLE
TO RESTART LOCO TRACING FOR FAULT FOUND STOP
BUTTON STUCK IN RESET LOCO RUN-UP.

D. HILL. P. COX
CARRS RUL LMS ETC:-

53208. 51202. 51196. 51182. 53450
54060. 54349. 54336. 54341. 59256
53428.

45104 CALL TO STATION DR REPORTED LOCO LOW IN POWER
NOT WORKING DURING WENT TO BLOWER & FOUND P.M
RELAY STICKING TIPS CLEANED & TESTED ON RETURN

51182 CALL TO STATION WINDSCREEN WIPER NOT WORKING
ARM LOOSE SCREWED UP & TESTED.

51188 CALL TO STATION. TRAIN LIGHTS NOT WORKING FROM
VAN. NO 4 RULS CHANGED & TESTED

59256 REAR BATTERIES. PUT ON CHARGE CIRCUIT CHECKED
DYNAMO BOLT MISSING NOW BOLT FITTED & ADJUSTED.

TUE 18-12-84

51182	NF
51196	"
51202	"
53228	"
53208	"
53203	"
51184	"
53931	"
51562	"
53428	—
53450	—
53732	—
53686	—

R-T. 67159 FULL.

FUEL IN TANKS NO1 900 NO2 5.200 TOTAL 6100

B.A. ROBERTS. M. PRICE. 53426 53732
 59256 59526 53931 51184
 CARS FUELLED ETC. 53450 53686 51562 54342

51182 51196 51202 53228 53203 53208
 54341 54336 54349 54055. 54080 54060

LOCOS FUELLED ETC; 25042 (S) 25276 (S) 47064 (S)
 25315 (F)

H5140 CAME OUT TO CONWYN BAY. LOCO FAILURE.
 ENG SHUT DOWN LOSS OF SUMP OIL, CAUSED
 BY NO. 4 CYL B. BANK ROCKER GEAR HOLDING
 DOWN STUDS BROKEN. ALSO ROCKER COVER
 NOOSE & HOLDING DOWN STUD BROKEN LOCO
 ISOLATED & HAWLED TO DEPOT. TOPS INFORMED
 CODE 121.

TUE 18-12-84

CAROLINE R E PRITCHARD

D. HILL 12.00 Post 16.00

CARS ROL ON WATER etc 51177 - 51191
54351 54340

45140 TO BE MOVED TO CRANE FOR REPAIRS.

LEO'S ROL LMS 47064 - 47227

47064 A EXAM AND BRAKE BLOCKS TO CHANGE

A EXAM COMPLETED LMS NO 1/F 24 BRAKE BLOCKS REMOVED

47442: CALLED OUT TO STATION REPORTED PRO. HUNT IN TRAIN
FOUND R.T.H RELAYS TRIPPED AND RESET REINSTALLED
CIRCUIT FOR 3 MIN. HOLDING OK LMS TESTED FOR POWER.

51177: CALLED OUT TO STATION. DEWON REPORTED NO 2 CIRCLES
KNOCKED OFF AND WOULD NOT RESTART FOUND TO HAVE AIR LOCK
BLEEDING FREE OF AIR.

47501. CALL TO YARD. DR REPORTED BARTH FAULT LIGHT
BRIGHT. FLAG RESET. & TESTED.

54080 CALL TO LINDENDUNO DR REPORTED NO 6 KISS BLOWN
FOUND IGNITION SWITCH DEFECTIVE. TEMP REPAIRED

54348 CALL TO STATION. DR REPORTED HORNS NOT WORKING
NO 6 KISS BLOWN NOW KISS FITTED ALSO NOW
GLOW PLUG FITTED R.H. HORNS BURNT OUT.
HORNS TESTED

47064 2 BRAKE SLACK ADJUSTERS REMOVED & REFIT. SIZED
47064 " " " " OVERHAULED ON BENCH.

CARS FUELLED ETC:-

51198/54337 51181/54345

54337. TOWARD HORN ADJUSTED & TESTED.

45123 CALL TO STATION. DR REPORTED. DR'S SEAT. NO 1 LMS
DEFECTIVE REPAIRED & TESTED.

MED. 19-12-84

	PICAR	MILEAGES
	53228	NF
	51198	u
	51181	u
	51196	u
	53931	u
	51562	u
	51188	u
	53203	u
	51184	u
	53664	—
	53702	—
	53722	—
	53672	—
R.T. 67159 FULL.		
R.T. 65727 FULL.		

FUEL IN TANKS N^o 1,000 N^o 2 3,900 TOTAL 4,900
B.A. ROBERTS. M. PRICE.

53664 53672
 CARS FUELLED ETC: 59206 59523 53931
 53702 53722 51562
 53228 51198 51181 51196 51188 53203 51184
 54055. 54337 54345 54336 54348 54080 54342

LOCOS FUELLED ETC: 25213 (S) 25042 (F) 25315 (S)
 47064 (F)

59206 FLAT BATTERIES PUT ON CHARGE, CIRC TESTED
 ALL BATTERY CELLS TOPPED UP.

51188 N^o 2 ENG EXHAUSTER - ALTERNATOR BELTS
 MISSING NEW BELTS FITTED.

WED 19 - 12 - 84

CABOULLES R. B. PRITCHARD.

DNU'S Fuel Oil Water Check etc

51202 - 51920
54349 54504

(5) (5)

Loco's Fuel Water etc. 47225 - 25213

51202 ATTENTION TO TRAIN HEADS MADE TO WORK
ALSO AIR MORN'S HOT WORKING REPAIRS

54504 REPORTED NO HEAT IN CONCRETE HEADER MADE TO WORK
BUT POOR HEAT OUT PUT. INTO CONCRETE.

47225 - DRIVER REPORTED AIR MORN STICKING ON IN HO/
ROAD CARB FOUND DIRTY UNDER VALVE SEATING VALVE
SERVICED AND REPTED. CAME TO YARD HERE FOR WORK
ON SUND PULL FUEL WATER AND REPAIR.

D. HILL. P. COX

CARS PULLED etc:-

51189/54343. 53668/59100/53721
51183/54344.

47409. CALL TO BANBOR. LOCO FAILED. ENGINES
SHUT-DOWN. WILL NOT RESTART. LOCO EXAM.
COOLANT 3/4 FULL FUEL 300 LUB OIL FULL
OVERSPEED CHECKED. SUSPECT FAULT ON E.T.H.
UNABLE TO REPAIR @ BANBOR LOCO STILL
@ BANBOR TO BE Hauled TO SITE. FOR EXAM'S.
(WANTS ISOLATING)

51189 NO1 ENGINES EXHAUSTOR & ACTUATOR BOLTS OFF
PULLEY ALL REPLACED & ADJUSTED.

53668. NO2 ENGINES THROTTLE STICKING. MOTOR STRIPPED & ASSEMBLED
& TESTED.

59100 FURT BATTERIES. PUT ON CHARGE CIRCUIT CHECKED.
FOUND NO9 FUSE BLOWN NEW FUSE FITTED & TESTED.

THURS 20-12-84

	PLCAR	MILES
	51198	NF
	51181	"
	51189	"
	51196	"
	53931	"
	57562	"
	51920	"
	51183	"
	51188	"
	53721	—
	53668	—
R.T. 67159 FULL		
" 65727 FULL.		

FUEL IN TANKS N^o1 1.100 N^o2 2.600 TOTAL 3.700

B. A. ROBERTS. M. PRICE.

53721

53931 59100 51198

CARS FUELLED ETC.: 57562 53668 54337

51181 51189 51196 51920 51183 51188

54345 54343 54336 54564 54344 54348

LOCOS FUELLED ETC.: 25042(5) 47064(5) 25276(5)
40118(5)

25276 EXHAUST MANIFOLD JOINTS BROWN OUT. TOP & BOTTOM ON TURBO CHARGER. NEW JOINTS FITTED

April 20-12-84

CARBOURERS RE PRITCHARD.

CARS RUN ON WATER CROCK

51187 - 51200

54332 54359

Wheels ③ ④ ⑤
47064 - 47365 - 25042

51200: EXHAUSTER BELTS OFF POLYERS AND REFITTED AND READJUSTED

54359: AIR LEAK BULB FITTED IN PORTER.

54332: ATTENTION TO HEADS MADE B WALL.

D. Hill. P. Cox.

CAR'S PULLED WTC:-

51184 51174 51161 51169
54342 54333 54343 54343

51434 / 51502

CALL TO STATION. 54332. DR REPORTED.
BUZZER NOT WORKING ADJUSTED & TESTED.

54333 CALL TO STATION. TRAIL LIGHTS NOT
WORKING NO 4 PIST BLOWN - NOW PIST FITTED
& TESTED

54336 CALL TO STATION WINDSCREEN WIPER UNCOUPLED
REPLACED ADJUSTED & TESTED.

51174. NO 2 ENGINES EXHAUST MANIFOLD JOINTS
BLEEDING NOW JOINTS FITTED & TESTED

47432. CALL TO STATION DR REPORTED WINDSCREEN
WIPER ARM UNCOUPLED REPLACED & ADJUSTED.

FRI 21-12-84

	PICAR	MILES
	51184	NF
	51181	NF
	51189	"
	51174	"
	51187	"
	51188	"
	51196	"
	51502	—
	51434	—
	53931	NF
R.T. 67159 FULL	51562	NF
65727 FULL	53316	NF
	53334	NF
	53313	"
	53333	"

FUEL IN TANKS NO 1 1.200 NO 2 900 TOTAL 2.100

B.A. ROBERTS. M. PRICE. 53313

53316 59116 53931 51434
 CARS FUELLED ETC: 53334 53333 51562 51502
 51184 51181 51189 51174 51187 51188 51196
 54342 54345 54343 54333 54332 54348 54336

LOCOS FUELLED ETC: 47064 (F) 40152 (F) 25042 (F)
 40012 (F)

51189 BOTH HEATERS REPAIRED ALSO R.H. SIDE
 MARKER LIGHT BULB RENEWED.

59116 FLAT BATTERIES, PUT ON CHARGE, CIRC TESTED
 AM CEMS DRY. TOPPED UP & TESTED.

53313 BOTH HEATERS REPAIRED. N.H. GLOW PLUG
 REMOVED & OVERTIGHTENED. R.H. SIDE NO 6 FUSE
 BLOWN RENEWED.

FRI 21-12-84

CARBOURERS REPRITCHED

51189 - ATTENTION TO 2 HEATERS MADE TO WORK.

51181 - DRIVERS REPORTED UNABLE TO START RANGING (GOOD WORKS)
FOUND TO HAVE PUT BATT PUT ON CHARGE ENGINES.
RUM-UP ALSO HEATERS MADE TO WORK.

CHARGES FUEL OIL WATER BIZ. 51177 - 53334
54351 53316

R.T 65727 DISCHARGED - FUEL TANKER

Loco's FUEL LHS (7) (5)
47064 - 47317

D. Hill P. Cox

45106 CARL TO BANGOR DR REPORTED. ENGINE SITUATION - DOWN
AXMAN & FOUND NO LUB OIL COCO ITALIAN TO
STOP STOPPED, TOPS INFORMED CODE 17.3

CAR'S FUELLED ETC.

53927 / 54214. 5194 / 54346 53206 / 54058

53228 / 54055. 53664 / 54206 / 53702

53664 NO2 ENGINE EXHAUST MANIFOLD JOINTS CHANGED &
TESTED.

54206. HEATERS NOT WORKING FOUND BATTERIES LOW PUT
ON CHARGE CIRCUIT CHECKED HEATERS TESTED
AFTER CHARGING.

53927. NO2 ENGINE EXHAUSTOR & ALTERNATOR BELTS OFF
REPLACED & ADJUSTED.

CARROLLS M. PRICE

P. CAR	MILES
51181	N/F
51184	"
51194	"
51174	"
51189	"
53228	"
53206	"
53927	"
53316	"
53334	"
51196	"
51562	"
53931	"
53664	—
53702	—

R.T. - 65727 Empty
 R.T. 67159 Full

FUEL IN TANKS No1 3,000 No2 6,500 TOTAL 9,500

CARS FUEL OIL WATER CHECK ETC

51181 - 51184 - 51194 - 51174 - 53228
 54345 54342 54346 54333 54055

53206 - 51189 - 53316 - 53927 - 51196
 54058 54343 53334 54214 54336

51562 - 53664 - 53702 - 53931

51196 ATTENTION TO HEATERS MADE TO WORK.
 51562 ATTENTION TO HEATERS MADE TO WORK.
 54343 ATTENTION TO HEATERS MADE TO WORK.
 53206 PROBLE REPORTED UNABLE TO START ENGINE DUE TO
 TO HAVE FUEL BUT PUT ON COURSE REPAIRS RUN-UP.

D. Hill. P. Cox
CAR'S Hauled etc:-

51199/54334 53316/53325

Loco's Hauled etc:-

40662 (S) 25226 (S) 47064 (S) 25042 (S)

45111 CALL TO STATION. DR REPORTED LOSS OF POWER
UNABLE TO REPAIR @ STATION. LOCO ISOLATED.
& HAILED TO MANCHESTER WITH TRAIN.

45106 "A" EXAM CARRIED OUT ALSO LUB OIL TOPPED UP.
LOCO STOPPED FOR BRAKE BLOCKS ~~REMOVED~~.

47428 CALL TO YARD DR REPORTED WORTH FAULT LIGHT.
BRIGHT FLAG RESET & TESTED.

SUNDAY 23-12-84

	PICAR	MILEAGE.
	51194.	NF
	51184.	"
	53325	"
	53306	"
	53208	"
	53206	"
	53228	"
	51199	"
	53927	"
	51174.	"
	51903	"
	53931	"
	51562	"
	51196.	"
	53702	—
	53664	—

B.A. ROBERTS. M. PRICE.

51194 51184 53325 53208
CARS FUELED ETC: 54346 54342 53306 54660
53206 53228 51199 53927 51174 51903 53931 51196
54058 54055. 54334 54214 54333 54486 51562 54336
53702
59206
53664.

45106 BRAKE BLOCKS RENEWED ALL ROUND.

MON 24-12-84

CARROLL R. BRITCHARD

P/CHR	Miles
51183	N.P
51200	N.P
51196	N.P
53931	n
51562	n
51903	n
51174	n
53927	n
53208	n
53325	n
53306	n
51199	n
53206	n
53228	n
53702	—
53664	—

R.T 65727 EMPTY
R.T 67159 FULL

FULL TANKS NO1 1,500 NO2 6,500 TOTAL 8,000
CHECK FUEL OIL WATER.

51183 - 51200 - 53325 - 53228 - 53306
54344 54359 53306 54055 54058

53208 - 51199 - 53927 - 51174 - 51903
54060 54334 54058 54333 54486

53931 - 51196 - 53702 - 53206 - 53664
51562 54336

Ⓟ

Locos Fuel hrs: 47064

53208 ATTENTION TO HEADS Hob Fuse Blow Repaired & Rechecked

53931: DRAWR REPORTED UNABLE TO START ENGINE FOUND TO HAVE PLAT BAIT PUT ON CHARGE ALSO ATTENTION TO HEADS

53664: TRAIN LEAVING FOUND BEFORE DRAWR UNABLE TO START ENGINES DUE TO PLAT BAIT PUT ON CHARGE ALSO ATTENTION TO HEADS

53325: DRAWR REPORTED UNABLE TO START ENGINES FOUND TO HAVE PLAT BAIT PUT ON CHARGE ALSO ATTENTION TO HEADS

53306: ATTENTION TO 2 HEADS MADE TO WORK

B.A. ROBERTS M. PRICE.

CARS FUELLED ETC. 53978 53316
54261. 53334.

LOCOS. FUELLED ETC. 45106 (S) 25042 (F)
47064 (F) 25226 (F) 25315 (S) 47598 (F)
47187 (S) 47468 (F)

53702 } CAMEL TO STATION DR REPORTED. VACUUM
53664 } VERY SLOW BLOWING UP. EXAMINED. EXHAUSTER
POTS M.C. FINISHED UP + TESTED.

47598. CAMEL TO STATION D.S.D NOT WORKING. EXAMINED
D.S.D. APPLICATION VALVE DEFECTIVE. LOCO
45106 WORKING FORWARD. 47598 BROUGHT
ON SHED. FOR ATTENTION.

47468. CAMEL TO NEW YARD DR UNABLE TO START
LOCO. FOUND TO HAVE FLAT BATTERIES.
LOCO HAWKED TO SHED PUT ON CHARGE
CAMEL TESTED ALL BATTERY CELLS TOPPED
UP. LOCO 25315 WORKED TRAIN FORWARD.

TUE 25-12-84

CITROUILLES R & PRITCHARD

	PLUM	MILES
	51200	NAF
	51202	"
	53228	"
	53206	"
	53306	"
	53325	"
	51196	"
	51562	"
	53931	"
	51199	"
	51174	"
	53927	"
	53334	"
	53316	"
	53664	—
	53702	—

RUB IN TANKS NO1

NO2

TOTAL

CHRS RIVER OIL WATER ETC.

53306 - 51196 - 51562 - 51199 - 51174

53325 54336 53931 54334 54333

53927 - 53334 - 51200 - 51202 - 53228

54214 52316 54359 54349 54055

53206 - 53664 - 59206 - 53702

54058

leeds 25042 - 25226 - 47598 - 47187 - 47468

8 hrs COURSED Frost-Preventions AND MAINTENANCE AND SECURITY OF LEES AND DMV'S + EQUIPMENT ETC

WED 26-12-84

ATTENUUS DA ROBERTS REPRITCHING - M PRICE

COVERING PROSI- PRECAUTIONS \$	51200	N.F
MAINTENANCE OF D&B SECURITY	51202	"
SECURITY OF WOODS \$ DMUS \$	53228	"
EQUIPMENT. ETC.	53206	"
	53306	"
	53325	"
	51196	"
	51562	"
	53931	"
	51199	"
	51174	"
	53927	"
	53334	"
	53316	"
	53664	"
	53702	"

RT 65727 EMPTY
RT 67159 FULL

FUEL INITIATES NO1 600 NO2 5400 TOTAL 6.000.

UNITS AND WOODS RUN-UP RE FIRST-PRECAUTION'S ETC.

53306 - 51196 - 51562 - 51199 - 51174

53325 54336 53931 54334 54333'

53927 - 53334 - 51200 51202 - 53228

54214 53316 54359 54349 54055

53206 - 53664 - 59206 - 53702

54058

WOODS 25042 - 25226 - 47598 - 47187 - 47468

TRUCK 27-12-84

CHANGES RE-PITCHED

	P/CHG	MILES
	51562	N.P
	53931	"
	51196	"
	53306	"
	53325	"
	51199	"
	51174	"
	53927	"
	53334	"
	53316	"
	51200	"
	51202	"
	53228	"
	53206	"
	53664	-
	53702	-
	51202	"
	53206	"
	51188	"
R.T 67159 Full		
R.T 65727 Empty		

FUEL IN TANKS NO1 600 NO2 5400 TOTAL 6,000

CARS PITCHED, ETC

53306 - 51562 - 53334 - 51196 - 51202
 53325 53931 53316 54336 54349

51199 - 51174 - 53927 - 51200
 54334 54333 54214 54359

53228 - 53206 - 53664 - 53206 - 53702
 54055 54058

53931 : UNABLE TO START ENGINES DUE TO FUEL BATT FROM CARLOS ALSO
 ATTENTION TO HEATERS MADE TO WORK.

51562 : AS ABOVE.

53664 : } UNABLE TO START ENGINES DUE TO FUEL BATT PUT ON CARLOS
 53702 : } ATTENTION TO HEATERS ALL MADE TO WORK.

51202 : } ATTENTION TO HEATERS 3 MADE TO WORK ON 12/12/84.
 54349 : }

A. A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51183 51191
54344 54340

LOCOMOTIVES FUELLED ETC: 47598. (S) 47064 (S) 25042 (S)
25226 (S)

45111 CALL OUT STATION. ETH NOT WORKING. EXAMINED
FOUND ETHFR TRIPPED. RESET & TESTED OK.

47523. CALL OUT BANGOR. DR REPORTED SERK
CELL TANK LOW. TOPPED UP & TESTED OK.

47064. NO 1 & 2. B. BANK EXHAUST MANIFOLD
JOINTS BLOWING. NEW JOINTS FITTED.

47598. D.S.D. DEFECTIVE. FAULT FINDING. TRACED
TO T.M.V. 7. DEFECTIVE. NEW VALVE FITTED
& TESTED.

51183. NO 1 ENG. EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED.

54340 FLAT BATTERS PUT ON CHARGE CIRCUIT TESTED
ANAL CELLS TOPPED UP & ALTERNATOR
BELTS ADJUSTED.

Feb 28-12-84

CITROUS REFRIGERATED

	P/CHZ	MILES
	51199	N/P
	51200	"
	51183	"
	51174	"
	53927	11
	51191	"
	53664	—
	53702	—
	51196	N/P
	51562	"
	53931	"
	51202	11
	53206	11
	51188	11

R.T 65727 Empty
R.T 67159 Full

FUEL IN TANKS No1 600 No2 4,200 Total 4,800

CARS ROLL ON WATER BIT.

51174 - 53927 - 51191 - 51200 - 51202
54333 54214 54340 54359 54349

51199 - 51183 - 51196 - 51562 53206
54334 54344 54336 53931 54056

53664 - 53206 - 53702 51188
54348

- 53931: UNABLE TO START BECAUSE LEAK BUT PUT ON CRUISE
- 54336: ATTENTION TO HANDLES 2 MADE TO WORK.
- 54359: ATTENTION TO HANDLES 2 MADE TO WORK
- 47468 out of course ATTENTION HANDLES TRAIL FRAMES.
- 54330: ATTENTION TO HANDLES MADE TO WORK

B. A. ROBERTS. M. PRICE.

CARS FURNED ETC: 53316 51190 51184
53334 54353 54342.

LOCOS FURNED ETC: 47064 (F) 47598 (F) 47468 (F)
25226 (F) 25042 (F) 25194 (F)

53931 CARL OUT LHANDUDNO. HEATER NOT WORKING
N^o 6 FUSE BLOWN. NEW FUSE FITTED.

45706 CARL OUT STATION. ENG SHUT DOWN. UNABLE TO
RESTART. OIL GOV FILTER TURNED. ENG STARTED
25194 COMPILED IN TANDEN TO ASSIST. SUSPECT
OIL PRESSURE SWITCH.

47401. N^o 1 END POLYMER PIPE. FLEX PIPE BURST
NEW PIPE FITTED (CARRIED OUT TO YARD)

25194. R. H. SIDE SETTLING TANK GARGE GLASS
BROKEN. NEW GLASS FITTED.

53334 N^o 1 ENG EXHAUST MANIFOLD JOINTS
BLOWING. NEW JOINTS FITTED.

SAT 29-12-84

CITIZENS REFINERY

P/MSZ	MILES
53334	M.F
53316	"
51199	M.F
51200	"
51202	"
51196	"
53931	"
51562	"
53664	—
53702	—
51174	"
53927	"

FUEL IN TANKS NO1	NO2	TOTAL
-------------------	-----	-------

CARS FUEL OIL WATER ETC.

53334 - 51199 - 51200 - 51202
 53316 54334 54359 54349
 51196 - 53931 - 51174 - 53927
 54336 51562 54335 54214

53664 - 59206 - 53702

⑤ ⑤
 holds 25042 - 28226

51199 } Attention to Hunters & made to work.
 54334 }
 59206 } Attention to Hunters & made to work Glow plugs service
 54332 " " " "

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC. 51180 51188 53206
54355 54348 54058
53306
53325.

LOCOS FUELLED ETC. 47332 (5)

45110 CALLED TO STATION DR REPORTED. PARTIAL LOSS OF POWER ENROUTE ALSO E.T.H NOT WORKING EXAMINED FOUND O.V.R TRIPPED RESET & TESTED OK.

47479. CALLED TO BANGOR. DR REPORTED N°2 END DR SIDE WARNING HORN VALVE HANDLE BROKEN. HANDLE REPAIRED & TESTED.

54349. FLAT BATTERIES PUT ON CHARGE CIR TESTED.

R.T. 67159 UNLOADED.

25042. N°2 END 2 MAN SIDE CAB DOOR HANDLE & LOCK BROKEN, NEW HANDLE & LOCK FITTED.

47332 EXHAUST MANIFOLD JOINTS BLOWING. TOP & BOTTOM B. BANK PRESSURE CHARGER NEW JOINTS & NEW SET SCREWS FITTED.

51188. N°1 ENG & F DRIVE ISOLATED. GASKET BLOWN UNIT TO WORK TO CHESTER.

51180 N°1 ENG EXHAUSTER ALTERNATOR BELLS OFF PULLEYS. ALL BELLS RELAXED & ADJUSTED.

Sunday. 30th Dec 84

P/CAR NO MILEAGE

53664

—

53702

—

51174.

N/F

50927.

"

53206.

"

51202.

"

51187.

"

53306

"

53325.

"

51200.

"

51188.

"

D. Hill. P. Cox

CAR'S PUZZLED ETC.

51174. 53927. 53206. 51202. 51187.
54333. 54214. 54058. 54349. 54332
53306 51200 53664/54206/53702
53325 54859

LOCO'S PUZZLED ETC.

47280 (S) 25226 (S)

51174. NO.1 ENGINES EXHAUST MANIFOLD JOINTS BLOWING.
NEW JOINTS FITTED & TESTED

54332. HURTOR MADE TO WORK NO.6 PISTON BLOWN.

51187. NO.1 ENGINES EXHAUSTOR & ALTERNATOR BOLTS
OFF PULLEY. BOLTS REPLACED & ADJUSTED

47280. DR REPORTED BLUE FLAME LIGHT BRIGHT. SUSPECT
LOW OIL PRESSURE. SUMP TO CHECK. LOCO EXAM.
SUMP OIL OK. LOCO LOW IN COOLANT. TOPPED UP

53702. R. H. HURTOR NOT WORKING. NEW GLOW PLUG
FITTED & TESTED.

MONDAY 31ST DEC. 84

P/CAR NO	MILES
53938	N/P
51184	"

R/T.

FUEL IN TANKS NO 1 NO 2 TOTAL 11,700.

D. HILL R. E. PRITCHARD.

CARS PULLED ETC. -

53938.	51188.	51200.	53306.	53206.
54411	54348.	54359.	53325	54058
51202.	51187.	51184.		
54349.	54332.	54342.		

Loco's PULLED ETC. -

47280 (F). 25226 (F) 25042 (F).

53938. NO 2 ENGINE THROTTLE STICKING REMOVED AND TESTED.

53306 NO 1 ENGINE EXHAUST MANIFOLD JOINT BLOWING. NOW JOINT FITTED & TESTED.

54342. PLAT BATTERS LIGHTS & INDICATOR LEFT ON. PUT ON CITRUS ETC. -

B. A. ROBERTS. P. COX. M. PRICE.

CARS FUELLED ETC.: 53316 51176 51198
53334 54360 54337

LOCOS FUELLED ETC.: 25059 (S) 47334 (F)

54360 FLAT BATTERIES. PUT ON CHARGE CIRK TESTED
NO 9 DYNAMO FUSE BLOWN.

51176 NO 1 ENG EXHAUSTER & ALTERNATOR BELTS
MISSING. NEW BELTS FITTED.

25059 ALL SANDERS MADE TO WORK.

53316 CANN OUT STATION T/TONE HORN. NOT WORKING
BOTH HORNS ADJUSTED.

47334 NO 2 & 3 EXHAUST MANIFOLD JOINTS BLOWING.
NEW JOINTS FITTED.

47409 CANN OUT STATION DR REPORT NO 1 END ENG
LED WARNING LIGHT NOT WORKING. NEW BULB
FITTED.

51184 CANN OUT BANBOR DR REPORTED FIRE ON TOP
OF NO 2 ENG. FIRE EXTINGUISHED. EXAMINED
FOUND COMPRESSOR FLEX PIPE BURST. UNIT
TAKEN OUT OF SERVICE FOR REPAIR.

Tuesday 1st JAN 88

P/CAR NO	MILEAGE
51187	N/F
51198	"
53938	"
53316	"
53334	"
51200	"
53325	"
53306	"
51184	"

R/T. 65727. } M.T.
" 67159. }

FUEL IN TANKS. NO 1 6,200. NO 2 4,600 TOTAL 10,800.

D. HILL M. PRICE R. B. PRITCHARD 00.00.
CARS FUELLED ETC.

51187.	51198.	53938.	51200.	51184.
54332	54337.	54411	54359.	54342.
53316.	53325.			
53334.	53306.			

LOCO'S FUELLED ETC:-
47334 (\$) 25059 (\$)

47529. CALL TO STATION. DR REPORTED BLUE FAULT
LIGHT BRIGHT. @ TIMES. FOUND STARTY FAULT
FLAG RESET. + TESTED.

51187. DR REPORTED NO 2 ENGINE SHORT OF WATER. RAD
TOPPED UP + TESTED FOR LEAKS. HOSE PIPE
BURST NEW PIPE FITTED + TESTED.

54411 PLAT BATT'S PUT ON CHARGE ETC.

51198. NO 1 ENGINE EXHAUSTOR + ALTERNATOR BELTS MISSING ALSO.
NO 2 ENGINE ALTERNATOR BELTS MISSING - NOW BELTS
FITTED + ADJUSTED.

B.A. ROBERTS. P. COX. M. PRICE.

CARS FUELLED ETC. 53733 51194

59054 54346

53694

LOCO'S FUELLED ETC. 45118 (S) 25226 (S)

CAME OUT TO BANGOR - ETR NOT WORKING ON 45143
AFTER RUNNING AROUND. TRAIN OVR TRIPPED RESET
& TESTED.

53306 CAME OUT WHANDUWANO L-H HEATER NOT WORKING
NEW GLOW PLUG = 25 AMP FUSE RENEWED
IN HEATER CONTROL PANEL.

47409 CAME OUT DR REPORTED HEADER TANK LOW
HEADER TOPPED UP @ BANGOR. EXAMINED
FOR LEAKS NONE FOUND. LOCO WORKED
FORWARD.

51184 PAUK? FINDING AFTER FIRE ON TOP OF NO2
ENG. TRACED TO COMPRESSOR FREE AIR PIPE
BURST & BURNT. AIR PIPES & NONRETURN
VALVE REMOVED CLEANED OF CARBON
BUILD UP. NEW PIPES & NONRETURN VALVE
FITTED. ENG RUN UP TESTED.

Wed. 2nd JAN 83

	P/CAR NO	MILEAGE.
	51194	N/F
	51187.	"
	53316	"
	53334.	"
	51203.	"
	53306.	"
	53325	"
	51184.	"
	53938.	"
	53733.	"
R/T 65727	53694	"
" 67159		

FUEL TANKS N°1 6,200. N°2 4,000. TOTAL 10,200.

D. HILL. M. PRICE. R. E. PRITCHARD 0000.

CARS FUELLED ETC:-

51194. 51187. 51203. 51184. 53938.
 54346. 54332. 54339. 54342. 54411
 53316. 53306. 53733/59054/53694.
 53334. 53325.

LOCO'S FUELLED ETC:-

47334. (R). 25059 (S). 47352. (R).

51203 CALL TO STATION. DR REPORTED, N°1 ENGINES CUTTING OUT. FOUND LUB OIL LOW ALSO SHORT OF WATER. CAR TAKEN OUT OF SERVICE.

47352 DR REPORTED OIL LIGHT BRIGHT ALSO WATER. BOTH PLUGS RESET. LOCO CHARGED FOR LUB OIL & COOLANT.

53306 WATER MADE TO WORK.

51184. " " " " N°6 PUSHS BLOWN. NOW PUSHS FITTED & TESTED.

59054. PLAT BATT'S PUT ON CHARGE ETC:-

53694. WINDSCREEN WIPER UNCOUPLED REPAIRED & TESTED

51203. BOTH ENGINES LUB OIL & COOLANT TOPPED UP. BOTH ENGINES RUN UP & TESTED. N°1 ENGINE THROTTLE ADJUSTED

51194. N°1 ENGINES AX THROTTLE & ALTERNATOR BOTH OFF. PULLEY BOLTS REPLACED & ADJUSTED

B.A. ROBERTS, P. COX, M. PRICE.

51200 57202 57199.
CAMS FUELLED ETC. 54359 54349. 54334.

47015 (S) 25226.
CAMS FUELLED ETC.

47421 CAMM OUT STATION, N^o 1 ENG DR SIDE W/WIPER
NOT WORKING. WIPER ARM LOOSE ON SPINDLE
REFITTED - ADJUSTED.

54339. CAMM OUT STATION DR REPAIRED L.H. HEATER
NOT WORKING. THERMOSTAT STUCK. RELEASED
& HEATER MADE TO WORK.

51202. N^o 1 ENG THROTTLE MOTOR STICKING. MOTOR
STRIPPED - CLEANED - REASSEMBLED. REPAIRED
& TESTED.

47015. N^o 1 ENG DR SIDE DROP WINDOW X SPRING BROKEN.
PANELS ETC REMOVED FOR ACCESS. NEW SPRING
FITTED.

54359. FRAT BATTERIES PUT ON CHARGE. CIRC TESTED
N^o 3 DYNATO FIELD FUSE RENEWED.

25226 SANDERS MADE TO WORK

51200 N^o 2 ENG EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED.

THURSDAY. 3RD JAN 85.

	P/CAR NO	MILEAGE
	53938.	N/F
	51200.	"
	53316.	"
	53334.	"
	51202.	"
	53325.	"
	53306.	"
	51199.	"
	53702.	—
	53664.	—
	53733.	—
	53694.	—
R/T. 65727	} M/T	
" 67159		

PULLINTANKS NO1 6,400 NO2 2,900 TOTAL 9,300.

J. HILL. M. PRICE. R.E. PRITCHARD.

CARS ROLLLED ETC:-

53938. 51200 51202. 51199. 53316.
 54411. 54359. 54349. 54334. 53334.

53325. 53702/59206/53664. 53733/59054/5394.
 53306.

LOCO'S ROLLLED ETC:-

47334. (S).

51190 CALL TO STATION. DR REPORTED. BUZZER IN
 CARS NOT WORKING. ADJUSTED & TESTED.

53316. R.H. HEATER MADE TO WORK. GLOW PLUG CLEARED.

53733. " " " " " " " "

59054. HEATERS NOT WORKING. BATTERIES LOW PUT ON
 CHARGE

59206. HEATERS MADE TO WORK. GLOW PLUGS CLEARED.

25042. CALL TO RHYL. LOCO FAILED ENGINE START DOWN.
 EXAM & FOUND NO LUB OIL LOCO HEALED
 TO SHED. FOR REPAIRS. TOP'S INVOLVED

47352. CALL TO YARD ENGINES WILL NOT START.

EXAM ENGINES RUN. BUT WITHIN START BUTTON
 IS RELEASED ENGINES WILL START-DOWN STOPPED
 PAIR OIL & WATER OK. STOP BUTTONS EXAM ALSO
 STOP RELAY, FOUND OK..

B. A. ROBERTS. P. COX. M. PRICE.

CARS FUELLED ETC. 57177 57190 53709
54351 54353 59297
57194.

LOCOS FUELLED ETC. 47352 (S) 25226 (S)
25042 (S) 47294 (S) 25792 A EX.

25042. SUMP OIL FILLING AFTER LOCO FAILURE. ENG
RUN UP TESTED. 3. ROCKER COVER JOINTS LEAKAGE
ENG BLOCK - ENG ROOM CLEANING UP.

47352 REPAIRS & FAULT FINDING AFTER FAILURE.
FRAT BATTERIES PUT ON CHARGE - ALL CELLS
FILLED.

25792 A. EXAMINATION CARRIED OUT. BALANCE BLOCKS
REMOVED.

54351 CALL OUT STATION. T/TONE HORN NOT WORKING
BOTH HORNS ADJUSTED.

53709 FRAT BATTERIES PUT ON CHARGE. CIRC TESTED
BOTH ALTERNATOR BELTS LOOSE. BOTH SETS
OF BELTS ADJUSTED.