

TUES. 29/1/85

	P/CAR	MILEAGE.
	53722	NI
	53672	"
	53729	"
	53660	"
	53333	"
	53313	"
	53208	"
	51947	"
	52062	"
	51178	"
	51196	"
R.T. 65724 M.T.		

FUEL IN TANKS NO 1 4.700 NO 2 7.000 TOTAL 11.700

B.A. ROBERTS. M. PRICE.

53208 51196 51178 51947
 CARS FUELLED ETC. 54060 54336 54335 52062
 53333 53729 53722
 59116 59070 59523
 53313 53666 53672

LOCOS FUELLED ETC. 47340 (S) 25300 (S) 25035 (S)
 25089 (P)

53729. BOTH HEATERS REPAIRED. GLOW PLUGS REMOVED
 SERVICED & REPAIRED. ALSO FINE BATTERIES
 PUT ON CHARGE CIRCUIT TESTED.

25089. WINDSCREEN WIPER MOTOR DEFECTIVE DR SIDE
 NO 2 END. W/N MOTORS REVERSED FROM 2ND
 MAN SIDE TO DR SIDE.

53208. UNIT VERY SLOW IN CREATING AIR PRESSURE
 EXAMINED. NO 2 ENG FLEX AIR PIPE BURNT. NEW
 FLEX PIPE FITTED. ALSO NON RETURN VALVE REMOVED
 STRIPPED & CLEANED OF CARBON. REPAIRED
 & TESTED.

TUE 29-1-85

CAROLINE R. E. PRITCHARD

CARS RICE OIL WATER COCOA ETC

51177 - 51906

54351 54489

(P)

(P)

Loco's 47321 - 25191

D. Hill. P. Cox

CARS PULLED ETC:-

51174.

51577/59532/51586.

54333

Loco's PULLED ETC:-

25262. (S).

51174. NO2 ENGINE EXHAUST MANIFOLD JOINTS.
BLOWING NOW JOINTS FITTED + TESTED.

51586. NO2 ENGINE THROTTLE STICKING MOTOR.
STRIPPED WASD REPLACED + TESTED.

59532. FLAT BATTERY W/ PUT ON CHARGE CIRCUIT CHECKED.

45114. CALL TO STATION. DR REPORTED WINDSCREEN
WIPER NOT WORKING NO2 W/ND FOUND WIPER
ARM BROKEN. UNABLE TO REPAIR LOW FORWARD.

25262 DR REPORTED SANDERS NOT WORKING REPAIRED

51181 CALL TO STATION NO1 ENGINE CUTTING OUT LOW IN LBS
OIL SUMP TOPPED UP 2 GAL + TESTED

WEDNESDAY 30-1-85.

	PLCAR	MILES
	53208	NF
	51174	"
	57947	"
	52062	"
	51177	"
	57196	"
	51577	"
	57586	"
	53333	"
	53313	"
R.T. 65724 M.T		
" 67141 FULL.		

FUEL IN TANKS N°1 3.400 N°2 7000 TOTAL 10.400

B.A. ROBELLS. M. PRICE.

53208 51174 51177 57196
 CARS FUELLED ETC: 54060 54333 54351 54336
 57947 53333 51577
 52062 59116 59532
 53313 57586

WHEELS RENEWED ETC: 47340 (F) 25300 (F) 25262 (F)
 47345 (F) 25048 (F)

51577 N°2 ENG EXHAUSTER & ALTERNATOR BELTS
 MISSING NEW BELTS FITTED.

51947 N°2 ENG RAD BOTTOM COOLANT HOSE BURST
 NEW HOSE FITTED.

59116 FNAT MOTORS PUT ON CHARGE CIRCUIT TESTED
 BOTH HEATERS MADE TO WORK.

Wed 30-1-85

CARROLLS REPAIRS.

CARS FUEL ON WATER TRENCH ETC

51181 - 51194
54345 54346

Loco's (S) (F)
25191 - 25300

51177: Arrived out to station down reported NO AIR LIGHT
IN FORWARD FROM PLANT NORTH INTO LEANING TO STATION
SUSPECT FAULT ON MICRO SWITCHES ON PLANT DOWN UNABLE
TO REPAIR IN TIME AT STATION. DRIVES HOME ON BR
FOR THE ATTENTION WAZUL ON PI ROAD. TO THIS FAULT.

51194: Reported vacuum very slow brake test carried out
FOUND EXHAUSTOR BOLTS OFF RILLYS UNIT PUT ON PI ROPS
BOLTS REFITTED AND READJUSTED.

51181 Reported loss of control AIR PRESSURE DOWN TO
FAULT ON FLEXIBLE AND PIPE ON ITEM REPAIRED

S. Hill. P. Cox

CARS FUELLED ETC.-

51203.

54339.

53450/54256/53428.

47454. OUT OF COURSE. DR BROUGHT LOCO ON SITE.
NO FUEL IN TANK. 2018 BATTERS. PUT IN TANK
LOCO WORKING BANDOR/YORK. DELAY UNKNOWN.

53450. NO1 ENGINE EXHAUSTOR BOLTS MISSING NOW
BOLTS FITTED & ADJUSTED.

54256. DYNAMO BOLT OFF REPLACED. PUT ON
CIRCUIT CHECKED

53428. 3 CAR SET. DR REPORTED SET VERY WORK.
TO WORK BACK TO MANCHESTER. FOR REPAIR.

51203. NO2 ENGINE ALTERNATOR BOLTS MISSING
FOUND ALTERNATOR SETTED R.H.D.

54336. CALL TO STATION NO TRAIN LIGHTS NO4 FUS
BLOWN NOW FUSE FITTED & TESTED

53625. CALL TO STATION R.H. TAIL LAMP NOT WORKING.
NEW BULB FITTED & TESTED.

47340 "A" STAM CARRIED OUT

THURS. 31-1-85.

	PLCAR	MILES
	51181	NF
	53450	u
	53428	v
	51177	u
	51203	v
	51196	u
	51947	u
	52062	u
	53729	u
	53660	u

R.T. N^o 65724 M.T.
 u u 67141 FULL.

FUEL IN TANKS N^o1 1.900 N^o2 7000 TOTAL 8.900

B.A. ROBERTS. M. PRICE.

	51181	51177	51196	51203
CARS FUELLED ETC:	54345	54351	54336	54369
	51947	53450	53729	
	52062	59256	59070	
	53428	53660		

LOCOMOTIVES FUELLED ETC: 47340 (S) 25191 (F) 25307 (F)

25191 SANDERS NOT WORKING. MADE TO WORK.

53428 DR REPORTED PANEL LIGHTS NOT WORKING SWITCH DEFECTIVE. NEW SWITCH FITTED.

59070 FLAT BATTERS PUT ON CHARGE CIRC TESTED ALL CELLS TOPPED UP. ALSO REPAIRS TO BOILER HEATERS BLOW PLUGS REMOVED & SERVICED W.H. HEATER FUEL PIPE REPAIRED.

THUR 31-1-85

ATTENDANCE RE PRITCHARD.

Dmv's Fuel Ins

53927 - 51203 - 53628
54214 54339 54213

54339 ATTENTION TO SHUTDOWNS MADE TO WORK BY
UNORTHODOX METHODS TO PREVENT
Loco's Fuel Ins 47064

53927 } ATTENTION TO SHUTDOWNS MADE TO WORK BY
* 54214 } UNORTHODOX METHODS TO FILL THEM UP. ALSO T/UNT FUEL
BAIT PUT ON GRABCO ETC.

ASSISTING P.M. HIGGS WITH BRAKE TEST ON CRANE

D. HILL P. COX.
CAR'S ROLLED ETC.

51174. 53739. 53735.
54332 59261 59528.
53695. 53680.

Loco's ROLLED ETC. 25298. (S)

53680. NO. 1 ENG. ALTERNATOR BOLTS OFF REPLACED. - ADJUSTED

46103 CALL TO STATION DR REPORTED WINDSCREEN WIPER
NOT WORKING DR'S SIDE NO. 2 WIPER REPAIRED & TESTED

47470 CALL TO STATION DR REPORTED COOLANT LOW.
BETWEEN 1/2 & 1/4. ALSO SURE TANK LOW BOTH
TOPPED UP & TESTED. REPAIRS CARRIED OUT
@ BANGOR TO SAVE DELAY.

53739. ALL ALTERNATOR BOLTS MISSING & PLAT BATT'S.
59261. OK.

53695. ALTERNATOR BOLTS MISSING NO. 2 ENGINE ALSO
EXHAUST'S FLUX PIPE BROKEN. NO. 1 ENGINE CAR
STOPPED FOR REPAIRS. NEW EXHAUST PIPE ORDERED
FROM CHETTER ON 07.05 X CHETTER.

51187. CALL TO STATION NO. 2 ENGINE CUTTING OUT LOW
IN COOLANT RAD TOPPED UP & TESTED.

53735. NO. 1 ENGINE EXHAUSTOR & ALTERNATOR BOLTS OFF
PULLY ALL BOLTS REPLACED & ADJUSTED

FRI 1-2-85

	PLCAR	MILES
	53739	NF
	53695	"
	53735	"
	53680	"
	53729	"
	53660	"
	51947	"
	52062	"
	51181	"
	51174	"
	53625	"
	51203	"
R.T. 65724 M.T.		
" 67141 FULL.		

FUEL IN TANKS NO 1 800 NO 2 7000 TOTAL 7.800

B.A. ROBERTS. M. PRICE.

51181 51174 51203 53625
 CARS FUELLED ETC: 54345 54333 54339 54213
 51947 53729 53735
 52062 59070 59528
 53660 53680

LOCOS FUELLED ETC: 47340 (F) 25307 (S) 25191 (S)
 25072 (F)

25072 NO 1 CYL MANIFOLD JOINTS BLOWING & NEW JOINTS FITTED.

53660 NO AIR & AXLE MIGHT IN FORWARD GEAR FAULT TRACED TO STICKING AIR PRESSURE SWITCH. SWITCH STRIPPED & CLEANED EASIER TEST.

25307 NO 2 END DR SIDE HORN VALVE STICKING VALVE REMOVED STRIPPED & VALVE SEATINGS CLEANED OF SCALE REBUILT & REPLACED & TESTED.

54213 TRAIN LIGHTS DEFECTIVE WILL NOT REMAIN ON FAULT TRACED TO OFF RELAY STUCK. RELAY CLEANED & TESTED.

FRI 1-2-85

WFOULKES R. R. PRITCHARD.

CHAS FUEL ON WATER ETC.

53203 - 51178

54080 54335

*53739 FRI BATT PUT ON CHARGE NEW ALTERNATOR BOLTS FITTED ON NO 1 AND NO 2 ENGINE ALSO EXHAUSTOR BOLTS FITTED ON NO 2 ENGINE AND AN READJUSTED.

*53695 FRI BATT PUT ON CHARGE NO 2 ENGINE ALTERNATOR AND EXHAUSTOR BOLTS MISSING AND NEW BOLTS FITTED ALSO HOFF MOLLING IMC AIRWINDERS AND BROKERT FLEXABLE EXHAUST ARE REMOVED AND NEW PIPE FITTED ON NO 1 ENGINE.

Locos Fuel for 25298-25268-47303-25072

25072 A EXAM COMPLETED AND BRAKE ADJUSTED READJUSTED AND 30 GALLONS SUMP OIL PUT IN 269328 MILES

47303 LOCO TO WORK THE WEEK END THEN WANT AN A EXAM AND BRAKE BLOCKS TO CHANGE 50 BRAKE BLOCKS ORDERED FROM HOLYHEADS FOR SAT OR SUN. CONTROL IMPROVED

D. HILL P. COF.

CARS PULLED ETC:

51194.

51198.

51187.

53938.

54346.

54335.

54332.

54411

51582/59108/ 51573.

Loco's PULLED ETC:-

25279 (S).

51186 CALL TO STATION. NO 2 ENGINE SHORT OF WATER RAD TOPPED UP & TESTED.

51582. NO 2 ENG THROTTLE STICKING MOTOR REASD. TESTED

51573 NO 2 ENG EXHAUST MANIFOLD JOINTS BLOWING AND JOINTS FITTED & TESTED.

54346. MOTORS NOT WORKING. BATTERIES LOW PUT ON CHARGE TESTED. L.H. BLOW PUG CHANGED.

53938. NO 1 ENGINE EXHAUSTOR & ALTERNATOR BOLTS WERE PULLED REPLACED & ADJUSTED.

SAT 2-2-85

	PICAR	MILEAGE
	53660	NF
	53729	"
	53739	"
	53695	"
	51582	"
	51573	"
	51203	"
	51194	"
	51174	"
	51178	"
	51947	"
	52062	"
	51181	"
	53938	"
R.T. 65724	M.T.	
" 67141	FULL.	

FUEL IN TANKS N^o1 800 N^o2 5.900 TOTAL 6.700

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51203 51194 51174 51178
 54339 54346 54333 54335
 51947 51181 53938 53660 53739 51582
 52062 54332 54411 59070 59261 59108
 53729 53695 51573

LOCOMOTIVES FUELLED ETC.

CAME TO STATION. 47490 LOSS OF POWER. UNABLE TO FIND FAULT. 47303. COUPLED IN TANDEM TO HOLYHEAD. DELAY UNKNOWN.

51582 N^o1 ENG THROTTLE STICKING ON FULL REVS. THROTTLE MOTOR STRIPPED CLEANED & EASED. GREASED.

59108 FLAT BATTERIES PUT ON CHARGE CUK TESTED N^o4 DYNAMO TUBE RENEWED ALSO AIR CILNS TOPPED UP.

D. Hill P. Cox

CAR'S FUZZLED ETC: -

51186 51201 53933
54357 54347 51566

Loco's FUZZLED ETC: -

25298 (S) 47352 (S) 25191 (F) 25279 (F)

54305. CALL TO STATION. WHISTLES NOT WORKING NO.6
PUS BLOWN. NOW PUS FTTD + TESTED
REPAIRS CARRIED OUT @ LLANDUDNO

47303 Aⁿ AXAM CARRIED OUT. ALSO BRAKE BLOCKS
CHANGED + ① BRAKE SLACK ADJUSTOR. SEIZED
REMOVED REPAIRED ON BENCH REPLACED + ADJUSTED

25191. Aⁿ AXAM CARRIED OUT.

SUNDAY 3-2-85

PICAR	MINES.
51194	
51201	
51184	
51178	
51947	
52062	
53933	
51566	
53729	
53660	
51582	
51573	

B. A. ROBERTS. M. PRICE.

51194 51186 51201 51178
CANS TURNED ETC. 54346 54357 54347 54335
51947 53933 53729 51582
52062 51566 59070 59109
53660 51573.

WOLDS TURNED ETC.

51201 NO 1 ENG EXHAUSTEN - ALTERNATOR BELLS
MISSING NEW BELLS FITTED.

51582 NO 1 ENG EXHAUST PIPE BKT BROKEN. BKT
REMOVED REPAIRED - RETIRED.

51186 L.H. HEATER NOT WORKING. THERMOSTAT IN HEATER
STICKING ON COLD AIR. THERMO REMOVED
REPAIRED - REPAIRED - TESTED.

59070 FRONT BATTERIES PUT ON CHARGE ALL TESTED
NO 9 BATTERY FUSE RENEWED

52062 NO 1 ENG FAN BELLS MISSING NEW BELLS FITTED

51194 DR SIDE WIPER ARM & BLADE BROKEN. NEW
ARM & BLADE FITTED.

Monday, 4th FEB 85.

P/CAR NO MILEAGE

53729

53660

51181

R/T. 67141 Full.
" 65724 M/T

Fuel in Tanks No 1 800 No 2 4,600 TOTAL. 5,400

D. Hill. P. Cox.

CAR'S ROLLING ETC:-

51947. 53933 51178 51201 51181

52062. 51566. 54335. 54347. 54345

51190 51582/59109/51573 53729/59070/53660.
54353

Loco's ROLLING ETC:-

25298 (F) 25279 (S). 25200 (E)

51181. Adjustments made to work. L.H. Glow Plug R.H. Fuel
PIPE REPAIRED.

25279. EXHAUST PIPE JOINT ON TURBO CHARGER BLOWING
NEW JOINT & BOLTS FITTED & TESTED.

A.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51196 53203
54336 54060

LOCOS FUELLED ETC: 47303 (S) 47352 (F)

47352 NO 1 END DR SIDE DROT LIGHT CAB WINDOW
X SPRING DEFECTIVE. PANELS REMOVED FOR ACCESS
X SPRING REPAIRED PANELS REPLACED.

47447 CALLED TO STATION DR REPORTED BLOW FAULT
NIGHT BRIGHT. F.F. RENAY OIL PRESSURE RELAY
TRIPPED. RESET & TESTED.

51947 CALLED TO W. ANDUENO HEATER NOT WORKING NO 6
FUSE BROWN NEW FUSE FITTED.

47429 CALLED TO STATION DR REPORTED SINK OIL LOW
SINK TOPPED UP 2 CARS. TESTED.

51196 NO 2 END EXHAUST MANIFOLD JOINTS BLOWING & STUDS
MISSING. NEW JOINTS & STUDS FITTED.

4 CARRIAGES REPAIRING

51177 CALLED OUT TO STATION DRIVER REPORTED MAX SPEED
COMPRI FOUND GEAR SLIP IN 2 3 AND 4TH GEAR ON NO 2
BLOWIE BLOWIE AND KINNE DOME ISOLATED BOX TOGGLED
UP BUT STILL SLIPS UNIT TAKEN OUT OF SERVICE PROBABLY
CHECKED ON SYSTEM IN INSIDE GEAR BOX.

UNITS FUEL OIL WATER CHECK ETC.

51190 - 51186 - 51178 - 51177 - 53203

54353 54357 54335 54351 54080

53933 - 51947

51866 52062

53320 CALLED OUT TO STATION MAXON HIGH BOLD FITTED.
51186 ALTERNATION BELTS OF PULVEYS REFITTED.

TUESDAY, 5TH FEB 85.

	P/CAR NO	
	51190	R/F
	51186	"
	51178	"
	51177	"
	53203	"
	53933	"
	51566	"
	51947	"
	52062	"
	53729	"
	53660	"
	53739	—
	53695	—
R/T. 67141 Full		
" 65724 m/r.		

FUEL IN TANKS. NO 1 800 NO 2 3,300. TOTAL 4,100.

D. HILL. P. COX.

CARS FUELLED ETC:-

51186	51190	51178	51177	53203
54357	54357	54335	54351	54080
53933	51947	53729	53739	
51566	52062	59070	59261	
		53660	53695	

LOCO'S FUELLED ETC:-

25200 (S) 47352 (S) 25213 (F)

54335. HEATERS MADE TO WORK R.H. NEW GLOW PLUG FITTED.
L.H. PULVE VALVE DEFECTIVE NO FUEL TO HEATER.

53739 } SET STOPPED. FLAT BATTERIES 53739 & 59261.
59261 } NO WATER IN CELLS. ALSO ALTERNATOR BOLTS OFF
53695 } 53739. REPLACED & ADJUSTED.

25226 CALL TO STATION DR REPORTED. ENGINE KEEPS SHUTTING
DOWN EXAM & FOUND NO LUB OIL LOCO BROUGHT
ON SITE SUMP TOPPED UP. 45 CALLS RUN UP & TOPPED

51190. HEATERS MADE TO WORK

53660. AIR LEAK NO 1 F/DR. FLEX PIPE HOLDS. NEW PIPE
FITTED & TESTED. ALSO REPAIRS TO AIR &
AXLE LIGHT.

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC. 51187 53320
54332 53237

LOCOS FUELLED ETC. 25226 (S) 25254 (S) 47303 (F)
25791 (F) 47600 (OC)

51186 CAME OUT MANDUDNO T/TONE HORNS NOT WORKING
BOTH HORNS ADJUSTED - TESTED.

51947 CAME OUT N^o 2 ENG RACING IN ALL GEARS. EXAM
FOUND F/DRIVE NOT ENGAGING. SUSPECT SLIDING
DOG DEFECTIVE ENG - F/DRIVE ISOLATED.

47600 OUT OF COURSE ATTENTION. LOCO BROUGHT ON
DEPOT BY DR. NOW IN FUEL OIL - COOLANT.
BOTH FINNED.

25254 AM BARRIE SMACK ADJUSTERS ADJUSTED
TO PISTON STROKE OF 1 1/4" DR REPORTED POOR
BARRIE ON LOCO. BARRIE TESTED. OK.

53739 FLAT BATTERIES. PUT ON CHARGE CIRC TESTED ALL
CELLS FINNED. ALSO EXAM OF N^o 1 ENG FLYWHEEL
OVERHEATING. CAUSED BY GEARBOX SEIZED. ENG
- F/DRIVE ISOLATED, TEMP DEPAIRS TO FLEX AIR
PIPE ON N^o 1 F/DRIVE. UNIT TO WORK BACK TO
HOME DEPOT FOR REPAIRS.

59261 FLAT BATTERIES PUT ON CHARGE. CIRC TESTED
ALL CELLS DRY. CELLS FINNED.

MAPOLKES RE PRITCHARD.

CARS FUEL OIL WATER CHECK ETC

51196 - 51947 - 51190 - 53933 - 53237

54336 52062^{H₂}₁₅₀ 54353 51566 53320

53695 - 59261 - 53739

51201 CAME ON TO STATION REPAIRED Buzzer in CARS NOT
WORKING MADE TO WORK.

52062 FLAT BATT DUE TO REGIME ISOLATED PUT ON CHARGE

WED. 6th FEB 85.

	P/CAR NO	MILEAGE
	51196.	N/E
	51947.	"
	52062.	"
	51190.	"
	53695.	"
	53739.	"
	53933.	"
	51566.	"
	53237.	"
	53320.	"
R/T. 67141 Full	51186.	"
" 65724 M/T	53729.	"
" 67510 "	53660.	"

PAULIN TANKS. N°1 6,500 N°2 4,900 TOTAL 11,400

D. Hill. P. Cox

CARS PAULINED ETC:-

51196 51190 51186 53237 53933
54336 54353 54357 53320 51566

51947. 53695. 53729.

52062. 59261 59070

53739. 53660.

LOCO'S PAULINED ETC:-

25307. (S) 47352 (F) 25300 (F)

25307. DR ROBERTED HORN STACK. N°2 END. DR SIDE VALVE REMOVED CLEANED REPLACED & TESTED

53660. L.H. HEATER MADE TO WORK NEW PLUG FITTED

59070 R.H. " " " " " " " "

51196. N°2 ENGINES EXHAUST MANIFOLD JOINTS BLOWING. NEW JOINTS FITTED & TESTED

B.A. ROBERTS . M. PRICE.

CARS FUELLED ETC. 51201 53938
54347 54411

LOCOS FUELLED ETC. 25226(F) 25296(F) 47303(S)
25300 A-EXAM.

25300 A-EXAM COMPLETED. ALSO SANDERS MADE TO
WORK. ① BRAKE SHACK ADJUSTER SEIZED REMOVED &
REFIT.

54411 HEATER NOT WORKING. GLOW PLUG REMOVED & CLEANED
ALSO FUEL PIPE TO FUNTEL BOWL REPAIRED.

X CARPENTERS R. E. PRITCHARD.

CARS FUEL OIL WATER ETC.

51197 ✓ - 53237 - 51186 - 53933 - 51192

54361 53320 54357 51566 54354 ✓

53682-59105-53726 ✓ - 53660-59070-53729

51186 CAME OUT TO STATION WENT INTO LAMBUDMO STATION.
DENVER REPAIRED TO HEAT FOUND HEATER GASES OUT OF
CONNECTIONS REPAIRED AND HEATERS MADE TO WORK.

51197 REPAIRED AIR MOTORS NOT WORKING MADE TO WORK ALSO
BULLER IN VAN NOT WORKING MADE TO WORK. ETC.

51201 CONTROL REPAIRED UNIT PAILED AT HOLYWELL

THURSDAY 7TH FEB 85.

	P/CAR NO
	53933.
	51566.
	51192.
	53660
	53729
	53237.
	53320.
	53682.
	53726.
	51197.
R/T. 67141 FULL	51186.

FUEL IN TANKS. NO 1 5,000 NO 2 5,000 TOTAL 10,000.

D. HILL. P. COX.

CARS FUELLED ETC:-

51192. 51197 51186 53237
54354. 54361 54357. 53320.

53933. 53660. 53682.
51566. 59070. 59105.
 53729. 53726.

LOCO'S FUELLED ETC:-

25300 (F) 25202 (S)

53682. NO 2 KNIBING EXHAUSTOR + ALTERNATOR BOLTS
MISSING NEW BOLTS FITTED + ADJUSTED.

25202. SANDERS MADE TO WORK BOTH BOGIES.

59105 HEATERS NOT WORKING NO 6 FUSE BLOWN NEW
FUSE FITTED + TESTED.

B. A. ROBERTS. M. PRICE.

CARS FUELED ETC. 51196 51920
54336 54504

LOCOS FUELED ETC. 25054 (S) 47303 (F)

47434 CALL OUT STATION. DR REPORTED NO CAB LIGHTS
& L.H. SIDE MARKER LIGHTS NOT WORKING. EXAM
FOUND LCB 2 TRIPPED RESET & TESTED.

47380 EXHAUST MANIFOLD JOINTS BLOWING NO 1 & 2 CYL HEAD
A. BANK. NEW JOINTS FITTED.

47537 OUT OF COURSE ATTENTION. COOLANT LOW. HEADER
COOLANT FILLED UP. & TESTED FOR LEAKS.

54504 R.H. MARKER LIGHT & TAIL LIGHT NOT WORKING
WIRE BROKEN ON SWITCH WIRE REPAIRED & TESTED

54336 FLAT BATTERS PUT ON CHARGE CIRK TESTED. NO 9
DYNAMO FUSE BLOWN NEW FUSE FITTED &
REPAIRS TO BOTH HEADERS.

(X) CARRIAGES REPRITCHED

51178 - 51920 - 53237 - 53933 - 51197
54335 54504 53320 51566 54361

53709 - 59297 - 51794 + 51582 - 59108 - 51573

53660 - 59070 - 53729

51566 CAME OUT TO STATION DRIVER REPORTED NO HEAT
IN COACH HEATER MADE TO WORK.

59297 T/WR PUT PU ON CHARGES

51794 ALTERNATOR BELTS OR PULLEYS REFITTED

54361 CAME OUT TO STATION ATTENTION TO TRAY
HEATER WOULD NOT FIRE UP. MADE TO WORK. BZ.

8th FEB 85.

	P/CAR NO	MILES/ABS.
	53237	N/P
	53320	"
	53933	"
	51566	"
	53709	"
	51794	"
	51582	"
	51573	"
	53660	"
	53729	"
	51197	"
	51178	"
R/T 67141 Pull	51920	"

PULL IN TANKS. NO 1 3,700 NO 2 5,000 TOTAL 8,700.

D. Hill. P. Cox.

51197. 51178. 51920 53237 53933
54361 54335. 54504. 53320 51566

53709. 51582. 53660
59297. 59108. 59070
51794. 51573 53729.

Loco's PULLED UTL:- 47229 (S)
25300 (F) 25202 (F) 25302 (F)

34504. WINDSCREEN. WIPER ARM UNCOUPLED. REPAIRED.
REPLACED. ADJUSTED + TESTED.

51794. NO 1 ENGINE & F/DR ISOLATED. STARTER MOTOR
DEFECTIVE. R.H.D.

59108. FLAT BATTERIES. PUT ON CHARGE. CIRCUIT CHECKED.

51573. NO 2 ENGINE THROTTLES STICKING. MOTOR
STRIPPED & OILED. + TESTED.

B.A. ROBERTS - M. PRICE.

CARS FUELLED ETC. 51200 51192
54359 54354

LOCOS FUELLED ETC. 47303 (5) 47229 A-EXAM

51566 CAME OUT STATION. HEATER NOT WORKING
NEW GLOW PLUG FITTED - FUEL SYSTEM BLED.

54335 } CALLED TO LLANDUDNO BOTH HEATERS NOT
51178 } WORKING ON T/CAR. UNIT TAKEN OUT OF
SERVICE. FLAT BATTERS. PUT ON CHARGE
CIRCUIT TESTED. BOTH HEATERS REPAIRED ALSO
BOTH HORNS ON P/CAR MADE TO WORK.

51192. NO 2 ENG EXHAUSTER - ALTERNATOR BELTS
MISSING NEW BELTS FITTED.

47229 A-EXAM COMPLETED.

CARBOURNE & R. PRITCHARD.

47303 CAME OUT TO YARD DOWN REPORTED CARS HEATERS
NOT WORKING FROM NO 1 ENG CONTROL RISE FOUND BLOWN
RESINUED CIRC REVISITED ONE HEATER UNIT IN CARS RAILWAY

51192 CAME OUT TO STATION DOWN REPORTED UNABLE TO
START NO 2 ENGINE FOUND SEIZED DUE TO CYCLINDER
HEAD GASKET BLOWN WENT INTO LLANDUDNO 2 TRIPS
ON ONE ENGINE NO 2 R/RM DRIVE ISOLATED AND JACKET
OUT OF SERVICE.

51178 CALLED OUT TO STATION DOWN REPORTED BUZZER
WILL NOT STOP VIBRATING FOUND HEAD SOURCE LIMIT
SWITCH STUCK ON RESET.

CARS FUEL OIL WATER ETC.

51192 - 53237 - 51200 - 53933

54354 53320 54359 51566

51580 + 59586 + 51589 + 53722 + 59523 + 53672

B. Price

SAT. 9TH FEB 85.

P/CAR NO	MILEAGE.
51192.	N/P
53237.	"
53320	"
51580.	"
51589.	"
53933.	"
51566	"
53722.	"
53672.	"
51200.	"
51199.	"
51201	"
51188.	"

PULL IN TANKS NO1 NO2 TOTAL.

D. HILL. P. COX.
CAR'S PULLED ETC:-

51188.	51201	51199.	51200	51192
54348.	54347.	54334	54359.	54354.
53237.	53933.	53722.	51580.	
53320.	51566.	59523.	59586.	
		53672.	51589.	

53722. PLAT BATTERIES. PUT ON CIGARETS CIRC
CHECKED. ETC:-

51188. BAD AIR LEAK IN FORWARD GEAR LEXAM
FOUND F.P. VALVE STUCK REMOVED
STRIPPED CLEANED REPLACED & TESTED

51589 NO2 ENGINES EXHAUST TUB & ALTERNATOR BOLTS
MISSING NOW BOLTS FITTED & ADJUSTED.

SUNDAY 10-2-85

51580	NF
51589	Y
51192	u
51174	u
51188	u
51200	u
53933	u
52566	u
53320	u
53237	u

B.A. ROBERTS, P. COX.

CARS FUELED ETC: 51188 51174 51192
 54348 54333 54354
 51200 53933 53320 51580
 54359 52566 53237 51586
 51589

LOCOS FUELED ETC: 25288 (F) 25202 (F)

51589 FORWARD GEAR AIR PRESSURE SWITCH DEFECTIVE
 NEW SWITCH FITTED. e PANELS REPAIRING.

53672 CAM OUT STATION. NO AIR PRESSURE. AIR SYSTEM
 FROZEN UP. UNIT TAKEN OUT OF SERVICE. STILL
 WORKED FORWARD. ON DEPOT FOR FURTHER APT

53320 CAM OUT STATION NO-1 ENG CUTTING OUT ENROUTE
 EXAMINED - PAN BELTS MISSING NO-1 ENG - FPR
 ISOLATED

54354 PRAT PARTS PUT ON CHARGE, CIRC TESTED
 BOTH HEATER REPAIRED.

MON 11-2-85

CHALLENGES R & RITCHMAN

P/CNR	MILES
53927	N/P
51174	"
51200	"
51203	"
51188	"
53933	"
51566	"
53672	-
53722	-
51580	-
51589	-

Please Note MAIN WATER SUPPLY
PIPE FOR HOSES FROZEN UP AND
HOSE PIPES - ALSO ALL TRAPS INSTALLED
FROZE UP LAST NIGHT.

R.I 67141 FULL

FULL IN TANKS No1 1,500 No2 5,000 TOTAL 6,500

51188 - 53933 - 51200 - 51203

54348 51566 54359 54339

53927 - 51174 51580 53672

54214 54333 59586 - 59523

① ① 51589 53722

HOSES 25302 + 25202 + 25257

D3 ON SLOW AIR SYSTEM FROZEN UP AIR PIPES BETWEEN ^{CONNECT}
POWER CABLE 53722 ON MAINS AND PIPEWORK TO T/CAR FROZEN
ALSO 53672 AND ONLY ONE BLOWING WORKING HO2
STATION MOTOR FAULTY, UNABLE TO ISOLATE HO AIR INT.

51200 Reported Air Hoses Not Working Snow inside Tromper Cusards
and made to work T/Car Heater Pipe Broken. FND.

53933 Attention to Heater made to work (AFTER 2 THINGS)

51566 " " " " " PUT ON CARRAGE

51580 Full BATT PUT ON CARRAGE Attention to Heaters 2 made to work

59586 Full BATT PUT ON CARRAGE only 1 Motor working

B.A. ROBERTS. P. COX.

53947 51177 53203
CARS FUELLED ETC. 54230 54351 54080

LOCOS FUELLED ETC. 47303 (S) 47229 (S)

53672 - 59523 - 53722 AIR SYSTEM FROZEN UP.
DE-FROSTING SAME. UNIT RUN UP TESTED.

25202 CAME TO NEW YARD. DR UNABLE TO
START LOCO. OVERSPEED TRIPPED RESET
& TESTED.

47439 CAME TO LLANDUDNO SEAK OIL TANK NOW
TOPPED UP 2 GALS & TESTED.

53672 } AIR SYSTEM FROZEN UP. FLEX PIPES
59523 } REMOVED. THAWED OUT & AIR SYSTEM
53722 } THAWED OUT. PIPES REPLACED & TESTED.

D. HILL. P. COX ROBRITCHARD.

CARS FUELLED ETC.:

53681/59153/53701 51184/54342

47426. CALL TO STATION. DR REPORTED SEAK
TANK LOW. TOPPED UP & TESTED REPAIR
CARRIED OUT @ BANBOR.

51566 CALL TO STATION HEATER NOT WORKING
REPAIRED @ LLANDUDNO.

53681 NO2 ENGINE EXTRACTOR & ALTERNATOR
BOLTS MISSING NEW BOLTS FITTED & ADJUSTED

59153 DYNAMO BELT OFF PULLEY REPAIRED

51184. NO2 ENGINE THROTTLE STICKING MOTOR
STRIPPED & OILED. TESTED

TUE 12-2-85

P/CHG	MILES
53203	
53927	
51174	
51177	
51184	
53933	
51566	
53701	—
53681	—
53672	—
53722	—

WATER PIPES FOR MINIM LIMELOXOS
 STILL FROZEN UP.
 NO IT WAS ^{BEHIND} NOT PONT HILL
 IT WAS STILL FROZEN AT 0600.
 P.T 67141 FULL ?
NOT M.O. D. HILL

FUEL IN TANKS No1 800 No2 4,400 Total 5,200

CARS RUEL OIL WATER BTC

53203 - 51174 - 51177 - 53927
 54080 54333 54351 54214

51184 - 53933 53701 53672
 54342 51566 59153 + 59523
 53681 53722

Loco's 25202 - 47229 - 47006

53701 : UNABLE TO START RANGES DUE TO RUST BAIT PUT ON
 CHARGE ALSO ATTENTION TO 2 HEADERS 2 MADE TO WORK.

59153 : RUST BAIT PUT ON CHARGE ALSO ATTENTION TO HEADERS
 ONLY ABLE TO GET 1 TO WORK IN RUEL FIREWORK.

51566 : UNABLE TO START RANGES PUT ON CHARGE ATTENTION
 TO HEADERS MADE TO WORK.

53927 } ATTENTION TO HEADERS MADE TO WORK.
 54214 }

B. A. ROBERTS. P. COX

CARS FUELLED ETC: 51179 51191
54358 54340

LOCOS FUELLED ETC: 25057 (F)

25202. DR REPORTED BRAKE PIPE PRESSURE DEFECTIVE NO. 2
END NOT COMING THROUGH SHUT OFF COCK. EXAMINED
FROZEN UP. DEFROSTING SAME & TESTING.

53933 CALL OUT HEATER DEFECTIVE. EXAMINED SUSPECT
FUEL LINES FROZEN. NO FUEL TO HEATER.

51174 CALL OUT W/ANDUINO BUZZER NOT WORKING BUZZER
ADJUSTED IN DR CAB.

53203 } AM HEATERS NOT WORKING. AM FUEL LINES
54080 } FROZEN. DEFROSTING. ALSO NO. 2 GEARBOX NO. 2
BAND SLIPPING. BAND ADJUSTED ALSO WARNING
HORNS MADE TO WORK.

51179. NO. 1 ENG EXHAUSTER & ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

D. HILL. M. PRICIS.

CARS FUELLED ETC. -

51200. 51791 / 59679 / 51786
54359.

LOCOS FUELLED ETC. -

25325. (F)

25057 FAULT FINDING. ALL CONTRACTORS CLEANED. LOCO WANTING TO WORK.

45104 CALL TO STATION. DR REPORTED. BRAKE PIPES
AIR PRESSURE NOT LEAKING OFF PITONS CALL FROM
BANDOR. NO FAULT FOUND. DR REPORTED OK.

(2) SET

51177 NO. 1 ENG EXHAUSTER & ALTERNATOR BOLTS OFF
PULLEY REPLACED & ADJUSTED.

51791 FLAT BATTERIES. PUT ON CHARGES CIRCUIT CHECKED
NO. 1 ENG EXHAUSTER & ALTERNATOR BOLTS MISSING.
NO. 2 " ALTERNATOR BOLTS MISSING. NOW
BOLTS FITTED & ADJUSTED.

51191 CALL TO STATION NO TRAIN LIGHTS NO. 4 KISS
EXAMINED & TESTED.

51786. NO. 2 ENG FUEL SYSTEM AIR LOCKED BLEED & TESTED.

CAROLLES R. B. RICHARDS.

P/CH2	MILES
51200	M.F
51177	"
53933	"
51566	"
51191	"
53203	"
51174	"
53672	—
53722	—
51791	—
51786	—

R.T 67141 Run.

RUE IN TANKS No1 900 No2 3000 TOTAL 3,900

CARS FUEL OIL WATER ETC.

51200 - 51177 - 51191 - 53203
 54359 54351 54340 54080
 51174 - 53933 - 51791 53672
 54333 51566 59679 - 59523
 51786 53722

Loc's (3) (P)
 47229 - 25176

53672 ATTENTION TO 2 HEATERS 2 MADE TO WORK.
 59523 " " " "
 54333 RWT BWT PUT ON CHANGE ALSO 2 HEATERS MADE TO WORK.
 51174 ATTENTION TO 2 HEATERS 2 MADE TO WORK GEAR PULVER CHANGES
 53933! ATTENTION TO HEATER MADE TO WORK. WOULD NOT HOLD IN.
 51566 - ATTENTION TO HEATER MADE TO WORK. " "
 59679 / RWT BWT PUT ON CHANGE ONLY 1 HEATER WORKING

B.A. ROBERTS D. HILL P. COX M. PRICE

CARS ROLLED ETC:-

51911	51189.	51573	51175	51919
54212.	54343.	59108.	54350	54503
		51582.		

51200/54359.

LOCO'S ROLLED ETC:-

25282. (F) 25057 (S)

25057. LOSS OF POWER. FAULT FINDING. STATIC TEST CARRIED OUT ON FIELD DIVORTS. LOCO RUN UP. & TESTED.

25325 "A" EXAM CARRIED OUT ALSO BRAKE BLOCKS CHANGED & ADJUSTED. ONE BRAKE SLACK ADJUSTOR SEIZED. REMOVED. OVERTHAULED ON BENCH REPLACED & ADJUSTED.

25176. "A" EXAM CARRIED OUT.

54212 FLAT BATTERIES. PUT ON CHARGE CIRC CHECKED LIGHTS & HEATER TESTED.

25282. R.H. SETTLING TANK GRAB HOAKING. REMOVED. REPAIRED. REPLACED & TESTED.

54359. CALL TO STATION NO FLAT. FOUND FLAT BATTERY. CAR TAKEN OUT OF SERVICE PUT ON CHARGE.

54350 CALL TO STATION NO TRAIN LIGHTS No 4 FUS BLOWN. NOW FUS FITTED & TESTED

31450. CALL TO STATION PHONE CALL FROM T. C. I. DR REPORTED. BROKEN WIND SCREEN. BRICKS FROM TUNNEL @ BANBOR. STATION. LOCO WORKED FORWARD. TO MANCHESTER

THUR 14-2-85

CARBOURERS REPRITCHERS

	P/CNR	MILES
	51197	H.F.
	51911	"
	51177	"
	51200	"
	51566	"
	53933	"
	51919	"
	51175	"
	51189	"
	51582	—
	51573	—

P.T 67141 Empty
R.T 65536 Full

FUEL IN TANKS No1 5000 No2 51000 TOTAL 10,000

CARS FUEL OIL WATER ETC.

51197 - 51911 - 51177 - 51200
54361 54212 54351 54359 51582
59108
51573

51566 - 51919 - 51175 - 51189
53933 54503 54350 54343

Ⓟ Ⓞ Ⓢ

Loco's 25325, 25176 25048

54359 ATTENTION TO HENTERS ONLY WORKING P.H. SIDE FUEL OIL WATER SUMP ON. F.H. D.V.

54212 P.W. BATT P.O. ON CHARGE ATTENTION TO HENTERS MADE TO WORK

51911: DOWN REPAIRS UNABLE TO START NO 2 LARGEST TRAILING FAULT TO STICKING STARTER MOTOR HOUSING REPAIR ENGINE RUN UP AND HOUSING.

51189 ATTENTION TO 2 HENTERS 2 MADE TO WORK

54343 " " " "

51175 " " " "

54350 " " " "

53933 ATTENTION TO HENTERS MADE TO WORK

51566 FAULT ON HENTERS. P.H. D.V. 59108 ONLY 1 HENTERS WORKING FROM

B. A. ROBERTS. P. COX.

51920 51186
CARS FUELLED ETC: 54504 54357

LOCOS FUELLED ETC: 47229 (F) 25282 (S)

51189 CALLED TO WANDUING T/ONE HORNS NOT WORKING
HORNS CLEARING OF FROZEN SNOW & ICE. TESTED OK

47404 CALLED TO STATION. KFRENAY TRIPPED RESET
& TESTED OK.

25282 SANDERS MADE TO WORK.

D. HILL. M. PRICE.

CARS FUELLED ETC: -

53733/59054/53694 53228/54055

4760P. CALL TO STATION DR REPORTED START FAULT
LIGHT BRIGHT RESET & TESTED

47503 CALL TO STATION. DR REPORTED COOLANT
LOSS FROM WIPES PIPS CLIPS SCREWED
UP. COOLANT EXAM FOUND VERY LOW LOCO
BROUGHT ON SITE OUT OF COURSE COOLANT
TOPPED UP LOCO WORKED FORWARD
WATER PIPES. FROZEN @ BANBOR.

53733. NO 2 ENGINES EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED & TESTED

59054. TRAIN LIGHTS LOW. BATTERIES PUT ON
CHARGE.

54354 CALL TO STATION BUZZER NOT WORKING
ADJUSTED & TESTED

B. A. ROBERTS. P. COX.

51174 53320 51197
CARS PULLED ETC: 54333 53237 54361

LOCOS PULLED ETC: 47219 (S) 47229 A. EXAM.

47425 CAME TO STATION ETH. NOT WORKING. LOCO
EXAMINED ETH WORKING ON LOCO TRAIN @
FAULT. NO TIME TO CHECK TRAIN. CONTROL
INFORMED.

47229 A-EXAMINATION CARRIED OUT.

D. Hill. M. PRICE

CARS PULLED ETC:

51190/54353. 53203/54080. 53927/54214

51203/54339. 51192/54354. 51187/54332.

45115. OUT OF COURSE DR BROUGHT LOCO ON
LOW IN TURN. 1205 LITRES PUT IN ONLY
1/2 PULL. LOCO WORKED FORWARD

54343. CALL TO STATION. GUARD REPORTED TRAIN LIGHTS
NOT WORKING FROM VAN. NEW PUS BLOWN NEW PUS
FITTED & TESTED

51190. NEW ENGINES. THROTTLES STICKING @ TIMES MOTOR
STRIPPED WASHED. & TESTED

54332. TRAIN LIGHTS LOW ALSO INDICATORS. NOT WORKING
BATTERIES. PUT ON CHARGE ETC:-

LOCO'S PULLED ETC: 25278. (F)

SAT 16-2-85

CARBOURNE REPAIRS

	P/MAZ	MILES
	53927	
	51203	
	51197	
	51190	
	53203	
	51919	
	51174	
	53320	
	53237	
	51186	
	51187	
	51192	

FUEL IN TANKS NO1	NO2	TOTAL
-------------------	-----	-------

CARS FUEL OIL WATER ETC.

53927	-	51203	-	51197	-	51190	-	51192
54214		54339		54361		54353		54354
53203	-	51919	-	51174	-	53320		51187
54080		54503		54333		53237		54332

51186
54357

- 51190 ATTENTION TO HEATERS UNABLE TO GET REAR SIDE TO FIRE UP IN HOT WATER.
- 53927 } DOWN REPORTED HEATERS NOT WORKING ONLY 1 HEATER FITTED
- 54214 } FOR CONCERN 2 WORKING BUT POOR HEAT OUTPUT.
- 54339 ATTENTION TO 2 HEATERS MADE TO WORK.
- 53320 ATTENTION TO 2 HEATERS 2 MADE TO WORK.
- 51203 DROVE TO STATION DOWN REPORTED NO 1 ENGINE KNOCKED OFF FOUND TO HAVE AIR LEAK BLEEDING FROST OF AIR
- 51187 GEAR SLIP IN NO 1 ENGINE NO 2 GEAR BOX TOOK UP! (GIR SLIPPING.)

SAT. 16TH FEB 85

D. HILL. M. PRICE.

CARS ROLLLED ETC. -

51189.	53206.	51175.
54343.	54058.	54350

Loco's ROLLLED ETC. -

47229 (F). 25176 (S). 25048 (S) 47292 (S)
25213 (F) 25190 (S)
25268. Aⁿ EXAM CARRIED OUT.

54361. CALL TO STATION BUZZER ADJUSTED + TESTED.

47456 CALL TO STATION EARTH FAULT LIGHT BRIGHT.
RESET - TESTED

SUNDAY 17-2-85

CHROLMES REPRITCHARD.

	P/NO2	MILES
	51919.	
	51175	
	51186	
	53237	
	53320	
	53206	
	51189	
	51197	
	53228	

R.T 65536 Full
R.T 67141 Empty.

FUEL IN TANKS No1 5,700 No2 2000 TOTAL 7,700

CARS FUEL OIL WATER ETC.

51919 - 51175 - 53237 - 51186
54503 54350 53320 54357

53206 - 51189 - 51197 - 53228
54058 54343 54361 54055

③
Loco 25176

53206 :- ATTENTION TO 2 HEATERS MADE TO WORK BY UNORTHODOX METHODS TO FIRE THEM UP ALSO PANEL BOLTS FITTED

54343 :- AS ABOVE BUT PUT ON CHARGE 2 HEATERS MADE TO WORK.

53228 :- FIAT BATT UNABLE TO START ENGINES PUT ON CHARGE ALSO ATTENTION TO 2 HEATERS 2 MADE TO WORK ETC.

51197 ATTENTION TO 2 HEATERS 2 MADE TO WORK ALSO BRASSIER BOLTS OFF FINEYS REFITTED

MON 18. 2. 85

PICAR

51189
53206
53938
\$3728
53691

R.T. 67141 MT
65536 FULL

FUEL IN TANKS N°1 5.700 N°2 1.700 TOTAL 7.400

B.A. ROBERTS M. PRICE.

CARS FUELLED ETC.	51919	51175	53320
	54503	54350	53237
51186	51189	53206	53938
54357	54343	54058	54411
			59583
			53691

WOCOS FUELLED ETC:	⑤ 47224	⑥ 47292	⑦ 25176
	25268(⑦)		

59583 FIAT BATTERIES PUT ON CHARGE CIRCUIT TESTED ALL CELLS TOPPED UP & HEATERS MADE TO WORK.

53938 N°2 ENG EXHAUSTER & ALTERNATOR BELTS MISSING. NEW BELTS FITTED

MON 18-2-85

CARBOURLES REPRITCHED.

CARS FULL OIL WATER ETC

51190 - 51188 - 53203

54353 54348 54080

51190 } UNIT RAN FROM HOLYWOOD DOWN REPORTED HEATERS
54353 } NOT WORKING TAKEN OUT OF SERVICE TRAVELING FOR PAULT
FOUND NO 6 AND NO 4 FUSE BLOWN AN 4 HEATERS MADE
TO WORK.

54348 ATTENTION TO BUYER IN CARS ADVISED TO WORK.

51919 CAME TO STATION NEXT INTO LLANDUDNO ATTENTION
TO HEATER REPORTED KNOCKED OFF MADE TO WORK AIR
LOCK IN PUL LINE BLEEDING REEF OF AIR.

53938 CAME OUT TO STATION DOWN REPORTED HEATER
NOT WORKING ONLY ONE FITTED FOR CONTACT UNABLE
TO GET TO WORK SUSPECT FAULTY RICE VALVE ON
HEATER UNIT F.H.D.A.

47615 DOWN REPORTED MAKE LIGHT BULBS WANTED NEW
LAMP FITTED. IN YARD.

(P) (P) (P)
Loco's fuel hrs 25048 - 25268 - 25190

D. Hill P. Cox.
CARS FULL OIL ETC:-

51194/54346. 53724/59530/53673

47626 CALL TO STATION. DR REPORTED. BLUE PAULT
LIGHT BRIGHT. FOUND COOLANT LOW SYSTEM
TOPPED UP & BANDOR TO STAVS DELAY.
LOCO WORKED FORWARD.

59530 PLAT BATTERY'S PUT ON CHARGE ETC:-

51919. CALL TO LLANDUDNO CAME REPORTED UNABLE
TO PUT TRAIN LIGHTS ON FROM PLAT. FOUND
N4 THERMOSTAT CONTROL FUSE BLOWN NOW FUSE
FITTED & TESTED.

53673 NO 2 OVA IN EXHAUSTOR & ALTERNATOR BOLTS
OFF PULLEY. REPLACED & ADJUSTED

TUE. 19.2 - 85'

	P/CAR	
	53938	NF
	57188	"
	57194	"
	53203	"
	57919	"
	51189	"
	53206	"
	53320	"
	53237	103080
	53724	NF
	53673	"
R.T. 67141 M.T		
" 65536 FULL.		

FUEL IN TANKS N^o1 5.800 N^o2 700 TOTAL 6.500

B. A. ROBERTS. M. PRICE.

53938 57188 51194
 CARS FUELLED ETC. 54411 54348 54346
 53203 53206 51189 57919 53320 53724
 54080 54058 54343 54503 53237 59580
 53673.

LOCOS FUELLED ETC. 25190 (S) 25268 (S) 25048 (S)
 25278 (S) 47229 (F)

53724 BOTH HEATERS REPAIRED N^o6 FUSE BLOWN
 RENEWED - 2 NEW GLOW PLUGS FITTED.

54343 HORN VALVE STUCK; VALVE REMOVED SEATINGS
 CLEARED OF SCALE - AIR PIPES BLOWN OUT

53203 FLAT BATTERS PUT ON CHARGE CUL TESTED

Tue 19-2-85

WABOLUES R B PRITCHARD.

CARS RUN OIL WATER ETC.

51203 - 51193
54339 54356

Loco's Fuel hrs

(P) (S)
47427 - 47006

25268 CAME OUT TO PEN YARD REPORTED OFF ROAD
DE-RAILED FOUND 1 PAIR WHEELS N°2 END HOLYHEAD INFORMED
TO RE RAIL LOCO ETC.

51193 CAME OUT TO STATION DRIVER REPORTED NO
REGIME LIGHTS ON PANEL CIRC REPAIRED.

47490 CAME OUT TO STATION TO CHECK ON FUEL AND HEAD ON.
LOCO BRAKES ON STEEP OUT OF COURSE ATTENTION ALSO
DANGER REPORTED FROM TENDERS SLOW BRAKE PRESSURE FINDA
D. HILL. A. COX.

CARS PULLED ETC:-

53927/54214.

Loco's PULLED ETC
47378 (S)

47470. CALL TO STATION. DR REPORTED WINDSCREEN
WIPER UNCOUPLED N°1 END. ARM REPLACED
ADJUSTED & TESTED.

53927. N°2 ENGINE THROTTLE STICKING MOTOR
STRIPPED & WASHED TESTED

51180 CALL TO STATION. DR REPORTED N°1 ENGINE CUTTING
OUT. RAD TOPPED UP & TESTED.

53927 N°2 ENGINE EXHAUSTOR & ALTERNATOR BELTS
REPLACED & ADJUSTED

47378. EXHAUST PIPE JOINTS ON TURBO CHARGER.
BLOWING JOINTS REPLACED & TESTED

WED. 20-2-85

	PLCAR	MILES
	51193	NF
	51188	"
	53938	"
	53927	"
	51919	"
	51194	"
	51189	"
R.T. 67141 M.T.	53206	"
" 65536 FULL.	53320	NF
67045 -11-	53237	103370

FUEL IN TANKS N^o1 2.800 N^o2 700 TOTAL 3.500.

B. A. ROBERTS. M. PRICE.

51193 51188 53938 53927
 CARS FUELLED ETC. 54356 54345 54411 54214
 53320 51919 51194 51189 53206
 53237 54503 54346 54343 54058

LOCOS FUELLED ETC. 47229 (S) 25145 (S) 25280 (S)
 25072 (F) 25048 (F)

25145. SANDERS NOT WORKING. MADE TO WORK.

54346 BOTH HEATERS REPAIRED. FUSE IN RELAY BOX RENEWED - GLOW PLUGS SERVICED

53938 } ALL HEATERS REPAIRED. FUEL LINES CLEARED
 54411 } OF AIR - ALL GLOW PLUGS SERVICED.

WBS 20-2-85

CAROLINE R. RITCHIE

CARS FUEL OIL WATER ETC

51185 — 51180
54352 54355

Loco's Fuel kes (F) out of course (S)
25282 47615 - 47229

47615 CALLED OUT TO LOCO (STATION) TO CHECK ON FUEL
IN LOCO OUT OF COURSE ATTENTION FUEL TANK
FILLED 1,100 LBS BROWN OIL SHED.

RAIL TANK 67045 UNLOADED.

54355 ATTENTION TO RED MARKER LIGHT CIRC
FAULTY LAMP HOLDER AND LAMP FITTED

51185 } ATTENTION TO HEATERS ARE MADE TO WORK BETT.
54352 }

5119 CALLED OUT TO STATION ATTENTION TO RED MARKER
545034 LIGHT CIRC NEW LAMP FITTED

D. Hill. P. Cox
CARS ROLLING ETC.

51181/54345 53739/59261/53695 51587/59580/51587.

47475 CALL TO STATION IN REPORTED BLUE FAULT LIGHT
BRIGHT. EXAM & FOUND WORTH FAULT. FLAG
RESET & TESTED.

51181. NO 2 ENGINE EXHAUST MANIFOLD JOINTS BLOWING
NOW JOINTS FITTED & TESTED.

53739. NO 2 ENGINE EXHAUSTOR & ALTERNATOR BOLTS
MISSING NOW BOLTS FITTED & ADJUSTED.

59261 PLAT BATTERS PUT ON CHARGE ETC.

51587. NO 6 HIGH PRESSURE FUEL PIPES BROKEN NOW
PIPS FITTED & TESTED.

51193 CALL TO STATION IN REPORTED NO 1 ENGINE
CUTTING OUT RAD. BOARD UP & TESTED.

54346 CALL TO LONDON DNO NO 6 PIPES BLOWN NOW PIPES
FITTED & TESTED.

THURS 21-2-85

	PICAR	MILES
	57919	NF
	57181	"
	57180	"
	57194	"
	57197	"
	53320	"
	53237	103690
	53739	—
	53695	—
R.T. 65536 FULL	51578	—
" 67045 M.T.	57587	—
	57582	—
	57573	—

FUEL IN TANKS NO 1 4.000 NO 2 6.200 TOTAL 10.200

P.A. ROBERTS. M. PRICE: 57919 57181 57180 57194
CANS FUELLED ETC: 54563 54345 54355 54346
57197 53320 53739 57582 57578
54361 53237 59261 59108 59580
53695 57573 57587

Locos FUELLED ETC: 25048 (S) 25268 (S) 25072 (S)
25154 (S)

59108 FNAT BATTERIES PUT ON CHARGE CIRC TESTED
ALL BATT CENS FILLED. NO 9 DYNAMO FULB
RENEWED.

57180 NO 1 ENG FAN BELLS MISSING NEW BELLS FITTED.

