

1 1
Log Book 5/2/86

BR.205/1

WED 5TH FEB 86

D. HILL. M. PRICE.

LOCO'S TRULLED ETC:-

47104 (A). 25181 (S) 47265. (S)

51203. CALL TO STATION. HEATERS NOT WORKING. NO.6
PLUGS BLOWN NOW PLUGS FITTED & TESTED.

51191 CALL TO LLANDUDNO. IN UNABLE TO START NO.2
ENGINE. FOUND STARTER MOTOR ROLLY & STUCK.
RELEASED & TESTED. ¹⁸⁵² ^{THIS}

45101 CALL TO PRESTATYN. LOCO FAILED ENGINE START-DOWN.
WILL NOT RESTART. FOUND NO FUEL IN TANK LOCO
TRULLED TO SITE. FUEL & TOPPED UP & COOLANT
LOCO RUN UP & TESTED OUT OF COURSE

25181. SAND PIPE & START DAMAGED RH SIDE NO.2 ENG. REPAIRED.

B. A. ROBERTS. M. PRICE, R. E. PRITCHARD.

51569

CARS TRULLED ETC: 51203 59207

54339 53432

53318 CALL OUT LLANDUDNO NO.1 ENG WENT START. PLAT
BATT. UNIT TAKEN OUT OF SERVICE.

54339 CALL OUT LLANDUDNO N.H. HEATER NOT WORKING
GLOW PLUG REMOVED. CLEANED REPLACED & TESTED

54342 CALL OUT LLANDUDNO. AIR AXLE LIGHT NOT
WORKING. WIRE BROKEN ON BULB HOLDER
WIRE REPAIRED & TESTED.

51569 NO.1 ENG THROTTLE MOTOR STICKING. MOTOR STRIPPED
& CLEANED & TESTED.

THUR 6-2-86

CATERPILLER REPAIRS

CARS RULZ OIL WATER ETC

51569
59207
53932

53673
59530
53724

51188
54348

51203
54339

53203
54080

51184
54342

51189
54343

51318
53328

(P)

(S)

Locos

25181

25910

53673 : Downer Reported Gear Slip in Mot No 2 between
ON No 2 Gear Box's TOGUE of Still Slip Mechanism
Fault to Faulty Tips on Gear Controller Repaired
Satisfactorily OK in Shed also Fault on Train Light
Circ unable to switch off Train Lights in this coach
only found points of lighting condition always
on on and off missing unable to repair. Fixing
also attention to heaters made to work

53724 ATTENTION TO 2 HEATERS MADE TO WORK
51188 " " "
54348 ATTENTION TO 2 HEATERS MADE TO WORK

51318 R.H Side Faulty Motor Motion Running Very Slow on D.M
also on Bait Charge to Start Ranges ETC.
54339 ATTENTION TO HEATERS MADE TO WORK.

51569 Downer Reported unable to start No 1 loco was found
to have air low in RULZ System bleeding free of Air
and RULZ also attention to heaters made to work.

47532 Called out to station to check on Reported Exhaust Blow of
RULZ in Tanks No 1 400 No 2 41000 Total 5,000
R.T 67156 Full

THURSDAY. 6TH FEB 86.

D. HILL. M. PRICE.

LOCO'S FUELLED ETC.

47194 (S) 47104 (S)

51191 CALL TO STATION. L.H. HEADLAMP NOT WORKING NOW PLUG-
FITTED & TESTED.

51200. CALL TO LLANDUDNO DR REPORTED AIR + AXLE LIGHT NOT
WORKING. PANEL REMOVED FOR ACCESS TO LAMP HOLDER.
FOUND WIRE UNCOUPLED REPLACED & TESTED.

47194 DR REPORTED DROP LIGHT WINDOW NOT OPEN WILL NOT
SHUT. FOUND CLIPS MISSING & SCREWS REPAIRED ETC.

47474. CALL TO STATION. PITONS CALL FROM CONTROL TO
EXAM LOCO + TRAIN. E.T.H. NOT WORKING. LOCO
TESTED @ LLANDUDNO NO FAULT FOUND. TESTED ON
TRAIN. FOUND WORKING. SUSPECT JUMPER CABLE
NO 1 WIRE DEFECTIVE OR JUMPER CABLE ON BRAKE
VAN NO NEX 92254. CONTROL + CREW MAINT
INFORMED.

BA. ROBERTS. M. PRICE. REPRITCHARD

CARS FUELLED ETC. 51175 51190
54350 54353.

LOCOS FUELLED 25181 A-EXAM

54359 CARB CUT MANDUDNO NO 6 FUSE BROWN NEW FUSE
FITTED & TESTED.

25181 NO 1 - 2 CYL MANIFOLD JOINTS BLOWING. NEW JOINTS FITTED
ALSO NO 1 BOGIE L-H LEADING SAND PIPE DAMAGED.
NEW SAND PIPE FITTED. & A-EXAM CARRIERS OUT.

51175 NO 1 ENG RAD FAN MOTOR FOUND UNCOUPLED & HANGING
OFF BED PLATE. MOTOR REMOVED FOR SAFETY. ENG &
FINAL DRIVE VERNATED.

51190 NO 2 ENG - EXHAUSTER - ALTERNATOR BELLS MISSING NEW
BELLS FITTED.

LAPOLKES REPAIRS

CHAS FULL OIL WATER ETC

51175 51190 53203
 54350 54353 54080

51184 51188 51189
 54342 54354 54343

51191 53328 51569-59207-53932
 54340 53318

 (F) (S) (P) (S)
 Low's 47104 25181 25910 47349

- 53328 ATTENTION TO 2 HEATERS 2 MADE TO WORK ETC
- 51318 RIGHT HAND SIDE FAULTY PUC LEFT OUT.
- 51188 NO 2 ENGINE ISOLATED DUE TO BAD AIR LOCK IN FUEL SYSTEM AFTER BLEEDING WOULD NOT REV UP TO FULL REV'S SUSPECT FUEL LIFT PUMP FAULTY.
- 54354 ATTENTION TO HEATERS 2 MADE TO WORK ETC
- 54340 ATTENTION TO HEATERS BLOW FLOOR SERVICE 2 MADE TO WORK
- 54342 DOWN REPORTED HEATERS NOT WORKING FOUND BATT'S LOW PUT ON CHARGE 2 HEATERS MADE TO WORK
- 51569 ATTENTION TO HEATER MADE TO WORK
- 53932 DOWN REPORTED UNABLE TO START NO 2 ENGINE FOUND STARTER MOTOR PUMPER STUCK IN REVERSE RESET KRIBIMES ALL RUN-UP.

FUEL IN TANKS NO 1 5,000 NO 2 7,000 TOTAL 12,000

R.T 67156 Empty

FRIDAY. 7TH FEB 86

D. HILL M. PRICE.

CARS FUELLED ETC:-

51197/54336

LOCO'S FUELLED ETC:-

45102 (S).

25034 (D)

51197 CALL TO LLANDUDNO. DR REPORTED. NO.2 UNDER EXHAUST PIPE BLOWING. SET BROUGHT ON SITE. NEW NUTS & BOLTS FITTED. ALSO HEATERS MADE TO WORK P/CAR & T/CAR. SET RETURNED TO SERVICE.

51203 CALL TO STATION. DR REPORTED WINDSCREEN WIPER UNCOUPLED. ARM REPLACED RESET & TESTED.

45141. CALL TO STATION. T.C.I. REPORTED. E.T.H NOT WORKING. DR REPORTED E.T.H. WORKING. NO FAULT. ON TRAIN. WORKED FORWARD.

B. A. ROBERTS. M. PRICE. R. E. PRITCHARD.

CARS FUELLED ETC:- 51203 51191 51907 51185
54339 54340 54490. 54352.

54339. CALL OUT MAINTAINING L.H. HEATER NOT WORKING. GLEN PLUG REMOVED. CLEANED & REPAIRED & TESTED.

25034 CALL OUT NEW YARD. DR REPORTED BRAKE DRAG ON BOTH BOGIE. EXAMINED AIR SYSTEM BLOWN OUT & LOCO RUN UP & TESTED. FAULT CLEARED.

51562. CALL OUT STATION. BUZZER NOT WORKING IN DRIVING CAB. BUZZER UNIT ADJUSTED & TESTED.

54490 FRAT BATTERIES PUT ON CHARGE CIRC TESTED. NO.9 DYNAMIC FUSE BLOWN. NEW FUSE FITTED ALSO ALL BATT CELLS FILLED.

54340 DYNAMIC BELTS MISSING NEW BELTS FITTED FROM AXLE DRAWN.

SATS - 2 - 86

CAROLINE REPRITCHARD

CARS RIA OIL WATER BR.

51185
54352

51907
54440

51191
54340

51203
54339

53203
54080

51197
54336

53328

53318

51203 ATTENTION TO HOPE PIPEWORK LEAKING RESERVES

54336 PUT SAT PUT ON COURSE BR. CURE CONCERNED.

53318: PUT SAT PUT ON COURSE BR. ALSO ATTENTION TO HERRICK MADE TO WORK.

51197: ATTENTION TO TRAIN LIGHT CURE NO 4 PUSE FOUND BROWN RESERVES CURE

51185: DEMON REPORTED ONLY 40-50 PSI AIR PRESSURE READING FOR AIR LEAK SYSTEM. PARTLY IMMOBILIZED VALVE STICKING. BLAMMED OFF RIGGING SLOW IN MAKING AIR

FULL IN THAMES NO 1 4,300 NO 2 7,000 TOTAL 11,300

NO R.T

B. A. ROBERTS. M. PRICE.

51569

51187

59207

CARS FUELLED ETC.

54332

53932

WAGONS FUELLED ETC. 47104 (S) 45102 (S) 25910 (S)

25205 (F) 47033 (F) 47381 (F)

51187 CAR OUT MAINTENANCE DR REPORTED NO.2 ENG REV
FLUCTUATING. FUEL SYSTEM AIR LOCKED. UNIT
TAKEN OUT OF SERVICE. FUEL SYSTEM BLED +
TESTED ON DEPOT.

53932 CAR OUT MAINTENANCE DR REPORTED HEATER
NOT WORKING. 25 AMP CONTROL PANEL FUSE
BLOWN NEW FUSE FITTED.

47104 NO.1 - 2 B BANK EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED.

Sunday 9-2-86

Caroules Repritchard.

CARS FUEL OIL WATER ETC.

51185	51187	51200
54352	54332	54359

51184	51904	53203
54342	54487	54080

53318 53932 - 59207 - 51569
53328

Loco 5	(E) WASSO 47413	(S) 25910	(F) 25205
--------	--------------------	--------------	--------------

47104 loco stopped suspect engine air valve stopped
on code 141 TFS informed. also TC1

53318 DRAWER UNABLE TO START ENGINES DUE TO RIM
BRAKE PUT ON CHARGE ETC.

53203 DRAWER REPORTED GEAR SLIP IN NO 1 AND 2 GEARS
NO 2 GEAR BOX BOXES TROTTLED UP, BUT STILL
GEAR SLIP IN NO 1 GEAR AND SOMETIMES IN NO 2 GEAR
NO ENGINE ENGINE AND FINAL DRIVE ISOLATED DUE
TO PULLY STARTER MOTOR. TC1 INFORMED

51185 REPORTED LOSS OF AIR TEMP RETAINED LEADING
PAST HOLDING STUDS PAST UNLOADER DUE NO PART
ON TURN TO PULLY REPAIR UNIT OR COUPLED UP.
UNLOADER BLANKED OFF.

51200 ATTENTION TO HEATERS DUE TO WORK ETC.

54359 ATTENTION TO HEATERS DUE TO WORK ETC.

MONDAY 10-2-86

FUEL IN TANKS N^o1 3.100 N^o2 7.000 TOTAL 10.100

R.T. 65709 FULL.

B.A. ROBERTS, M. PRICE.

CARS FUELLED ETC: 53203 51904 51184
54080 54487 54342

53318 53932

53328 59207

57569

LOCOMOTIVES FUELLED ETC: 47033 (5) 25205 (5) 25910 (F)
25037 (5)

59207 PUMP BATTERIES PUT ON CHARGE ALL CELLS TOPPED UP.

53328 } ALL HEATERS MADE TO WORK. 3 NEW GLOW PLUGS
53932 } FITTED - 2 OTHERS SERVICED
54487 }

25205 BOTH BOGE SANDERS NOT WORKING. MADE TO WORK.

CARBOURIES REPAIRS

51903 CAMEL OUT TO LUNDAVIDMO ATTENTION TO HEATERS REPAIRS
BLOWING COLD AIR MADE TO WORK ETC

25205 CAMEL OUT TO YARD DOWN REPORTED RED AIR BRAKE
PIPE LEAKING BAD FOUND ICE IN VALVE. NOT SEATING
VALVE MADE TO WORK ETC BRAKE TEST ON LOCO CARRIED
OUT

25037 CAMEL TO LOCO AFTER WORKING AT PUM GOODS YARD
WAS WINDOWS DIRTY CLEANING ALL WINDOWS ETC.

47104 TRACTION MOTORS AND D.S.D (SOLVED WERE TO BE HUNG)
TO CREW FOR ATTENTION TO DEFECTIVE ENGINE
RUM SOLENOID AND COV

47190 CREW REPORTED WERE AT RHYL SUSPECT PUMP BRIT BLOCKED
IN YARD BY DERAILED WAGONS?!!

53203 PUMP BRIT PUT ON CHARGE. UNIT TO WORK BACK TO CREW
1805 FOR ATTENTION NO ENGINE FAULTY STRAIGHT MOTOR.
H 2 ENGINE GEAR SLIP IN NO. 2 GEAR.

Monday, 10th Feb. 86.

D. Hill. P. Cox
CAR'S PULLED ETC:-

51903 53931 51179.
54486. 51562 54358.

51903 NO 2 ENGINE EXHAUSTOR & ALTERNATOR BOLTS
MISSING NOW BOLTS FITTED & ADJUSTED.

54486 CALL TO LLANDUDNO. DR REPORTED THAT BATT'S
CAR TAKEN OUT OF SERVICE BROUGHT ON STND.
PUT ON CHARGE. ETC:-

51562 NO 1 ENGINE EXHAUST MANIFOLD JOINTS BLEWING
NOW JOINTS FITTED & TIGHT

TUE. 11 - 2 - 86

FUEL IN TANKS N^o 1, 2300 N^o 2, 7000 TOTAL 9300

R.T. N^o 65709 FULL.

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC. 51179 53931 51903
54358 57562 54486

51909 53318 53311
54271 53328 59117
53322

LOCOS FUELLED ETC. 47033 (F) 25910 (S) 25037 (F)
25205 (F) 25196 (S)

59117 FIAT BATTERIES PUT ON CHARGE CIRC TESTED
AM CELLS FILLED - DYNAMO BELTS MISSING
NEW BELTS FITTED.

25196 COOLANT HOSE PIPE SPLIT ON TOP OF ENG
NEW HOSE PIPE FITTED.

51909 DR SIDE W/WIPER MOTOR DEFECTIVE NEW
MOTOR FITTED.

53311 BOTH HEATERS REPAIRED. (1) NEW GLOW PLUG
FITTED + FUEL SYSTEM BLEED

CARBURES REPAIRS

51562 :- Called out to station Reported no heat in cabin went into
Llandudno found heater working but very poor heat output only 1 heater

53931 :- Called out to station Driver Reported unable to close
driving cab window, window made to work etc

51184 :- Called out to station Reported no buzzer in van and returned

47190 loco still at Rhyll Fiat Bait

47104 } Called to yard by Tel Driver Reported unable to get Air
25196 } Brake to work after 2 locos coupled up 25196 travelled 47104
to crew for attention tracing for fault found for brake valve
not locked on brake test carried out etc.

51179 :- Called out to station Driver Reported no 2 engine
knocking off rails topped up at Llandudno also heater on/over
cutoff in and out but no heat unable to retrain.

Tuesday, 11th Feb 86.

D. Hill. P. Cox

CAR'S ROLLING ETC-

51181.

51197.

142035.

54345.

54336.

54345. CALL TO LLANDUDNO DR REPORTED TRAIN LIGHTS & INDICATORS NOT WORKING FOUND. REAR BATTERIES. CAR BROUGHT ON STAN. PUT ON CIRCUITS CIRCT CHECKED ETC-

51181 NO.2 ENGINES THROTTLES STICKING MOTOR STRIPPED WASHED & TESTED.

51197. BAD AIR LOCK FROM L.P. VALVE BOY FOUND FORWARDED L.P. VALVE LOCKING REMOVED STRIPPED CLEANED. REPLACED. & TESTED.

54048. CALL TO LLANDUDNO NO HEAT NO.6 PISTON BLOWN ALSO L.H. GLOW PLUG BURNT NEW PISTON & PLUG-PISTON & TESTED.

53228. CALL TO STATION DR REPORTED NO.1 ENGINES CUTTING OUT ROD TOPPED UP & TESTED.

WED 12-2-86

FUEL IN TANKS No 1. 1.300 No 2 7000 TOTAL 8.300

R.T. No 65709 FULL.

B. A. ROBERTS. M. PRICE.

53311

CARS FUELED ETC: 59117 51569 51903 51909

53322 53931 54486 54271

51191 51181 51197

54340 54345 54336

LOCOMOTIVES FUELED ETC: 47033(S) 25037(S) 25910(F)

25095(S)

51191 No 2 ENG EXHAUSTER & ALTERNATOR BELTS MISSING NEW BELTS FITTED.

54271 FINE MAT BATTERIES PUT ON CHARGE WERE TESTED No 3 DYNAMO FIELD FUSE RENEWED.

51197 } AIR HEATERS REPAIRED. 2 NEW GLOW PLUGS
54336 } FITTED - No 6 FUSE RENEWED ON TIE

CAPRIKES R. R. PRITCHARD

54340 FINE MAT PUT ON CHARGE

51191 DOWNER REPORTED UNABLE TO START No 1 ENGINE FOUND TO HAVE AIR LOCK IN FUEL SYSTEM BLEEDING RACE OF AIR LATERIES RUN-UP ALSO ATTENTION TO 2 TREATMENTS MADE TO WHEEL

25191 CAME OUT TO QUARD BY TEL TO CHECK ON LOCO DOWNER REPORTED HUB ON OUTER SIDE OF LEFT HAND AND FRONT TO BE CLEANED WHEN ON SHED UNABLE TO TAKE ANY WORKING ON FIREWORK. ETC

51569 } CAME OUT TO STATION DOWNER REPORTED NO
53931 } HEATING CONVEYERS FOUND THEMSELVES WORKING BUT VERY POOR HEAT OUT-PUT ETC UNIT TAKEN OUT OF SERVICE. 51191 TAKEN UP WORKING

142035 FUELED ETC. SERVICE CREW

WED. 12/2/86.

D. HILL. P. COX
CAR'S FOLLOWED UTCI-

51201 51913
54349 54497.

47033 "A" EXAM CARRIED OUT. ALSO DE REPORTED
BRAKES WANT ADJUSTING. ROUND ONE SLACK
ADJUSTOR SEIZON. REMOVED. REPAIRED ON
BENCH. REFITTED & ADJUSTED BRAKES TEST
CARRIED OUT.

47543 CALL TO STATION. LOCO FAILED @ PRYSTAYN
EXAM & FOUND NO COOLANT. LOCO HAULLED TO
HOLYTRAD. 25037 WORKED FORWARD.

54336. CALL TO STATION. R.H. HUNTER NOT WORKING.
NOW GLOW PLUG. FITTED & TESTED.

51913 NO1 ENGINES EXHAUSTOR & ALTERNATOR BOLTS OVERT
PULLEY REPLACED & ADJUSTED

THURS. 13. 2-86

FUEL IN TANKS N^o1 400 N^o2 6.400 TOTAL 6.800

R.T. 65709 FULM.

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51191 53625 51181 51202
54340 54213 54345 54349

51913 51562 53322
54497 53931 59117
53311

WAGONS FUELLED ETC: 47033 (F) 25910 (S) 25037 (F)
25032 (S)

53625 N^o1 ENG EXHAUST MANIFOLD JOINTS BLOWING NEW JOINTS FITTED.

54349 PLAT BATTERS PUT ON CHARGE. CIRK TESTED POS LEAD ON DYNAMO TERMINAL BLOCK. MOOSE SEIZED UP & TESTED ALSO ALL CELLS FILLED.

54213 BUZZER UNIT IN CAB DEFECTIVE. NEW BUZZER UNIT FITTED.

25032 N^o2 END R.H. WD SANDPIPE DAMAGED NEW SAND-PIPE FITTED.

CARBUKES REPAIRING

25032 CAME OUT TO YARD REPORTED LOSS OF AIR THROUGH AIR LEAKING TO FLEXIBLE AIR PIPE WASHED WITH LECO COILED UP TO WAGONS REPAIRED

51199 CAME TO STATION ATTENTION TO HEADERS MADE TO WORK.

47033 CAME OUT TO YARD TO CHECK ON HEADEN TANK UNABLE TO FULL HEADEN DUE TO WATER VALVE FROZE-UP.

142035 CARS A AND B SEALIE GREEN BR2

Thursday 13th Feb 86

D. Hill. P. Co x

CAR'S PULLED ETC:-

53938/54411

51910/54052.

51199 CALL TO LLANDUDNO DA UNABLE TO START NO. 1
ENGINE FOUND STARTER MOTOR RELAY STUCK.
REMOVED AND RUN UP & TESTED

54336 CALL TO LLANDUDNO NO START. FOUND NO. 6 PUMP
BLOWN NOW PUMP FITTED ALSO R.H. HORN BLOW
PUMP BURNT NOW PUMP FITTED & TESTED.

54339. CALL TO STATION. R.H. HORN NOT WORKING
BLOW PUMP SERVICED & TESTED.

53938. NO. 2 ENGINE EXHAUSTOR & ALTERNATOR BELTS
OFF PULLEY. BELTS REPLACED & ADJUSTED

51910. EXHAUSTOR & ALTERNATOR BELTS MISSING.
NO. 1 ENGINE NOW BELTS FITTED & ADJUSTED.
ALSO ALTERNATOR BELTS OFF NO. 2 ENGINE
BELTS REPLACED & ADJUSTED 2 SETS COUPLED.
53938 51910.

FRI 14-2-86

FUEL IN TANKS N^o1 400 N^o2 5.500 TOTAL 5.900

R.T. 65709 FULL.

B.A. ROBERTS M. PRICE.

CANS FUELLED ETC: 51913 57181 51910 53938
54497 54345 54052 54411

53625 53311 51183
54213 59117 54344
53322

WCCS FUELLED ETC: 25037 (S) 25910 (F) 25206 (F)
25202 (F) 25323 (S)

25206 BOTH BOVE SANDERS NOT WORKING. MADE TO WORK.

54344 BOTH HEATERS NOT WORKING. BOTH GLOW PLUGS REMOVED & CLEANED REPAIRED & TESTED

57183 N^o1 ENG THROTTLE MOTOR STICKING. MOTOR STRIPPED & CLEANED & OILED.

CAPTAIN RE BRITNARD

A
LEO'S RUN 25032

33938 } CALLED OUT TO WINDSOR STATION GUARDS/DRAWN
54411 } REPORTED UNIT VERY COLD AND TO CHECK ON HEATERS
IF WORKING FOUND THE WORKING BUT POOR HEAT OUTPUT
ON T/CAR.

34345 CALLED OUT TO STATION REPORTED HEATER NOT WORKING
FOUND WORKING

25032 A-EXAM COMPLETED AT 235138 MILES.
BRAKE SLIPER ADJUSTERS RE ADJUSTED.
LAMP FITTED IN ENGINE ROOM LIGHTING
WINDSCREEN WIPER MOTOR SERVICED AND LAMP
DRAWN SIDE AND MADE TO WORK. ENGINE
BLOW CURTAINING DUE TO ENGINE COVERS OFF
WAS RELETED CAP AND FIRE CONTROL BELL
ADJUSTED AND MADE TO WORK.

FRIDAY, 14TH FEB 86.

D. HILL R. L. PRITCHARD. M. PRICE 20.00

CARS ROLLED ETC:-

51187	51192	51184	51907
54332	54354	54342	54490.

54497 CALL TO LINDA DR REPORTED NO MARKER OR
CAB LIGHTS FOUND NO 5 FUSE BLOWN. NOW FUSE FITTED
& TESTED

51192 NO 2 ENGINE & ALTERNATOR BOLTS MISSING
NOW BOLTS FITTED & ADJUSTED.

53316 CALL TO STATION. DR REPORTED NO 2 ENGINE
CUTTING OUT. FOUND LOW IN LUB OIL SUMP
TOPPED UP & TESTED

54342 FLAT BATTERIES. PUT ON CHARGE CIRCT CHECKED
NO 3 DYNAMO FUSE BLOWN. NOW FUSE FITTED & TESTED

54344. CALL TO STATION. DR REPORTED AIR & AXLE LIGHT
NOT WORKING. NOW BULB FITTED & TESTED

SAT. 15.2.86

FUEL IN TANKS N^o1 400 N^o2 4.700 TOTAL 5.100

R.T. N^o 65709 FULL

B. A. ROBERTS - M. PRICE.

CARS FUELED ETC: 51183 51187 51192 51184.
54344 54332 54354 54342
51910 53938 57181 53311
54052 54411 54345 59117
53322

53938. N^o1 ENG EXHAUST & ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

54332 FLAT BATTERIES PUT ON CHARGE CIRCUIT TESTED
ALL CELLS FILLED ALSO N^o9 BATTERY CHARGE
FUSE BLOWN NEW FUSE FITTED.

53322 N^o2 ENG EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED.

51184 FLAT BATTERIES PUT ON CHARGE CIRCUIT TESTED

54052 TOP SIDE W/ WIPER MOTOR DEFECTIVE MOTOR
RENEWED.

D. HILL. ROOF

LOCO'S FULLY UPTO.

25910. (S) 25032. (S) 25037. (R) 47328 (S)

CARS FULLY UPTO: 51907/54490 53208/54060.

45125. CALL TO STATION. DR REPORTED BRAKE AIR PRESSURE
ON BOGIE GAUGES GOING "ON" & "OFF" TESTED IN STATION.
NO FAULT FOUND LOCO WORKED FORWARD.

53334 CALL TO LLANDUDNO DR UNABLE TO START
N^o2 ENGINE FOUND FUEL SYSTEM AIR LOCKED BLEW. TESTED

25037. DR REPORTED STANDARD NOT WORKING. MADE TO
WORK BOTH BOGIES.

47328 CAB DR DR'S SIDE N^o1 AND WILL NOT START.
REPAIRED ETC.

45142 CALL TO LLANDUDNO DR UNABLE TO START ENGINE
ON ARR @ LLANDUDNO LOCO RUNNING OK. TESTED
FOR POWER ETC.

51907. N^o2 ENGINE EXHAUST & ALTERNATOR BELTS OFF PULLEY
REPLACED & ADJUSTED

Sunday, 16th Feb 86

B. A. ROBERTS M. PRICIS.

CARS ROLLING ETC:-

51181	53938.	51907.	53208.	53334
54345.	54411	54490.	54060.	53316.
53311/59117/53322.				

LOCO'S ROLLING ETC:-

45115 (B) 47328 (B)

STEEL EXAM ALLOT.

3052 so 5293 TSO 5288 TSO. 5408 TSO. 5389 TSO.
13448 FK. 84239 NDX.

53938 PLAT BATTERED. PUT ON CHARGES ETC:-

54345 PLAT BATTERED PUT ON CHARGES ETC:-

51907 DR UNABLE TO START NO.1 LONGING. REPAIRS START MOTOR STUCK RELATED + TESTED.

53208. L.H. HUNTER NOT WORKING. THIS IN PAVOL ROUND BLOWN. NOW THIS RE-TWO + TESTED

MON 17-2-86

LAFOUKES P. COX

CARS ROLL OIL WATER ETC.

51181

51187

53228

54345

54332

54055

53334

53311 - 59117 - 53334

53316

	(F)	(P)	(S)	(R)
Locos	25910	- 25032 -	25037	47328

54055 ATTENTION TO HEATERS UNABLE TO GET LEFT HAND SIDE HEATER TO WORK DUE TO BRUISED PORE VALVE

53311 ATTENTION TO 2 HEATERS 2 MADE TO WORK ALSO HAND BATTLE LIMIT SWITCH STUCK OFF. SWITCH RESET

53322 ATTENTION TO 2 HEATERS 2 MADE TO WORK ETC.

54332 ATTENTION TO 2 HEATERS 2 MADE TO WORK ACTION BUT COMBUSTOR ETC

ALL ABOVE HEATERS MADE TO RUN UP BY UNCONVENTIONAL METHODS

ROLL IN TANKS No1 400

No2 3,900

TOTAL 4,300

R.T 65709 ROLL

MON 17-5-71 HOW
Monday. 17th Feb 86.

Loco's Fuelled etc: -
25265. (3)

51185. CALL to Llandudno. Guard Reported. R.H.
Heater NOT WORKING. New Glow Plug. Fitted.
+ Tested ALSO BUZZER in CAB adjusted + tested.

54055. CALL to STATION. L.H. Heater NOT WORKING.
UNABLE TO REPAIR. Fuel Valve Defective F.H.S.

47301. DR Brought Loco on site Low in COOLANT.
SYSTEM TOPPED UP + TESTED NO LEAKS FOUND.
Returned to SERVICE. OUT OF COURSE.

25265. SANDRUS. made to work BOTH BOGIES.

47446. CALL to STATION. DR Reported Sump Tank Low.
TOPPED UP + TESTED. FOR LEAKS NONE FOUND.
REPAIRS CARRIED OUT @ BANGOR TO SAVE JOURNEY.

142035. DR Reported. UNABLE TO LOCK OR UNLOCK.
MASTER KEY. PANEL REMOVED FOR ACCESS. TO SAME.
OILS + TESTED. PANEL REPLACED. CAR 55576.

TUE 18-2-86

CAROLINE P. Cox

CARS ROLL ON WATER ETC.

51907
54490

53208
54060

51183
54344

53228
54055

51191
54340

53316
53334

53311 - 59117 - 53322

Locos	(S)	(S)
	25032	25910

51191 ATTENTION TO HEATERS ALSO NO 2 ENGINE ALTERNATOR AND EXHAUSTOR BELTS OFF PULLEYS AND REPIRTED AND 2 HEATERS MADE TO WORK.

54340 ATTENTION TO HEATERS 2 MADE TO WORK. ETC.

53311 ATTENTION TO HEATERS 2 MADE TO WORK. ETC

53322 ATTENTION TO HEATERS 2 MADE TO WORK ETC

53208 ATTENTION TO HEATERS 2 MADE TO WORK ETC.
ALL ABOVE HEATERS MADE TO WORK BY UNCONVENTIONAL METHODS

54060 RIAS BATT PUT ON CHARGE ETC. CURE GIVEN ON

53316 } DOWN REPORTED NO HEAT IN COACH BLOWING COLD
53334 } AIR BOUND GUARD'S HAD PUT HEATER CONTROLS TO
VENT SWITCHES RESET TO HEAT AND CURR CONTROLS
RESTARTED ALL 4 HEATERS THEN MADE TO WORK
LEFT ON TEST FOR 2 HRS ALL WORKING WHEN LAST CROCKED OFF

PULL INSTANCES NO1 400 NO2 3000 TOTAL 3,400

R.T 65709 Full

TUE 18-2-86

D. Hill in Price

CAR'S PUZZLED ETC:-

53929.

54269.

LOCO'S PUZZLED ETC:-

25037. (F) 25265 (F)

25910 "A" EXAM. CARRIED OUT.

54269. CALL TO LLANDUDNO HONOUR MADE TO WORK.

25037. SETTLING TANK GAUGES BELOW - NOW GAUGES
PUTTED ROOMY TAPPED UP & TESTED

53929. CALL TO LLANDUDNO. NO HOAT & TRAIN LIGHTS
NOT WORKING FOUND FLAT BATTERIES.
CAR TAKEN OUT OF SERVICE FOR CHARGING.

53929. FLAT BATTERIES PUT ON CHARGE ETC:-

WED 19-2-86

CHAPOULLES P. COX.

CARS FUEL OIL WATER ETC.

51903

51191

53226

54339

54340

54066

53929

53228

51910

54269

54055

54052

53311 - 59117 - 53322

53334

53316

	(R)	(S)	(S)
LOOS	25910	25265	25199

54269 PUT BAIT PUT ON CARROUSE TO FIRE UP HEATER ATTENTION TO HEATER MADE TO WORK.

53228 ATTENTION TO HEATER 2 MADE TO WORK.

53322 ATTENTION TO RED MARKER LIGHT CURR ALSO 2 HEATERS MADE TO WORK AND ENGINE PANEL LIGHT BULBS FITTED.

54052 PUT BAIT PUT ON CARROUSE ETC CURE CHECKED. ALSO ATTENTION TO HULL LIGHT. NEW BULBS FITTED.

FUEL IN TANKS NO1 5,000 NO2 6,000 TOTAL 11,000

R.T 65523 FULL

19/2/86.

D. Hill. M. PRICE R. S. PRITCHARD

CARS Pulled etc:-

53625.

54213

Loco's Pulled etc:-

25037 (S)

51909. CALL TO STATION NO 2 ENGINES CUTTING
OUT RAIL TOPPED UP & TESTED

51200 CALL TO LLANDUDNO. DR REPORTED L.H
MOTOR NOT WORKING NOW GLOW PLUG FITTED
& TESTED

142035 PULLING POINT EXAM

53226 NO 2 ENGINE EXHAUST FLEX PIPE HOLED NOW
PIPE FITTED & TESTED.

25265 "A" EXAM CARRIED OUT ALSO 5 EXHAUST PIPES
JOINTS BLOWING NUTS & BOLTS MISSING.

NOW JOINTS & NUT & BOLTS FITTED & TESTED
DR REPORTED LOSS OF POWER, ALSO A.W.I.S
ISOLATED BOTH ENDS TESTED & SUSPENDED.

RELAY UNIT DEFECTIVE. REMOVED. TIPS CLEANED
REPLACED STILL DEFECTIVE LOCO TO CROWD
MAINT INFORMED.

25199 "A" EXAM CARRIED OUT.

THUR 20-2-86

CARBOURIS P. CAR,

CARS FUEL OIL WATER. ETC.

51203
54339

51187
54332

51191
54340

* 53625
54213

51181
54345

* 53929
54269

53311-59117-53322

53334
53316

	(S)	(P)	(R)	(S)
Loco's	25910	25199	25265	25244

53929 DOWN REPORTED UNABLE TO START ENGINES FOUND TO HAVE FUEL BATT PUT ON CHARCOLE AND AIR FUSES CHECKED CARS TOPPED UP WITH WATER. REPAIRS MADE TO WORK. ETC.

51181 ATTENTION TO HEATERS 2 MADE TO WORK.

54345 ATTENTION TO HEATERS MADE TO WORK

51187 ATTENTION TO HEATERS 2 MADE TO WORK.

51203 ATTENTION TO HEATERS 2 MADE TO WORK

54332 ATTENTION TO HEATERS 2 MADE TO WORK

53334 DOWN REPORTED THE MOT WORKING MADE TO WORK.

FUEL INTAKES NO1 5000 NO2 4,700 TOTAL 9,700

R.T 65523 FULL

THURSDAY. 20TH FEB. 86

D. HILL. M. PRICE R. D. PRITCHARD.

25058. Aⁿ EXAM CARRIED OUT ALSO BRAKE BLOCKS.
CITARD-GTD

51903. CALL TO STATION. DR REPORTED. AIR & AXLS
LIGHT NOT WORKING. NOW BULB FITTED & TESTED.

51179. CALL TO L. Lian Dubno. DR REPORTED. NO. 2 ENGINES
WILL NOT START FOUND STARTER MOTOR STUCK
IN PLY WHEEL. RELEASED & TESTED

47619. CALL TO STATION. DR REPORTED LOW AMPS. EXAM
RWT FACTORS TURNED. SUSPECT NOT WORK FUELING.
LOCO WORKED TO CROWS. MAINT INFORMED.

53929 CALL TO STATION. DR REPORTED FLAT BATTERIES.
SET TAKEN OUT OF SERVICE PUT ON CITARD-G. STOPPED
Lian Dubno.

54358 CALL TO STATION. R. H. HAVATOR NOT WORKING NOW
GLOW PLUG FITTED & TESTED

25199. CALL TO YARD. DR REPORTED ENGINES SHUT-DOWN
EXAM & FOUND. COOLANT PIPE JOINT TO NO. 1 CYLINDER
"B" BANK. ON ENGINES BLOCK. LEAKING. LOCO BROUGHT
ON SHED STOPPED. PIPE REMOVED. NOW JOINTS ORDERED
FROM CROWS. LOCO STOPPED

CARFINDER P. COX

ENGS ROLL OIL WATER ETC.

51191 53206 53625
54340 54058 54213

53332 53929 51197
53312 54269 54336

53716 - 59091 - 53675 53334
53316

Locos (P) (P) (S) (P)
25910 - 25224 25173 47482

25224 Checked over to yard reported unable to close gas cocks
Attention to loco tank made to work.

54340 Attention to heaters & made to work also
engine room bulbs fitted in parallel

51191 Reported that lights not working from various cars
found fuse blown and replaced.

54269 } Rept Batt put on charge. Also heaters made to work.
53929 } " " " "

51197 Attention to heaters & made to work.

53312 Attention to white mineral light cure made
to work.

*53716 Driver reported no heat in coach & heaters made
to work but no heat in dining cars.

*53675 No heat in cars * Cars not fitted with water heaters Batt to check

Roll in tanks No 1 5,000 No 2 3,900 Total 8,900

R.T. - 65523 Full.

FRIDAY. 21st FEB 86

D. HILL. M. PRIED. R. SPRITCHARD 15.00.

Loco's Pulled etc:-
47095 (S).

53625. CALL TO LLANDUDNO. DR REPORTED NO 1 ENGINE
GEAR BOX SLIPPING IN 1ST QUAR. UNABLE TO
REPAIR GOT WORKED TO CHESTER.

25199. COOLANT PIPES & NEW JOINTS REPLACED HOSE
PIPS FITTED COOLANT TOPPED UP & TESTED

54213 CALL TO STATION. IGNITOR NOT WORKING. NEW
GLOW PLUG FITTED & TESTED.

51180 CALL TO STATION DR REPORTED NO 2 ENGINE & V/DR
ISOLATED @ HOLYTRIN. UNABLE TO REPAIR
@ STATION CAR TO CHESTER.

51907. CALL TO STATION. DR REPORTED NO 2 ENGINE
CUTTING OUT RAD TOPPED UP & TESTED.

53334. CALL TO LLANDUDNO. DR REPORTED NO 2 ENGINE
CUTTING OUT SHORT OF WATER. RAD TOPPED UP
& TESTED. FOUND TRAN START MISSING. ENGINE
& V/DR ISOLATED.

SAT 22-2-86

CRIPPLES P. 601

CRIPPLES RUN ON WATER ETC.

51184

51907

53929

54342

54490

54269

53206

53332

53334

54058

53312

53316

53927

53326 - 59128

- 53310

54214

53927 :- Called out to station driver reported No 2 engine knocks off found to have air leak in fuel system bleeding free of air and engine run-up also attention to heaters made to work.

53316 :- Called out to station driver reported loss of control air went into handbrake to save delay system unloader valve sticking for further check water on pit road for attention. To park faulty unloader valve blanked off in service P.M.D.A. Attention to heaters made to work.

53929 :- Driver reported unable to start engines found fuel bait (good drain lights) put on engine systems run-up but unable to get heaters to work only one heater fitted for check now replacement heater fitted

51907 :- Attention to marker lamp now lamp fitted also attention to heaters made to work.

53334 :- Slow in marking air on engine No 2 engine and fuel drive isolated due to fuel spray missing.

SAT 22nd FEB 86.

D. HILL. R. E. PRITCHARD.

Loco's Ruined etc.

25224 (S) 25910 (S) 25265 (F) 47482 (S) 47079 (F)

142028. F + I. DR REPORTED. UNABLE TO RELEASE BRAKES.
"FOR" + "REV" PUT TO NET. UNCOUPLED BUTTON PRESSED.
& RELEASED. BRAKES RELEASED.

53317. CALL TO STATION DR REPORTED. HEATER NOT
WORKING. R.H. SIDE NOW GLOW PLUG FITTED & TESTED.

25224. SANDERS MADE TO WORK BOTH BEHNS.

142036 F + I CARRIED OUT.

54487 CALL TO LLANDUDNO. DR REPORTED. HEATER NOT
WORKING ALSO NO CAB OR MARKER LIGHTS EXON.
& FOUND NO 6 FUSE BLOWN. NOW FUSE FITTED.
ALSO NO 5 FUSE EXCHANGED & TESTED.

53324. CALL TO LLANDUDNO. DR REPORTED. NO 2 ENGINE
WILL NOT START. FOUND STARTER MOTOR RELAY
STUCK. RELEASED.

CAR'S RUINED ETC:-

51191 51188 51197 51906
54340 54348 54336 54489.

54348. FLEW BATTERIES. PUT ON CIGARETTES ETC:-

SUNDAY 23-2-86

D.F.HILL. P. COX.

CARS FUELLED ETC: 53206 51197 51966
54058 54336 54489

51188 51191 53929 53312 53310
54348 54340 54269 53332 59128
53326

LOCOS FUELLED ETC: 47434(5) 47482(5)
25910(5)

STOCK EXAM. 92092 NEA. 13463 FK 5195 TSO
5340 TSO 5298 TSO 5268 TSO 3607 SO
3071 SO.

51906 N°1 ENG EXHAUSTER - ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

51197 REMAINS TO BOTH HEATERS (1) NEW GLOW PLUG
FITTED - N°6 TUBE RENEWED ON OTHER.

53306 CASH OUT STATION. BUZZER NOT WORKING IN GUARDIA
VAN. BUZZER UNIT ADJUSTED - TESTED.

MON 24-2-86

CATERPILLAR

CANDS FUEL OIL WATER ETC.

51188	51191	53929
54348	54340	54269

53927	51907
54214	54490

53310-59128-53326

53312	53306
53332	53325

	(P)	(P)	(P)
Loco's	25224	25910	47482

53312 ATTENTION TO MEMBERS 2 MADE TO WORK ETC

53332 ATTENTION TO MEMBERS 2 MADE TO WORK AND DAWD REPORTED UNABLE TO RESIST NO 12 ENGINE FOUND BUT NOW PUT ON CHARGE TO START CATERPILLAR ETC

51188 ATTENTION TO MEMBERS 2 MADE TO WORK ETC

54348 ATTENTION TO MEMBERS 2 MADE TO WORK ETC

54340 ATTENTION TO MEMBERS 2 MADE TO WORK ETC

53310 DAWD REPORTED UNABLE TO START NO 1 ENGINE DUE TO OLD BLEEDING FUEL SYSTEM BLEEDING AND THEN RUN UP AND ATTENTION TO MEMBERS 2 MADE TO WORK

53326 DAWD REPORTED UNABLE TO START NO 2 ENGINE DUE TO OLD BLEEDING FUEL SYSTEM THEN RUN UP ALSO MEMBERS MADE TO WORK

* 47482 CHANDS RELEASE POWER REPORTED UNABLE TO START FOUND TO HAVE PUT BUT PUT ON CHARGE Loco THEN RUN UP

FUEL IN TANKS NO 1	5,400	NO 2	1,600	TOTAL	7,000
R. F. NO	65523	FULL			

P.S. ALL PIPES IN SHED FROZE UP LAST NIGHT NO WATER. ONLY THIS END OF SHED REMAINING

MONDAY, 24TH FEB 86.

LOCO'S FUELLED ETC:

25196 (W) 47098 (F)

51202 CALL TO LLANDUDNO. DR REPORTED. N°2 ENGINE CUTTING OUT FUEL SYSTEM BLED & TESTED.

25196. MARKER LIGHT GLASS BROKEN. TEMP REPAIR CARRIED OUT. MAINT. INFORMED.

97405. OUT OF COURSE DR BROUGHT LOCO FROM PEN-ONSHEB LOW IN FUEL. 2,120 LITRES. PUT IN TANK. ALSO DR REPORTED LOW IN POWER FOUND LOAD RATE TIPS. BURNT. LOCO TO CROWN FOR REPAIRS.

53938 CALL TO STATION. DR REPORTED ONLY ONE TONE FROM HORN. ADJUSTED & TESTED.

54490. CALL TO STATION. DR REPORTED HEATER NOT WORKING SUSPECT PANEL DEFECTIVE. F.H.D. REPAIRS CARRIED OUT @ LLANDUDNO.

25224 DR REPORTED BEGIE BRAKE CYLINDERS TO EXAM. BRAKE BLOCKS FREE PULL BRAKE PRESSURE. ALL BRAKES SLACK ADJUSTERS ADJUSTED & BRAKE TEST CARRIED OUT.

B.A. ROBERTS. M. PRICE.

CANS FUELLED ETC: 51203 53938
54339 54411

LOCOS FUELLED ETC: 47098 A-EXAM.

53545 CALL OUT LLANDUDNO N°6 FUSE BLOWN. NEW FUSE FITTED & TESTED.

54349 CALL OUT LLANDUDNO HEATERS NOT WORKING HEAT GROW PLUGS REMOVED & CLEANED REPAIRED & TESTED.

54339 FLAT BATTERIES PUT ON CHARGE. CIRC TESTED N°9 BATTERY CHARGE FUSE RENEWED. ALL CIRCUITS TESTED & FULLED.

Tue 25-2-86

Choukies Refitment

CARS Fuel Oil WATER etc

53312

53927

53938

53332

54214

54411

51203

51907

51188

54339

54498

54348

51904

54487

Ⓢ

Ⓢ

Ⓢ

Leeds

25910

25224

47098

54214 Fuel BATT put on STANCO and ATTENTION TO HEATER
MADE TO WORK.

53938 ATTENTION TO HEATERS 2 MADE TO WORK.

51188 ATTENTION TO HEATERS 2 MADE TO WORK.

53312 ATTENTION TO HEATERS 2 MADE TO WORK

53332 ATTENTION TO HEATERS 2 MADE TO WORK

54498 Fuel BATT on HEATER like glow plug live at
THE TIME. F.H.D.W

25910 DOWN REPORTED BLOWER NOT WORKING? CHECKED
WINDLOW RUN NO FUEL FOUND ONLY FUEL TRIPPED RESET.

FUEL INTAKES NO1 4,100 NO2 1,200 TOTAL 5,300

R.F 65523 Full

TUESDAY, 25TH FEB 86

D. HILL P. COX.

25266 "A" EXAM CARRIED OUT.

51202. CALL TO STATION. L.H. HORN NOT WORKING. NEW C-LOW PLUG FITTED & TESTED.

51906. CALL TO WHANDUENO. DR REPORTED NO.1 OVERHEAT. EXHAUST PIPE 3 BOLT JOINT BLOWING. NUTS MISSING. 3 NEW NUTS + BOLTS FITTED & TESTED.

RAIL TRUCK. 65523 UNLOADED TOP'S INFORMED.

31446. PHONE CALL FROM T.C.I. REPORTED BRAKE FAULT ON LOCO. OR TRAIN. ON EXAM NO FAULT. DR REPORTED BROKEN RAIL. TRAIN WORKED FORWARD. (CALL OUT).

47565. CALL TO STATION. DR REPORTED W.T.H. NOT WORKING. FOUND THCFR TRIPPED. RESET & TESTED.

B.A. ROBERTS. M. PRICE.

CANS FUELLED ETC. 51180 51904
54355 54487

54489 CALL OUT WHANDUENO T/TONE HORN NOT WORKING. BOTH HORNS ADJUSTED & TESTED.

53312 CALL OUT WHANDUENO W/WINTER ARM & BLADE UNCOUPLED & FITTED & ADJUSTED.

51180 NO.2 ENG EXHAUSTEN & ALTERNATOR BELTS MISSING. NEW BELTS FITTED.

54487 PRAT BATTERIES PUT ON CHARGE CIRK TESTED. ALL CELLS TOPPED UP.

WED. 26TH FEB 86

D. HILL. A COX M. PRICE. £6.00
LOCO'S PUZZLED ETC:-

47424 (P) 25191 (S).

53332. CALL TO LLANDUDNO DR REPORTED NO. 2
ENGINES CUTTING OUT RAW TOPPED UP & TESTED.
FOUND WATER PUMP SEAL'S LEAKING ENGINES & P/A
ISOLATED. UNABLE TO REPAIR CAR TO CITUATOR.

47424. DR REPORTED. HORN STUCK NO. 2 UNDERGROUND
HORN VALVE 2ND MAN'S SIDE DEFECTIVE. VALVE REMOVED,
STRIPPED, CLEANED, REPLACED & TESTED.

53724. CALL TO STATION. L.H. HORN NOT WORKING. NOW
PLUG FITTED & TESTED

25191 DR REPORTED BRAKE DEFECTIVE. WANTS
ADJUSTING ALL BRAKE SLACK ADJUSTERS.
ADJUSTED & BRAKE TEST CARRIED OUT. ALSO
COOLANT FILLER VALVE LEAKING. TEMP REPAIR CARRIED
OUT COOLANT TOPPED UP & TESTED. ALSO LUB OIL
LEAK IN ENGINE ROOM FOUND ROCKER COVER
LEAKING SCREWED UP & TESTED. ENGINE
ROOM & BLOCK CLEANED. ALSO CAB WINDOW'S
CLEANED

53673. CALL TO STATION. DR REPORTED. BUZZER NOT
WORKING. ADJUSTED & TESTED

54349. CALL TO LLANDUDNO DR REPORTED NO MARKER OR
CAB LIGHTS. FOUND NO 5 FUSES BLOWN. NOW FUSES FITTED
& TESTED.

THUR 27-2-86

CARBOLES REFRIGERATOR

CARS FUEL OIL WATER

53927

51200

51904

54214

54359

54487

53938

51179

53312

54411

54358

53332

NO 2 LIGHT BULB

51907

54498

	Ⓟ	Ⓟ	Ⓟ
Lamps	25191	25910	25224

53332 : ATTENTION TO HEATERS 2 MADE TO WORK.

53332 : ATTENTION TO HEATERS 2 MADE TO WORK ALSO INSIDE LIGHT BULBS FITTED

54358 : ATTENTION TO HEATERS UNABLE TO GET RIGHT HAND SIDE TO PICK UP SYSTEM FAULTY FUEL SUPPLY INSIDE HEATER ALSO FUEL BAIT PUMP CHECKED ETC.

53927 : ATTENTION TO HEATER WORKING BUT VERY POOR HEAT OUTPUT INTO COACH ONLY 1 HEATER FITTED ALSO LAMPS FITTED IN GUARD'S VAN LIGHTING LAMPS WORKING

54214 ATTENTION TO HEATER WORKING BUT VERY POOR HEAT OUTPUT INTO COACH ONLY HEATER FITTED.

51200 ATTENTION TO HEATERS 2 MADE TO WORK ETC

54498 BOMBAY PATROL LIGHT BULBS FITTED AT PATROL

FUEL IN TANKS No 1 5000 No 2 7000 TOTAL 12,000

R. T 65523 Empty.

THURSDAY, 27th FEB 86

D. Hill P. Cox M. Price. 16.00.

LOCO'S REWELDED ETC:-

25034 (S).

142036. F + 1. CARRIED OUT.

CALLOUT.

53673 DR REPORTED AIR + AXLE LIGHT NOT WORKING.
NEW BULB FITTED + TESTED.

53313 CALL TO LLANDUDNO. DR REPORTED L.H. HORN NOT WORKING NEW GLOW PLUG FITTED + TESTED.

25034. DR REPORTED SANDERS NOT WORKING MADE TO WORK BOTH BODIES.

25910 CALL TO YARD DR REPORTED. AIR BRAKE PIPE NO 2 AND BOILER BROKEN. LOCO BROUGHT ON SHED PIPE REMOVED. REPAIRED REPLACED + TESTED

53312 CALL TO LLANDUDNO DR UNABLE TO START NO 2 ENGINE FOUND CYLINDER HEAD GASKET BLOWN. ENGINE + P/D ISOLATED TO CITATOR.

47324 "A" EXAM CARRIED OUT.

53337 CALL TO STATION. DR REPORTED HORN. DEFECTIVE ONLY ONE TONE ADJUSTED + TESTED

FRI 28-2-86

CUTFOUNDS RE-RITCHMAN

CARS FUEL OIL WATER ETC

51903

51907

53938

54486

54490

54411

51179

51200

53203

54358

54359

54080

53228

54055

(P)

(P)

(P)

Loco 47324

25910

25058

54490 :- FUEL BATT PUT ON CHARGE BFC ALSO ATTENTION TO HEATER MADE TO WORK.

51907 :- ATTENTION TO HEATER MADE TO WORK.

54055 :- FUEL BATT PUT ON CHARGE ATTENTION TO HEATERS MADE TO WORK.

51200 :- ATTENTION TO HEATERS MADE TO WORK.

54359 :- ATTENTION TO HEATERS MADE TO WORK.

FUEL IN TANKS No 1 4000

No 2 7,000

TOTAL 11,000

R.T. :- 65523 Empty, R.T. 67141 FULL.

FRI 28.2.86

B. A. ROBERTS. P. COX. M. PRICE.

CARS FUELLED. 53672
53722

LOCOMOTIVES FUELLED ETC.: 25058 A-EXAM 47066 (F)

51201 CALL OUT MAINTENANCE NO ENGINE WONT START
STARTER MOTOR RELAY. STUCK. RELEASED &
TESTED.

53672 CALL OUT MAINTENANCE L.H. HEATER NOT
WORKING. NEW GLOW PLUG FITTED & TESTED

25058 BOTH POGIE SANDERS NOT WORKING MADE TO
WORK. & A-EXAM CANNIST CERT.

54349. CALL OUT MAINTENANCE T/TONE HORN NOT
WORKING. BOTH HORNS ADJUSTED.

1-3-86

CAFOLKES RE PRITCHARD

CARS Fuel oil WATER etc.

53625

51194

53228

54213

54346

54055

53203

53307

51903

54080

53323

54486

53722

53724

53672

53673

53772 - Fuel BATT pvi on CARS etc ATTENTION TO HEATERS
2 made to work

53672 - Reported no LIGHTS in lower FOUND CUE FUSE BROWN
Repaired also 2 HEATERS made to work.

51194 - Reported UNABLE to START no 2 LUBRIC BOUNDS TO
HAVE AIR LOCK in FUEL SYSTEM BUBBLES W/2 PUFFS
OF AIR AND W/2-UP ALSO ATTENTION TO HEATERS
2 made to work.

51903 - FOUND BYPASSING BRIS off PUMPS Reported
POOR VACUUM BRIS REPERED AND ADJUSTED
ALSO ATTENTION TO HEATER MADE TO WORK.

54213 - ATTENTION TO AMERICAN HEAT 'RED' CUE
TRACING PVI TO PAVLY HAMPTON.

1-3-86

BAILROBERTS. M. PRICE.

CARS FUELLED ETC: 51185 51179
54352 54358

WAGONS FUELLED ETC: 47324 (S) 25910 (S)
25181 (F) 25206 (S)

53312 CALL OUT MAINTAINING CAB WATER HEATER
NOT WORKING. EXAM FOUND 25AMP FUSE MISSING
NEW FUSE FITTED & TESTED.

54358 CALL OUT MAINTAINING HEATERS NOT WORKING.
FOUND FLAT BATTERIES. UNIT TAKEN OUT
OF SERVICE. PUT ON CHARGE. CABLE TESTED
ALL CELLS FILLED & HEATERS REPAIRED.

51902 CALL OUT STATION BOTH ENDS CUTTING OUT
WAGONS TOPPED UP & SWAMP CUB CHECKED.
ENDS RUN UP TESTED.

51185 NO ENGINE EXHAUSTER & ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

SUN 2-3-86

CHFOUKES R & PRITCHARD

CRDS PWR OIL WATER ETC.

51179
54358

51185
54352

51177
54351

51903
54486

51181
54345

53927
54214

53625
54213

53332
53312

53724
53673

Loco's ^(F) 45105

^(S) 25206

DAILY EXAM OF LOCOMOTIVE STEEL

MDR PR TSO TSO TSO SO SO
84252 - 13471 - 5313 - 5399 - 3650 - 3694 - 3605
51181 ATTENTION TO HEAD WORK CRD RELAXED.

51179 NO ENGINE AND PUMP DRIVE KEPTED DUE TO KROCKIT
PUMP DRIVE ALSO SUSPECT GASKET BLOWN ON CRANK
USEFUL ALOT OF WATER BATCH TRIP ALSO ATTENTION
TO HEADS 2 MADE TO WORK ETC.

51177 ATTENTION TO HEADS 2 MADE TO WORK RELAX
PWS BLOWN 2 MADE TO WORK ETC ALSO RED MARKER
LIGHT BULB REPLACED CRD CRACKED OK

54351 ATTENTION TO HEADS 2 MADE TO WORK ALSO
MARKER LIGHT "WHITE" MADE TO WORK PARTLY
HAMPTONIAN.

51185 ATTENTION TO HEADS 2 MADE TO WORK