

MONDAY 3RD MARCH 86

RAIL TANKS NO 67141 FULL 65523 MT.

FUEL IN TANKS NO 1. 200 NO 2 7000 TOTAL 8.200
D. HILL M PRICE.

53332 53927 53625 51903

53312 54214 54213 54486

53724/53673 51181/54345.

LOCOS FUELLED ETC.

47324 (F) 25910 (F) 25181 (S)

53927. PLAT BATTERIES PUT ON CHARGE CRECT
CITIZEN & TOSTON.

53312. R.H. HEATER MADE TO WORK.

51903 HEATER MADE TO WORK. (ONLY ONE HEATER ON P/CAR)

54486. HEATER MADE TO WORK - - - T/COAR.

51181. L.H. HEATER MADE TO WORK.

25181 SANDERS MADE TO WORK BOTH BOGIES.

3.3.86

B.A. ROBENS. R.E. PRITCHARD.

CARS FUELLED ETC. 57194 51910 53938
54346 54052 54411
57184/54342.

LOCOMOTIVES FUELLED ETC. 25206 (F) 47270 (F)
25910 A. EXAM.

25910 A. EXAM CARRIED OUT ALSO NO 3 & 4 CYL
HEAD MANIFOLD JOINTS BLOWING. NEW JOINTS
FITTED.

57194 CALL OUT HANDLING NO 1 LENS CUTTING OUT
EXAMINED FOUND FAN BELTS MISSING.
UNIT TAKEN OUT OF SERVICE. NEW BELTS
FITTED & RELEASED BACK INTO SERVICE.

53206 CALL OUT HANDLING HAND BRAKE BUZZER
STUCK. RELEASED & TESTED.

4-3-86

PULL IN TANKS NO 1 400 NO 2 6,600 TOTAL 7,000

R/TANK 67141 FULL.

D-HILL M. PRICES.

53325. CALL TO STATION. DR REPORTED. BUZZER NOT WORKING. IN VAN. ADJUSTED & TESTED.

CARS FUELLED ETC:-

53927.	53938.	51184	51910.	51194.
54214.	54411	54342	54052.	524346.

53673/53724

53312/53332.

Loco's FUELLED ETC:-

25910 (S) 25206 (S). 25224 (S)

47270 "A" EXAM CARRIED OUT.

51194. NO 1 ENGINE FAN BELTS MISSING. ALSO STUD'S BROKEN. ON FAN DRIVE HOLDING DOWN STUD'S. ALSO FOUND FINE FILTER BOWL BRACKET BROKEN. ENGINE & F/DR ISOLATED. CAR TO CUSTODIAN FOR REPAIRS.

54411 HEATER MADE TO WORK GLOW PLUG CHANGED.

51910. NO 2 ENGINE EXHAUSTOR & ALTERNATOR BELTS MISSING. NEW BELTS FITTED & ADJUSTED

51184. NO 1 ENGINE THROTTLE STICKING. MOTOR STRIPPED WASHED. & TESTED

54052 FLAT BATTERIES. PUT ON CHARGES CIRCUIT CHANGED. ALL CELLS TOPPED UP. & TESTED

4-3-86

B. A. ROBERTS R. E. PRITCHARD.

CARS FUELLED ETC. 142033 SERVICE CHECK.

51185/54352

LOCOS FUELLED ETC. 47280 (S) 25224 A. EXAM.
47590 A. EXAM.

53673 CALL OUT MANDUONO L.H. RED TAIL LAMP NOT WORKING NEW BULB FITTED.

53333 CALL OUT MANDUONO BOTH ENDS CUTTING OUT RADS TOPPED UP & SUMP OIL ON N°2 ENG TOPPED UP - TESTED.

53318 CALL OUT MANDUONO N°6 FUSE BROWN ON POWER CIR. NEW FUSE FITTED. ALSO REPAIRS TO BUZZER SWITCH. IN DR CAR.

5-3-86.

FILLIN TANKS NO1 400 NO2 5,400 TOTAL 5,800.

RAIL TANKS 67141 FILL.

D. HILL. M. PRICES.

CAR'S FUELLED ETC:-

51177. 51183. 51184 51185. 53910.
54351. 54344 54342. 54352 54052.

53673/53724. 53312/53332.

LOCO'S FUELLED ETC:-

2 5224 (F) 25998 (S) 47270 (F)

54346. CALL TO LLANDUDNO HEATERS NOT WORKING NO6
FUSE BLOWN. NOW FUSE FITTED ALSO LIT GLOW
PLUG-CHANGED BOTH HEATERS TESTED

25191 STANDARDS MADE TO WORK BOTH BOGIES.

51177. NO1 ENGINE EXHAUSTOR & ALTERNATOR BELTS OFF
PULLEY. ~~THE~~ BELTS REPLACED & ADJUSTED.

54344 HEAT BATTERIES. PUT ON CHARGE CIRCUT CHECKED.
ALL COZLS TOPPED UP HEATERS & LIGHTS.
TESTED.

51185. NO2 ENGINE FLOX EXHAUST PIPE HELD ON NOW PIPE
FITTED & TESTED.

5-3-86

B.A. ROBERTS. R.E. PRITCHARD. P. COX.

CALLS FURNISHED ETC: 53927
54214.

LOCOMOTIVES FURNISHED ETC: 25904 (F) 25910 (F) 47590 (F)

47590 BRAKE BLOCKS RENEWED ALSO (2) BRAKE
SHOCK ADJUSTERS SEIZED, REMOVED
REPAIRED & REFITTED.

53927 CALL OUT WANDUIDNO NO 2 ENG WONT START.
START MOTOR PINION STUCK IN FLYWHEEL.
RELEASED & ENG RUN UP & TESTED.

54214. CALL OUT WANDUIDNO HEATER NOT WORKING
NO FUEL TO HEATER SUSPECT FUEL LINE
BLOCKED. UNIT TAKEN OUT OF SERVICE.

6-3-86

FUEL TANKS NO1 400 NO2 4,500 TOTAL 4,900.

RAIL TANK. 67141 FULL.

D. HILL. P. COX M. PRICE 00.00.

CARS FUELLED ETC:-

51185. 51913. 53206. 51183. 51177.
54352. 54497. 54058. 54344. 54351.

53927/54214 53673/53724 53332/53312.

LOCO'S FUELLED ETC:-

25191 (F) 25910 (S) 25266 (S)

54349. CALL TO STATION. DR REPORTED AIR &
ATLUS LIGHT NOT WORKING. NEW BULB
FITTED & TESTED.

54352. CALL TO LLANDUDNO. DR REPORTED NO
CARB OR MARKER LIGHTS. FOUND NO 5 FUSE
BLOWN. NEW FUSE FITTED & TESTED.

51913. NO 1 ENGINE EXHAUSTOR + ALTERNATOR BOLTS
MISSING. NEW BOLTS FITTED + ADJUSTED.

53206 NO 2 ENGINE EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED + TESTED.

25266. R.H. SETTLING TANK GAUGE LEAKING NOW
GAUGE FITTED COOLANT TOPPED UP & TESTED.

6.3.86

B.A. ROBERTS. R.E. PRITCHARD. P. COX.

CARS FUELLED ETC: 53938 51203 53625
54411 54334 54213

LOCOS FUELLED ETC: 47270 (S) 25206 (S) 47342 (S)
25323 (F)

RAIL TANKER NO 67141 UNLOADED.

54344 CALL OUT MAINTENANCE L.H. HEATER NOT WORKING
FUEL SOLENOID DEFECTIVE. UNABLE TO REPAIR.

53625 CALL OUT MAINTENANCE DR BRAKE VALVE VERY
STIFF TO OPERATE. VALVE STRIPPED CLEANED
& REASSEMBLED.

51194. CALL OUT MAINTENANCE EXHAUST PIPE UNCOUPLED
FROM ENG. 3 NEW NUTS & BOLTS FITTED.
(Nº 1 ENG.)

7-3-86

PULLIN TANKS. NO1 5,800 NO2 6000 TOTAL. 11,800.

RAIL TANKS. 67017 Full. 67141 M.T.

D. HILL. P. COX M. PRICE.

CARS PULLLED ETC:-

51203. 53938. 51185. 53625. 53206.
54339. 54411 54352. 54213. 54058.

51177. 53332. 53673.
54351. 53312. 53724.

LOCO'S PULLLED ETC:-

25191 (S) 25910 (F) 25323 (S).

54334. CALL TO STATION. DR REPORTED L.H. HEATER
NOT WORKING. NOW GLOW PLUG FITTED & TESTED.

51185. CALL TO LLANDUDNO DR REPORTED TWO TOWNS HORN.
NOT WORKING. FOUND CONTROL VALVE HANDLE LOOSE.
REPAIRED & TESTED.

53938. DR REPORTED AIR LEAK. IN FORWARD GUAR
FOUND L.P. VALVE LEAKING. VALVE REMOVED.
STRIPPED CLEANED REPLACED & TESTED.

54411 TRAIN LIGHTS LOW & HEATERS NOT WORKING.
BATTERIES PUT ON CHARGE. CIRCET CHECKED.
LIGHTS & HEATERS TESTED AFTER CHARGING.

54213. WIND SCREEN WIPER ARM BROKEN. NOW
WIPER FITTED ADJUSTED & TESTED.

25323 SANDERS NOT WORKING MADE TO WORK.
BOTH BOGIES..

7.3.86

B.A. ROBERTS. RE PRITCHARD. P. COX.

CARS FUELLED ETC: 51183 51194 51201 53732
54344 54354 54347 59526
53686

LOCOMOTIVES FUELLED ETC: 47113 (S) 47270 (P) 25224 (F)
25266 (F)

51183 CALL OUT MANDUINO REPORT UNIT FAILED
54344 LAST NIGHT. BRAKE GEAR UNCOUPLED. EXAM
WITH R.S.T. 2. FOUND NO 2 BOGIE ON T/CAR
NO BRAKE HANGER TOP PIN MISSING. NEW
PIN FITTED. UNIT BROUGHT ON SHED & SERVICED.

51187 CALL OUT MANDUINO A.W.S. NOT WORKING. NO HORN
SOUNDING. HORN E.P. VALVE DEFECTIVE. A.W.S
ISOLATED & FORWARD TO CHESTER.

51194 CALL OUT MANDUINO NO 1 ENG WONT START
STARTER MOTOR RELAY STICKING. RELEASED
& TESTED.

25224 ~~WAS~~ BAD AIR LEAK ON LOCO WHEN BRAKE APPLIED
EXAMINED FOUND BRAKE AIR PIPE ON NO 1
BOGIE UNCOUPLED. REFITTED & TESTED.

25910 BAD AIR LEAK ON LOCO NO 2 BOGIE BRAKE
SUPPLY PIPE TO CYLS BACKEN. PIPE REMOVED
REPAIRED - REPLACED.

25266 FAULT FINDING LOSS OF POWER. TRACED
TO DIRTY CONTACTOR TIPS UNDER CONTROLLER
NO 1 END. TIPS CLEANED & LOCO RUN UP
& TESTED. ALSO NO 9 FUSE LOOSE IN HOLDER
SECURED.

8.3.86.

FULL TANKS N^o1 4,300 N^o2 6,000 TOTAL. 10,300.

RAIL TANKS 67143 FULL 67017 FULL 67141 m/t.

D. HILL. P. COX M. PRICE.

CAR'S IN WULLS ETC:-

51194. 51183. 53206. 51203. 51192.
54346. 54344. 54058. 54339. 54354.

51201 53724 53317. 53732/59526/53686.
54347. 53673. 53324.

51183 N^o2 ENGINE FLEX EXHAUST PIPE BROKEN.
NEW PIPE FITTED & TESTED.

51194. N^o2 ENGINE EXHAUSTOR & ALTERNATOR BOLTS MISSING.
NOW BOLTS FITTED & ADJUSTED.

54346 HEATERS NOT WORKING N^o6 FUSE BLOWN. NOW
FUSE FITTED ALSO R.H. GLOW PLUG CHANGED TESTED.

54354. FLAT BATTERIES. PUT ON CHARGE CIRCUIT CHECKED
ALL COILS TOPPED UP LIGHTS & HEATERS TESTED
AFTER CHARGING L.H. HEATER GLOW PLUG CHANGED.

53732. N^o2 ENGINE EXHAUST MANIFOLD JOINTS
BLOWING NOW JOINTS FITTED & TESTED.

59526. TRAIN LIGHTS LOW - BATTERIES. PUT ON
CHARGE CIRCUIT CHECKED ETC:-

8.3.86

B A ROBERTS. P. COX.

CARS FUELLED ETC:

LOCOS FUELLED ETC: 25191 (F) 47270 (S) 25224 (S)
25910 (S) 25659 (F) 25266 (S)

53228 CARR OUT MANTUANO T/TONE HORN NOT WORKING
BOTH HORNS ADJUSTED.

54055 CARR OUT MANTUANO L.H. HEATER NOT WORKING
NEW GLOW PLUG FITTED & TESTED.

54352 CARR OUT MANTUANO. NO TRAIN LIGHTS FROM
LIGHTING SWITCH. NO 4 FUSE BLOWN NEW FUSE
FITTED.

25266 BOTH BOGIE SANDERS NOT WORKING MADE TO
WORK.

SUN 9 - 3.86

B. A. ROBERTS. M. PRICE.

CARS FURNISHED ETC: 53206 51179 51190 51181
54058 54358 54353 54345
51194 53228 53317 53732
54346 54055 53324 54526
53686

LOCOS FURNISHED ETC: 47441 (F) 25224 (S) 47270 (S)

STOCK EXAM. 84239 NDX 13448 FR 3052 SO 5293 TSO
5288 TSO 5408 TSO 5389 TSO

51190 NO 2 ENG EXHAUSTER + ALTERNATOR BELTS
MISSING NEW BELTS FITTED.

84239 NDX. FLAT BATTERIES PUT ON CHARGE. CIRC
TESTED. ALL CELLS TAPPED UP. ALSO DYNAMO
BELT MISSING. NEW BELT FITTED.

10.3.86.

FULL IN TANKS NO 1 31400 NO 2 61000 TOTAL 91400

RAIL TANKS 67143 FULL 67017 FULL 67141 M/T.

D. HILL P. COX.

CAR'S FUELLED ETC:-

51194	51181.	53228.	53317.
54346.	54345	54055.	53324.

53732 / 59526 / 53686.

LOCO'S FUELLED ETC:-

25191 (S) 25910 (P) 25206 (P)

~~25191. CALL TO LOCO IN STATION HORN STUCK. FOUND CONTROL VALVE NO 1 LEAK. 2ND MAN'S SIDE STUCK REMOVED. STRIPPED CLEANED REPLACED. + TESTED~~

54346. HOISTERS MADE TO WORK NO 6 PIST BLOWN. + R.H. BLOW PLUG CHANGED.

54055. WIND SCREEN WIPER ARM UNCOUPLED REPAIRED + TESTED

53324. ONLY ONE TONE FROM HORN ADJUSTED + TESTED

53732. HOISTERS NOT WORKING. R.H. BLOW PLUG CHANGED + TESTED
L.H. HOIST CABLE UNCOUPLED REPLACED + TESTED

53686 FLAT BATTERIES. PUT ON CHARGED CIRCUIT CHARGED
CELLS TOPPED UP. + TESTED

25191. CALL TO LOCO IN STATION HORN STUCK. FOUND CONTROL VALVE NO 1 LEAK. 2ND MAN'S SIDE STUCK REMOVED. STRIPPED CLEANED REPLACED. + TESTED

10 - 3. 86

B.A. ROBERTS. M. PRICE. R.E. PRITCHARD.

CARS FUELLED ETC: 53316
53334.

LOCOS FUELLED ETC: 47270 (F) 25224. (F)

53625. CALL OUT WANDUIDNO NO 1 ENG CUTTING OUT
FUEL SYSTEM AIR LOCKED. SYSTEM BLED
- TESTED.

51201 CALL OUT WANDUIDNO L.H. HEATER NOT
WORKING - SNOW PILE REMOVED, CLEANED
- REPLACED. HEATER TESTED.

54213 CALL OUT WANDUIDNO HAND BRAKE BUZZER
STUCK. SWITCH RELEASED & TESTED.

53317 CALL OUT STATION NO 1 ENG ISOLATED BY DR.
EXHAUST MANIFOLD JOINTS BLOWING. UNIT TAKEN
OUT OF SERVICE. NEW JOINTS FITTED & RELEASED
BACK INTO SERVICE.

53334 NO 2 ENG THROTTLE MOTOR STICKING MOTOR STRIPPED
CLEANED - REASSEMBLED.

11th MARCH 86

FUEL IN TANKS. NO.1 2,800 NO.2 6,000 TOTAL. 8,800

RAIL TANKS. 67143 FULL 67017 FULL. 67141 m/t.

D. HILL. R.E. PRITCHARD. P. COX 0000.

CARS PULLED ETC:-

51201 51181 51910 53228 53206
54347. 54345. 54052. 54055 54058.

53334/53316. 53732/59526/53686.

LOCO'S PULLED ETC:-

25224 (B) 47344 (B) 25059 (F).

25191 "A" EXAM CARRIED OUT.

54345. CALL TO LLANDUDNO DR REPORTED BUZZER NOT WORKING A.W.S. NOT WORKING ISOLATED.
& ONLY ONE TONE FROM HORN. FOUND FLAT BATTERIES UNIT TAKEN OUT OF SERVICE.
SEC D.M.U. SHUT.

51201. NO.1 ENGINE EXHAUSTOR & ALTERNATOR BELTS OFF PULLEY. BELTS REPLACED & ADJUSTED.

54345. BATTERIES. PUT ON CHARGE ALL CELL'S TOPPED UP. A.W.S. & ISOLATED. HORN ADJUSTED. BUZZER & A.W.S. TESTED AFTER CHARGING.

54052. HEATERS NOT WORKING. R.H. GLOW PLUG SERVICED & TESTED. L.H. GLOW PLUG CHANGED & TESTED.

11-3-86

B. A. ROBERTS. M. PRICE. R. E. PRITCHARD.

CARS FUELLED ETC.

LOCOS FUELLED ETC. 25206 (S) 25910 (S)

51187 CARB OUT MAINTAINED AIR & AXLE LIGHT
NOT WORKING. EXAMINED FOUND ELECTRICAL
PLUG UNCOUPLED ON N°2 FIDRIVE.
RETTIED & TESTED.

51190 CARB OUT MAINTAINED NO ENG WONT
START, STARTER MOTOR PINION STUCK
IN FLYWHEEL. RELEASED ENG RUN
UP TESTED.

54353 CARB OUT MAINTAINED BOTH HEATERS
NOT WORKING. BOTH GLOW PLUGS REMOVED
CLEANED & REPLACED & TESTED.

54345 CARB OUT STATION TO EXAM DR REPORTED
DYNAMO DROPPED OFF ENROUTE. UNIT
TAKEN OUT OF SERVICE TO BE WOLLED
TO CHESTER FOR REPAIRS.

12.3.86.

FULL IN TANKS NO 1 1,500 NO 2 6,000 TOTAL 7,500

RAIL TANKS 67143 FULL 67017 FULL 67147 M/T.

D. HILL REPRITCHARD P. COX

CAR'S PUZZLED ETC:-

51913. 51177. 53206. 53228. 51181
54497. 54351. 54058 54055. 54345.

51200 53334 53686/59526/53732.
54359. 53316.

LOCO'S PUZZLED ETC:-

25224 (12) 25910 (13) 47188 (14).

51177 CALL TO LLANDUDNO. DR REPORTED NO 2 ENGINES
WILL NOT START. EXAM & FOUND. SHORT ON COOLANT.
ALSO FAN BOLTS MISSING LWB & R/DR ISOLATED.
TAKEN OUT OF SERVICE.

54354 CALL TO STATION. GUARD REPORTED TRAIN
LIGHTS NOT WORKING FOUND NO 4 FUSE BLOWN.
NOW FUSE FITTED & TESTED

51177. NO 2 LWB FAN BOLTS FITTED. LWB & R/DR DEISOLATED
COOLANT TOPPED UP & TESTED.

54351. HEATER NOT WORKING. NO 6 FUSE BLOWN. NOW FUSE
FITTED & R.H. GLOW PLUG SERVICED & TESTED

51913. DR REPORTED NO 1 ENGINES THROTTLES STICKING.
MOTOR STRIPPED EASED & TESTED.

51200. NO 2 ENGINE EXHAUSTOR & ALTERNATOR BOLTS
MISSING NOW BOLTS FITTED & ADJUSTED.

54359. PLAT BATTERIES. PUT ON CHARGE CIRCT CHECKED
FOUND. NO 3 DYNAMO FUSE BLOWN. NOW FUSE
FITTED. & TESTED.

12-3-86

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC.

LOCOS FUELLED ETC: 47340 (F) 25181 (S)

51185. CARB OUT MAINTAINED RED TAIL LAMP NOT WORKING
NEW BULB FITTED.

54345 CARB OUT MAINTAINED T/TONE HORN NOT WORKING
BOTH HORNS ADJUSTED.

25181 N°2 END DR SIDE W/WIPER CONTROL VALVE DEFECTIVE
NEW VALVE FITTED.

47340 COOLANT HOSE PIPE ON TOP OF HEAT EXCHANGER
SPRIT NEW HOSE PIPE FITTED.

CARBUKES RE-PRITCHARD

CARS FUEL OIL WATER ETC.

51909

53206

51177

54271

54058

54351

51913

53686 - 59526 - 53732

54497

54487 CARB OUT TO STATION ATTENTION TO "ROD" MANUAL LIGHT
GEE MADE TO WORK.

54058 REPORTED NO AIR LIGHT UNITS COUPLED UP BULBS
REPLACED IN PARK.

51177 DRIVER REPORTED UNABLE TO START HOI BECAUSE FOUND
SIGNAL MOTOR PINION STUCK IN KEYWAY. REPAIR DONE. N.H. SP.

13.3.86.

FUEL IN TANKS. N^o1 800 N^o2 61000 TOTAL. 61800.

RAIL TRAKERS 67143 FULL. 67017 FULL 67141 M/T.

D. HILL. P. COX

CARS FUELLED ETC:-

51199. 51177. 51913. 51909. 53206.
54334. 54351. 54497. 54271. 54058.

53334/53316. 53686/59526/53732.

LOCO'S FUELLED ETC:-

47290 (S) 25910 (S) 25224 (S)

54334. HUNTORS NOT WORKING R.H. GLOW PLUG CHANGED
L.H. GLOW PLUG UNCOUPLED REPLACED HUNTORS
TESTED.

51909. N^o1 ENG MANIFOLD JOINTS BLOWING NEW
JOINTS FITTED & TESTED.

54271 PLAT BATTERIES. PUT ON CHARGE CIRCUT CHARGED
ALL COLL'S TOPPED UP & TESTED AFTER CHARGING.

53686. R.H. TAIL LAMP NOT WORKING FOUND WIRES
TO LAMP HOLDER. UNCOUPLED REPLACED NOW BULB
FITTED & TESTED

BALROBERTS. M. PRICE.

CARS FUELLED ETC:-

LOCOS FUELLED ETC: 47340 (S) 25042 (S) 25911 (S)

25042 FAULT FINDING AFTER LOSS OF POWER ENROUTE. FAULT TRACED
TO NEAR FIELD PILOT MOTOR OVERHEAT. MOTOR RESET &
AUX CONTACTS CLEANED LOCO RUN UP TESTED.

47340 N^o2 & 3 CYL R-BANK EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED

53334 ASSISTING R.S.T2 WITH BRAKE GEAR UNCOUPLED &
DAMAGED. BRAKE CYL BRANKED OFF & MADE SAFE
UNIT TO CHESTER FOR FURTHER REPAIRS.

51201 CALL OUT MANITOWING N^o1 ENG WONT RUN. RAD
FIXED & SUMP OIL CHECKED ENG RUN UP & TESTED

51904 CALL OUT STATION. L.H. ENG LIGHT NOT WORKING
NEW BULB FITTED.

THUR 13-3-86

CAROLINE R. & RICHARD

CAR FUEL OIL WATER ETC.

51913 51190 53208
54497 54353 54060

51177 51905
54351 54488

54353 CALLED OUT TO STATION REPAIRED NO HEAT OR LIGHTS IN COACH WENT INTO LITHIUM BATTERY STATION TO SAVE DELAY FOUND TO HAVE FLAT BATT PUT ON CHARGE WHEN ARR BACK ON TO STREET

51190 ALSO REFERRED TO COACH LIGHTS OR HEATINGS WORKING THROUGH PROBLEMS NO 4 AND NO 6 FUSES BLOWN NEW FUSES FITTED.

51905 } CALLED OUT TO STATION DOWN REFERRED
54488 } NO RETURN WILL NOT REPAIR FOUND TO HAVE FLAT BATT IN STATION (51905) ALSO 54488 T/ONS REPAIRED NO HEAT OR LIGHTS ALSO FOUND TO HAVE FLAT BATT UNIT TAKEN OUT OF SERVICE 51913 TAKEN UP WORKINGS UNIT BROUGHT ON STREET AND PUT ON CHARGE FOUND ALL BATT CELLS EMPTY FILLED WITH WATER.

FKI 14-3-86

CARROLLS REPAIRS

CARS RUN ON WATER ETC.

53203
54080

51185
54352

51902
54485

51177
54351

53929
54269

53318
53328

53686 - 59526 - 53732

51905 DAWON REPORTED UNABLE TO START No 2 LOCOMOTIVE
FOUND FAULTY STATION MOTOR ENGINE MADE
TO RUN UP. BUT STATION MOTOR FOR HOME DES ATTENTION.

51902 PART BRIT PUT ON CHARGE ETC.

51185 No 2 LOCOMOTIVE FOUND AN ALTERNATOR BELT OFF
PULLEYS EXTENSION AND ALTERNATOR REPAIRED

16.3.86.

D. Hill. P. Cox.

CAR'S ROLLLED ETC:-

51175. 51194 53929. 51177 51905
54350. 54346. 54269. 54351. 54488

51904 53318. 53686/59526/53732.
54487. 53328

LOCO'S ROLLLED ETC:-
47561 (1²).

STOCK EXAM PLCT.

92092. NOVA 13463 PK. 3071 SO 3607 SO.
5268 T80 5298 T. SO. 5195 T80

51194. NO 1 ENGINE PAN BOLTS MISSING NONE IN STOCK.
ENG. & F/DR ISOLATED.

51905 FLAT BATTERIES. PUT ON CHARGE NO 1 ENG. & F/DR
DISOLATED SET. WANTS TESTING AFTER CHARGING.

51175. NO 2 ENGINE EXHAUSTOR & ALTERNATOR BOLTS MISSING
NOW BOLTS FITTED & ADJUSTED

47290. FAULT FINDING. ENGINE WILL NOT START. EXAM
& FOUND S. 1. CONTACTOR. RELAY. NOT MAKING WITHIN
CONTACTOR TIPS ARE CLOSED. ALSO S2 TIPS BURNED. LOCO.
ISOLATED. T/MOTORS & D.S.D. LOCO TO BS
HAULED TO CROWD. MAINT & TOPS INFORMED.

MON 17-3-86

CARROLLS REPAIRS

CARS FUEL OIL WATER LTR

51904 51905 51190
54487 54488 54353

53203 53318
54080 53328

53732 - 59526 - 53686

Locos (S) (P) (P)
25109 - 25042 - 47340

53203: ATTENTION TO HEATERS 2 MADE TO WORK.

54080: ATTENTION TO HEATERS ONLY (WORKING RIGHT HAND SIDE HEATER) RAILWAY FUEL SUPPLY INSIDE HEATER.

51905: RWT BATT PUT ON CHARGE

53318: DOWN REPORTED UNABLE TO START WORKING FOUND TO HAVE RWT BATT PUT ON CHARGE AFTER CHARGE WROTE RUN UP ALSO ATTENTION TO HEATERS 2 MADE TO WORK.

51904: ATTENTION TO HEATER MADE TO WORK

54487: ATTENTION TO HEATER BLOW PWC SERVICES MADE TO WORK

FUEL IN TANKS NO1 4,400 NO2 7,000 TOTAL 11,400

R.F 67143 FULL.

17. 3. 86

D. HILL. P. COX

LOCO'S FUELLED ETC.

47203

(S)

25910

(F)

142033 S/C

51175 CALL TO STATION. DR REPORTED ONLY ONE HORN FROM HORN. ADJUSTED & TESTED.

51177. CALL TO LLANIDUDNO. DR UNABLE TO START NO. 1 ENGINES. FOUND STARTER RELAY STUCK RELEASED ENGINES RUN UP & TESTED.

47203. DR REPORTED EXHAUST PIPE JOINT ON PRESSURE CHARGER UNCOUPLED. REPLACED SET BOLTS FITTED & TESTED. ALSO BRAKES WANT ADJUSTING. ALL BRAKE SLACK ADJUSTORS ADJUSTED & TESTED.

47098. OUT OF COURSE DR BROUGHT LOCO ON SHED LOW IN COOLANT SYSTEM TOPPED UP & TESTED FOR LEAKS NONE FOUND ALSO SIFTK TANK TOPPED UP. LOCO RETURN TO SERVICE.

R. A. ROBERTS. P. COX. R. E. PRITCHARD.

CARS FUELLED ETC: 51902 51909 53931
54485 54271 51562

47307 CALL OUT STATION WITH R.S.T.2. DR REPORTED FIRE ON VEHICLE. FIRE EXTINGUISHER USED OFF LOCO. NEW ONE SUPPLIED. HOT BOX ON VEHICLE SEE R.S.T.2. REPORT.

53318. CALL OUT LLANIDUDNO DR UNABLE TO START ENG. FLAT BATTERIES. UNIT TO WORK BACK TO DEPOT FOR REPAIRS.

54350 CALL OUT LLANIDUDNO TONE HORN NOT WORKING BOTH HORNS ADJUSTED & TESTED

51905 CALL OUT STATION DR REPORTED ENG OF TRAVE ISOLATED @ H/HEAD. FLAT BATTERIES UNIT BROUGHT ON SHED FOR REPAIRS.

TOE 18-3-86

Catpooles Rubricard

CARS RUN ON WATER &c

51902

51909

51904

54485

54271

54487

51905

53203

53328

54488

54080

53318

53931

53336 - 59120 - 53303

51562

Locos (GWE) (S) (S) (S)
47290 - 47340 - 25910 - 25042

53203 ATTENTION TO AIR HOOMS MADE TO WORK ALSO 2 HOOMERS MADE TO WORK

54080 ATTENTION TO AIR HOOM MADE TO WORK ALSO ATTENTION TO WAGON HOOM.

53931 FURTHER BAIT PUT ON CARRIAGE HOOM BICYCLES ISOLATED DUE TO (PARTS WANTED) ALSO ATTENTION TO HOOMER MADE TO WORK

51562 ATTENTION TO HOOMER MADE TO WORK

53318 FURTHER BAIT PUT ON CARRIAGE HOOMERS MADE TO WORK

53336 ATTENTION TO HOOMERS MADE TO WORK

53303 FURTHER BAIT PUT ON CARRIAGE TO START BICYCLES ALSO ATTENTION TO HOOMER MADE TO WORK.

RUBRICARDS NO 1 3,500 NO 2 7000 TOTAL 10,500

R.T 67143 RUL.

18.3.86

D. Hill. P. Cox

LOCO'S FUELLED ETC:-

25288 (S) 47203 (F)(BF)

53333. CALL TO STATION NO.1 LONG SHORT OF WATER RAD
TOPPED UP & TESTED.

51562. CALL TO LLANDUDNO DR REPORTED FLAT BATT'S.
CAR TAKEN OUT OF SERVICE PUT ON CHARGE ETC:-

51178. CALL TO STATION. DR REPORTED. HAND BRAKE BUZZER
STUCK. SWITCH RELEASED & TESTED @ LLANDUDNO.

51902. CALL TO STATION. DR REPORTED FLAT BATT'S CAR
TAKEN OUT OF SERVICE PUT ON CHARGE ETC:-

47340 } COUPLED UP LOCO 47290 & BRAKE TEST COMPLETED.

47290 } LOCO HAULED TO CROWS.

53312. CALL TO STATION. DR REPORTED. R.H. HEATER NOT
WORKING. NOW BLOW PLUG FITTED & TESTED.

25288. SAND PIPES & STRAY DAMAGED. NO.1 AND L.H. SIDER REPAIRED.

B. A. ROBERTS. P. COX. R. E. PRITCHARD.

CARS FUELLED ETC. 57180 57922 51913
54355 54493 54497.

LOCO'S FUELLED 25095 (F) 25095 A-EXAM.

25095 A-EXAM COMPLETED ALSO NO.1 & 2 EXHAUST
MANIFOLD JOINTS BLOWING. NEW JOINTS FITTED.

54493 CAR OUT LLANDUDNO DR REPORTED NO. ENG LIGHTS
OR CAB LIGHTS. EXAM FOUND FLAT BATTERIES
PUT ON CHARGE AFTER UNIT PARALLEL ON SHED
ALSO AIR CELLS TOPPED UP & NO.9 DYNAMO WHEEL
RENEWED.

51180 NO.1 ENG EXHAUSTER - WATERPUMP BELTS MISSING
NEW BELTS FITTED.

DMU 142033 CAR NO. 55624 CALLED TO UNIT. DR
REPORTED FIRE BELLS RINGING EXAMINED FOUND
FIRE BOTTLE BLOWN. FIRE ALARM ISOLATED
SWITCH PUT TO OFF, NEW FIRE BOTTLE COMING
FROM CHESTER FOR SAME. REQS FITTING.

WED 19-3-86

CAROLINE REPRITCHARD

CHRS FUEL OIL WATER ETC

51203
54339

53203
54080

51909
54271

51180
54355

51913
54497

51922
54493

51904
54487

53336 - 59120 - 53303

Loco's ^⑤ 25095 - ^⑥ 25288.

54493 FIAT BATT PUT ON CHARGE

51904 ATTENTION TO WINDSCREEN WIPER'S NEW WIPER
BLADES FITTED AND MOTOR MADE TO WORK.

54487 ATTENTION TO HEATER MADE TO WORK ALSO
NEW WINDSCREEN WIPER BLADE FITTED.

47203 CAME OUT TO YARD BY TCI TO CHECK ON FUEL AND
HEATER TRUCK ON LOCO IN YARD. OK FULL

51203 ATTENTION TO 2 HEATERS 2 MADE TO WORK.

54339 ATTENTION TO 2 HEATERS 2 MADE TO WORK.

FUEL IN TANKS NO1 2,700 NO2 7,000 TOTAL 9,700
D.F 67143 FULL

WED. 19.3.86

D. HILL. P. COX

LOCOS FUELLED ETC.:

25201. (S) 25109 (S) 25908 (F)

CARS FUELLED ETC.:

53311/59117/53322. 51178/54335.

51178 CALL TO STATION (Llandudno) DR REPORTED UNABLE TO CRACK VACUUM + NO 2 ENGINE WILL NOT START. NO 2 ENGINE COOLANT TOPPED UP + TESTED. FOUND EXHAUSTOR + ALTERNATOR BOLTS MISSING. NO 1 ENGINE CAR TAKEN OUT OF SERVICE. BROUGHT ON STAND. NOW BOLTS FITTED + ADJUSTED.

142038 CAR NO 55624 NEW FIRE BOTTLES FITTED. FIRE ALARM SWITCH RESET ETC.:

25201. L.H. SETTLING TANK GAUGE LEAKING. NOW GAUGE FITTED. COOLANT TOPPED UP + TESTED.

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC. 53927 51913 51912
54214 54497 54500

LOCOS FUELLED. 47203 (S) 25109 A-EXAM

51904 CALL OUT MANDUDNO DR REPORTED STAY ON EXHAUST PIPE BKT LOOSE. BKT REMOVED FOR SAFETY.

51912 CALL OUT MANDUDNO DR REPORTED GEAR SNIP IN 3RD GEAR BOTH ENDS. FOUND 3RD GEAR E.P. VALVE STUCK. VALVE REMOVED STRIPPED + CLEANED. REPLACE - TESTED.

53927 NO 1 ENG EXHAUST MANIFOLD JOINTS BROWING. NEW JOINTS FITTED.

54500 FLAT BATTERS PUT ON CHARGE. CIRC TESTED. DYNAMIC BELTS SNACK. BELTS ADJUSTED.

25109 A-EXAM CALLED OUT.

THUR 20-3-86

CARBURES REPAIRS

CARS RUN ON WATER ETC.

53927 51912 51913
54214 54500 54497

51904 51909 51178.
54487 54271 54335

53322 53336 53203
59117 59120 54080
53311 53303

Loos (P) (P) (S)
47203 25109 - 25908

51904 REPAIRS BUZZER NOT WORKING IN CAB REPAIRED CURS
MADE TO WORK.

51913 REPORTED VACUUM SLOW BOUND EXHAUSTION AND AUTOMATIC
BETS OFF PULLS AN REBUILT AND ADJUSTED USED
ATTENTION TO HEATER MADE TO WORK

54497 ATTENTION TO HEATER MADE TO WORK ETC

54214 ATTENTION TO HEATER MADE TO WORK

53927 ATTENTION TO HEATER ALSO PAPER LIGHT BULBS
FITTED HEATER MADE TO WORK

59120 ATTENTION TO 2 HEADS 2 MADE TO WORK.

FUEL IN TANKS NO1 1,300 NO2 7,000 TOTAL 8,300

R.T No 6714 3 FUEL www.railcar.co.uk

THURSDAY, 20th MARCH 86

Locos FUELLED ETC:-
25321 (F) 47446 (S)

51991 CALL TO STATION. DR REPORTED WINDSCREEN WIPER
ARM UNCOUPLED. REPLACED ROSET & TESTED.

25321. DR REPORTED SANDERS NOT WORKING MADE TO
WORK BOTH BOGIES.

51424. CALL TO LLANDUDNO. DR REPORTED BOTH ENGINES ON
FULL REV'S. ENGINES SHUT-DOWN. FOUND NO.4
THROTTLE E.P. VALVE DEFECTIVE. BOTTOM PLATE
BROKEN. SUT. TAKEN OUT OF SERVICE. STOPPED.
NEW E.P. VALVE ORDERED FROM CHESTER.

51424. E.P. VALVE REMOVED. NEW VALVE WANTED.

Cars FUELLED ETC:-
51424/54222.

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51906 53938 51916 51189
54489 54411 54499 54343

Locos FUELLED ETC: 47203 BF. A. EXAM.

54340 CALL OUT LLANDUDNO L.H. HEATER NOT WORKING. GLOW
PLUG REMOVED CLEANED REPLACED & TESTED.

47203. A. EXAM CALLED OUT.

51424. NEW 4TH GEAR E.P. VALVE. FITTED ENG & P/D DRIVES
DISCONNECTED. UNIT RUN UP TESTED.

For 21-3-86

CARBURES REPRITING

CHOS Fuel oil water etc.

51913
54479

51189
54343

51912
54500

51916
54499

51906
54489

53938
54411

51909
54271

51904
54487

51424
54222

53336 - 59120 - 53303

Locos (F) 25192 (S) 25109 (R) 25908 (S) 47203

51189 ATTENTION TO AIR HOOPS ONLY HAVE TO GET ONE IDME TO WORK Faulty DIAPHRAGM NONE ON HAND TO PUT ALSO ATTENTION TO HERTONS 2 made to work

53336 ATTENTION TO 2 HERTONS Grow Pines SERVICES 2 made to work

59120 ATTENTION TO HERTONS 2 made to work

53303 Put on COUPORE TO START Engines are covered on.

54271 ATTENTION TO HERTON ALSO PUT IN WATER HOOP MADE TO WORK. ETC. ALSO BRAKE VALVE STUFF TO WORK VALVE CLEANED. ETC.

FUEL IN TANKS No 1 500 No 2 7,000 TOTAL 7,500
R.F.M. 67143 FUEL

21-3-86

B. A. ROBERTS. P. COX. M. PRICE.

CARS FUELLED ETC. 53625 51910 51194 53206
54213 54052 54346 54058

LOCOS FUELLED ETC. 25095. (S) 47188 (F)

51194 CAR OUT MANDUANO NO 2 ENG WONT START. STARTER MOTOR STUCK. RELEASED & TESTED.

53625 CAR OUT MANDUANO NO 2 ENG CUTTING OUT FUEL SYSTEM AIR LOCKED UNABLE TO CLEAR UNIT TAKEN OUT OF SERVICE FOR REPAIR.

54343 CAR OUT MANDUANO NO LIGHTS & AHS NOT WORKING. EXAMINED FOUND FLAT BATTERIS. UNIT TAKEN OUT OF SERVICE. PUT ON CHARGE. CIRL TESTED.

25095 BOTH BOGIE SANDERS NOT WORKING. MADE TO WORK.

SAT 22-3-86

CARBOURLES REPAIRS

CARS ROL ON WHEELS ETC.

51912
54500

51913
54497

51910
54052

51194
54346

53206
54058

53625
54213

51904
54487

51906
54489

51916
54499

53206:- ATTENTION TO MONTORS UNABLE TO GET RIGHT HAND SIDE
MONTOR TO WORK DUE TO PAULITY OF WORN MONTOR.
MOTOR INSIDE MONTOR UNIT NEW MONTOR WANTED

51910:- DRIVER REPORTED UNABLE TO START NO 2 ENGINE
FOUND TO HAVE AIR LOCK AND STICKING BYENGINE
SHUT-DOWN BYENGINE TURN UP ETC. AFTER BLEEDING
PULV SYSTEM ETC.

51194:- DRIVER REPORTED UNABLE TO START NO 1 ENGINE
FOUND STARTER MOTOR PINION STUCK IN BY WHEEL.
RESET BYENGINE TURN UP ALSO ATTENTION TO
MONTORS MADE TO WORK.

51916:- REPORTED AIR LEAKING FROM JOURNAL UNIT THROUGH
GASKET TO NO 2 GEAR UP VALVE WAVE REMOVED AND
SERVICED RETURNED ETC.

22-3-86

B.A. ROBERTS. M. PRICE.

CANS FULMLED ETC: 53927 53303
54214 59120
53336.

WOCOS FULMLED ETC: 25908 (S) 25230 (S) 47188 (S)
25190 (S)

53228 CANN OUT MAINTAINING NO 6 FUSE BROWN ON POWER
CIRK NEW FUSE FITTED & TESTED.

54055 CANN OUT MAINTAINING R.H. HEATER NOT WORKING
CROW PING REMOVED CLEANED & REPLACED
& TESTED.

47188 TOP & BOTTOM B. BANK EXHAUST MANIFOLD
JOINTS BROWN OUT & SET SCREWS MISSING
NEW JOINTS & SET SCREWS FITTED.

53927 REPAIRS TO NIGHTING CIRC IN GUARDS VAN
NO 5 FUSE BROWN ALSO REPAIRS TO NIGHTING
SWITCH R.H. SIDE.

54214 FMAT BATTERIES PUT ON CHARGE CIRC TESTED
ALL BATT CELLS TOPPED UP.

Sunday 23-3-86

CARBOURERS REPAIRS

CARS FUEL OIL WATER ETC

51194
54346

51906
54489

51916
54499

53927
54214

51913
54497

51912
54500

51903
54486

51189
54343

53228
54055

51185
54352

51191
54340

53625
54213

53303 - 59120 - 53336

Loco 3 (S) (S)
47422 25230^{3/4}

51912 ATTENTION TO HULL LIGHT NEW BULBS FITTED IN PANEL CASE.

51194:- Reported unit failed in station 2000 SMT MGMT AND TRUCKS OUT OF SERVICE DUE TO FAILURE A LOT OF WATER MOISTURE AND PANEL DAME ISOLATED SUSPECT CYLINDER HEAD CRACKS BLOWN WATER SIDE THIS FAULT P.H.D. A BEVIS OK AND NO LEAKS.

53228:- Reported failed in station 2200hrs SMT MGMT NO POWER IN THIS CAB 3 SETS COUPLED UP AWS ISOLATED (BOUN BURE) TRUCK HOOKED FORWARD TO BANGOR TRUCK ON SHED, DEISOLATED DSD AND AWS RETESTED IN SHEDS NO FAULT FOUND POWER AND VACUUM OK.

47422:- CAME OUT TO LOCO DRAWN REPORTED BATTERY FAULT LIGHT UP ON PANEL AFTER SIMULING LOCO FOUND POWER BATTERY FAULT REMOVED TRIPPED RESET.

MONDAY 24-3-86

FUEL IN TANKS N°1 3.00 N°2 5.300 TOTAL 5.600

R.T. N° 67143 FULL.

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51194 57906 57916
54346 54489 54499
51903 51189 53228 53927 51913 53303
54486 54343 54055. 54214 54497 59120
53336

LOCOMOTIVES FUELLED ETC: 47188 (F) 25908 (F)

51903. N°1 ENG EXHAUSTER - ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

25908 BOTH MOBILE SANDERS NOT WORKING MADE TO
WORK.

D. HILL P. COX.

CARS FUELLED ETC:-

51911/54496. 51906/54489. 51186/54355

LOCOMOTIVES FUELLED ETC:-

25230 (F)

51192 CALL TO LLANDUDNO. WINDSCREEN WIPER NOT WORKING. CONTROL
VALVE UNCOUPLED REPLACED - TESTED.

25230. SANDERS MADE TO WORK BOTH ROBOTS.

51197. CALL TO LLANDUDNO. HEATERS NOT WORKING FOUND N°6 FUEL
BLOWN NOW FUEL FITTED + TESTED.

47593. CALL TO BANGOR. BRAD AIR LEAK BETWEEN LOCO + TRAIN
FOUND BRAKE PIPE COCK LEAKING ON TRAIN (BOX R.S. 7 II

Reported)

47588. CALL TO STATION WINDSCREEN WIPER UNCOUPLED. DR'S SIDE
N°1 END. REPLACED + TESTED.

TUE 25.13.86

FUEL IN TANKS N^o1 3.00 N^o2 4.80 TOTAL 5.100

R.T. 67143. FULL.

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC. 51911 51906 51180
54496 54484 54355.

51913 51903 53927 51902 51916
54497 54486 54214 54500 54499

53303/59120/53336

LOCOMOTIVES FUELLED ETC. 25908 (5)

47553. CASH OUT STATION LITH NOT WORKING. TRIPPER TRIPPED. RESET & TESTED TRIPPED OUT AGAIN. NOW TESTED OFF TRAIN. OIL SUSPECT FAULT ON TRAIN. WORKED FORWARD. MAINT CONTROL INFORMED.

51185. CASH OUT MANUFACTURE R.H. HEATER NOT WORKING. GLOW PLUG REMOVED CLEANED & REPLACED & TESTED.

51911 N^o1 ENG EXHAUSTER & ALTERNATOR BELTS OFF PULLEYS. ALL BELTS REPLACED & ADJUSTED.

51906 N^o1 & N^o2 EXHAUSTER & ALTERNATOR BELTS OFF PULLEYS. ALL BELTS REPLACED & ADJUSTED.

51180 N^o1 ENG EXHAUSTER & ALTERNATOR BELTS OFF PULLEYS. ALL BELTS REPLACED & ADJUSTED.

59120 FLAT BATTERIES PUT ON CHARGE. CARK TESTED. ALL BATTERY CELLS TOPPED UP. ALSO NEG BATT. RUBBER BROWN NEW RUBBER FITTED.

53336 BOTH HEATERS NOT WORKING. BOTH GLOW PLUGS REMOVED CLEANED & REPLACED. HEATERS TESTED.

Tuesday 25th March 86

D. Hill P. Cox.

CAR'S FUELLED ETC:-

53208/54060 51189/54343

LOCO'S FUELLED ETC:-

25259 (R) 47218 (S)

51912. CALL TO STATION DR REPORTED GEAR SLIP IN 3RD GEAR BOTH BOXES. CAR TAKEN OUT OF SERVICE EXAM + FOUND N^O 3 E. P. VALVE DEFECTIVE REMOVED STRIPPED. CLEANED REPLACED + TESTED.
47433. CALL TO STATION. ENGINE OVERHEATING. LOSS OF COOLANT. ENGINE SHUT-DOWN. HAULED ONTO SITE. EXAM + FOUND. SERVO SYSTEM DEFECTIVE TRAIN'S NOT RUNNING. ETC:- ALSO HIGH WATER TEMP. SWITCH DEFECTIVE DID NOT SHUT ENGINE DOWN. LOCO ISOLATED. T/MOTORS D.S.D. TO BE HAULED TO CROWN. MAINT INFORMED ALSO TOP'S. CODES "H.W.T." + "T."
51197. CALL TO LLANDUDNO. DR UNABLE TO START N^O 1 ENGINE FOUND STARTER MOTOR STUCK IN FLUTTER. RELEASED. ENGINE RUN UP + TESTED.
25259. WINDSCREEN WIPER DR'S SIDE N^O 2 AND NOT WORKING FOUND CONTROL VALVE DEFECTIVE. NEW VALVE FITTED + TESTED.
51916. PLAT BATTERIES. PLATON CHARGE CURCT CHECKED ETC:-
25059. CALL TO YARD DR REPORTED COMPRESSOR GOV. STICKING. EXAM TIPS CLEANED + TESTED
53310. CALL TO LLANDUDNO WINDSCREEN WIPER ARM UNCOUPLED DR'S SIDE. WIPER CHANGED WITH 2ND MAN'S SIDE + TESTED.

26-3-86

FUEL IN TANK. NO 1 5.500 NO 2 7000 TOTAL 12.500

R-T. 67143 M-T.

B.A. ROBERTS. M. PRICE:

51916 53208 51189
CARS FURNISHED ETC: 54499 54060 54343
51906 53328 53927 57413 57919 51903
54489 53318 54214 54497 54257 54486

LOCOMOTIVES FURNISHED ETC: 25259 (S) 25908 (P) 47292 ^{A EX}

51175 CALL OUT WHANDUONG NO 1 ENGINE CUTTING OUT
HAD TOPPED UP & TESTED.

53303 CALL OUT WHANDUONG TITONE HORN NOT
WORKING BOTH HORNS ADJUSTED.

47292 A-EXAM CARRIED OUT ~~ADJUSTED~~

47439 CALL OUT STATION. A.O.C CHESTER REPORTED
LOCO IN TROUBLE. EXAMINED LOSING POWER
OVER 60 MPH UNABLE TO FAULT LOCO WORKED
FORWARD CREW MAINT INFORMED.

53318 CALL OUT STATION NO 1 ENGINE WONT START FRONT
FRONT BATTERIES. UNIT TO WORK TO WHANDUONG
& BACK ON DEPOT FOR REPAIRS.

26-3-86

D. Hill. P. Cox

CAR'S FUELLED ETC:-

53336	53206	51181	51911
59120	54058	54345	54496
53303.			

Loco's FUELLED ETC:-

25181 (S) 25037 (S).

47281 CALL TO STATION DR REPORTED BRAKE DRAG ON
Loco. FOUND STRAIGHT AIR BRAKE VALVE LEAKING
NEW VALVE FITTED & TESTED.

51181. CALL TO STATION ONLY ONE TONE FROM HORN ADJUSTED
& TESTED.

51175. CALL TO LLANDUDNO. NO. 1 ENGINE SHORT OF COOLANT
RAD TOPPED UP & TESTED.

45143. OUT OF COURSE DR BROUGHT LOCO ON SITE EXHAUST
PIPE JOINT BLOWING TOP OF NO. 6 CYLINDER UNABLE
TO REPAIR NO TIME. LOCO FUELLED & COOLANT
TOPPED UP. RETURNED TO SERVICE. CROWD MAINT
INFORMED

47433 FLEX OIL PIPE REMOVED & SENT TO HOLYHEAD.
MAINT CROWD ORDERS.

47439 } BRAKES TEST CARRIED OUT 47439 HAULED
47433 } TO CROWD FOR REPAIRS.

25181. DR REPORTED ENGINE SHUT-DOWN. LOW IN COOLANT
& LUB OIL EXHAUST & FOUND SETTLING TANK GAUGES
LEAKING R.H. SIDE NEW GAUGES FITTED ALSO 30 GALL'S
LUB OIL PUT IN SUMP ENGINE RUN UP & TESTED.

THURS 27-3-86

FUEL IN TANKS NO 1 3.800 NO 2 7000 TOTAL 10.800

R.T. 67143 MT. + 60605. FULL

By AROBENTS M. PRICE.

CARS FUELLED ETC: 51916 51919 51903 51906
54499 54257 54486 54489
53303
53927 53318 51913 53208 51902 51920
54214 53328 54497 54060 54485 53336

LOCOS FUELLED ETC: 47292 (S) 25908 (S) 25181 (E)

51911 CALL OUT W/ANDITNO ENG & F/DRIVE WARNING
NIGHT BULB MISSING NEW BULBS FITTED.

54068 CALL OUT W/ANDITNO L.H. HEATER NOT WORKING
NEW 25 AMP CONTROL FUSE FITTED & TESTED

25908 NO 1 BOGIE L.H. LEADING SANDPIPE DAMAGED
NEW SAND PIPE FITTED

53208 NO 1 ENG EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED.

51902 NO 2 ENG FAN BELTS MISSING NEW BELTS
FITTED.

Catrolles P. Cox. D. Hill, 200-2400 (A)
Woods for 25181 47306.

47306 A-EXAM COMPLETED AND BRAKE BLOCK CONTAINED
ALL ROUND 24 BLOWS. 98210 MILES.

47306 TRACKING FOR FAULT IN INSTRUMENT PANEL LIGHT
CIRCUIT FAULTY. CONTROL SWITCH REBUILT AND WOUND
TO WORK. SWITCH REMOVED AND REBUILT AT WORKSHOP. ALSO
ATTENTION TO 2 BRAKE SHOE ADJUSTERS. LOCKED ON.
REMOVED AND REBUILT AT WORK SHOP.

THURS 27-3-86.

D. HILL P. COX M. PRICE. 20.00.
CAR'S PUZZLED ETC.

25181. "A" LEXAN CARRIAGE OUT.

51199. CALL TO LLANDUDNO DR REPORTED UNABLE TO
START NO1 ENGINE. FOUND STARTER MOTOR RELAY.
STUCK RELEASED ENGINE RUN UP & TESTED.

51189. CALL TO STATION DR REPORTED NO2 ENGINE
CUTTING OUT RAN TOPPED UP & TESTED.

5320F CALL TO LLANDUDNO HEAVYWARE NOT WORKING NO6
FUSE BLOWN NEW FUSE FITTED & TESTED.

FRI 28.3.86

FUEL IN TANKS N^o1 2.800 N^o2 7.000 TOTAL 9.800

R.T. 67143 MT. 60605 FULL.

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 51913 51916 53927
54497 54499 54214
51906 53318 51203 53306 51903
54489 53328 54339 53325 54486

LOCOS FUELLED ETC: 25781 (S) 25908 (F)
25659 (S)

53325 N^o2 ENG EXHAUSTED & ALTERNATOR BELTS
MISSING NEW BELTS FITTED.

51203 N^o2 ENG EXHAUST MANIFOLD JOINTS
BLOWING NEW JOINTS FITTED.

54339 PLAT BATTERIES PUT ON CHARGE CURC
TESTED. ALL CELLS TOPPED UP

ENVOUES P. COX

CARS ROLL ON WATER ETC.

51178 51909
54335 54271

Locos (F) (F)
47292 - 47322

51178 : LANED OUT TO SIMION DOWN REPAIRED NO LENSING
KNEEDING OFF ALL THE TIME WENT INTO LUMINADITO TO
SAVE DRYING ROUND WATER PUMP BELTS MISSING NEW
TAKEN OUT OF SERVICE AND BROUGHT ON PIT ROAD BELTS
FITTED AND ROAD REPAIRED.

53318 } LANED OUT TO SIMION DOWN REPAIRED NO POWER
53328 } FOUND TO HAVE FUEL BAIT UNIT TAKEN OUT OF SERVICE
AND BROUGHT ON STED FOR BAIT CHARGING ETC.

51906 ATTENTION TO HEADERS MADE TO NAME PLATE/TITLE

53306 ATTENTION TO HEADERS MADE TO WORK.

FRIDAY 28th MARCH 86

D. HILL PLOX. M. PRICE 20.00

CARS FUELLED ETC:-

53318/53328 57910 51183
54052 54344

53318 SWT BROUGHT ON SITE THAT BATTERIES. PUT ON CHARGE ETC:-

45148. OUT OF COURSE DR BROUGHT LOCO ON SITE LOW IN FUEL & COOLANT BOTH TOPPED UP & TESTED FOR LEAKS NONE FOUND LOCO RETURNED TO SERVICE.

51181. CALL TO STATION. NO. 2 ENGINES CUTTING OUT. RAD TOPPED UP & TESTED.

54273 CALL TO LLANDUDNO TRAIN LIGHTS NOT WORKING. NO. 4 PUS BLOWN NOW MUST BE TESTED & TESTED

53625. CALL TO LLANDUDNO WIND SCREEN WIPER UNCOOPERATED WIPER ARM REPLACED ADJUSTED & TESTED.

