

LOG BOOK.

FROM 8TH DEC TO 28 JAN.

8TH DEC. 82.

D. HILL. M. PRICE

CARS PULLED ETC.-

50938

56411.

Locos Pulled etc.-

25308(F) 40076(A) 47202(F) 25316(F) 25136(F)

50628. } CALL TO LLANDUDNO DR REPORTED. UNABLE TO GET.
56503. } 1ST + 2ND GEAR DRIVING FROM 56503. GEAR
CONTROLLER REMOVED ALL TIPS CLEANED REPLACED
& TESTED. ALSO DR REPORTED. HEATER P/C AND
T/CAR AND NOT WORKING EXAM NO FAULT
FOUND BOTH HEATERS WORKING.

50938. HEATER MADE TO WORK.

56503. TRAIN LIGHTS LOW PUT ON CHARGE ETC.-

40027. CALL TO STATION. DR REPORTED UNABLE TO
SHUT DROP LIGHT WINDOW NO1 AND DR'S SIDE
CLIPS. RESET WINDOW SHUT & TESTED.

40076. DR REPORTED. WINDSCREEN WIPER NOT WORKING
DR'S SIDE NO1 AND CONTROL VALVE STRIPPED
REMOVED. REPAIRED REPLACED & TESTED.

47202. DR REPORTED. BARTH FAULT LIGHT BRIGHT. RESET
& TESTED.

25316. DR REPORTED. L.O.P. LOCO TO CROWS L.D.
(IN YARD) FOR REPAIRS. LOCO SENT TO CROWS ON THE 7/12/82
FOR SAME REPAIRS. CROWS MANIT & TOPS INFORMED.

40022. CALL TO STATION. DR REPORTED WIPER UNCOUPLED.
NO2 AND DR'S SIDE UNABLE TO REPAIR @ STATION.
LOCO WORKED FORWARD.

TRAIL 9-12-82

CHROULNES P. COX

PLATE	MILES
50721	14690
50668	91400
50628	101260
51177	64080
51569	30720
50932	30750
52046	70730
50939	71160

FUEL IN TANKS NO 1 4,600 NO 2 1000 TOTAL 5,600

CARS FUEL ON WATER LAR. 51177 - 50628
56351 56503

52046 - 51569 - 50721

50939 50932 59100

50668

WOCOS 40143 S/L ^{POWER} 47430 S/L

STOCK: 35295-26015-25725-25975-16196-26011-81180

56503 reported NO BATTERY LIGHTS FOUND WIRELESS ON HAMP PROXIMITY.
REPAIRS AND NEW HAMP FITTED

D. Hill M. Price
CAR'S FUELED ETC.

51196

56376

25146 (S)

Loco's FUELED ETC.

25136 (S)

25050 (S)

40181 (F)

51196. NO. 2 ENG EXHAUSTOR & ALTERNATOR BELTS OFF PULLEYS
ALL REPLACED & ADJUSTED

56376. HEADLAMP NOT WORKING. NO. 6 PIPES CLEANED & TESTED
ALSO. L.H. MARKER LIGHT LAMP HOLDER WIRE
BROKEN. REMAINS NOW BULB FITTED & TESTED

25050. EXHAUST PIPE JOINT NO. 4 CYLINDER REPAIRED

47503. CALL TO STATION. BAD FUEL LINE "B" BANK EXAM
& FOUND H.P. FUEL PIPE TO NO. 10 INJECTOR BROKEN
NOW PIPE FITTED REPAIRS CARRIED OUT @ BANBOR.

47237. WATTH FAULT RELAY TRIPPED. RESET & TESTED.

40181. SANDERS MADE TO WORK.

51196. CALL TO YARD. SET LOCO. HAULAGE FROM
HOLYHEAD. NO. 1 ENG STARTER MOTOR DEFECTIVE.

EXAM UNABLE TO REPAIR. NEW MOTOR WANTED
NO. 2 ENGINE & R/P/R ALSO D.S.D. DISCONNECTED
BROUGHT ON SITE. CALL TO STATION FOR REPAIRS.

Feb 10 - 12 - 82

CARROLLS P. COX

P/CHG	MILES
51192	N/F
51198	155620
51177	64370
51196	51180
50932	31050
51569	31010
50668	91960
50721	14680

R/T. 65710 } Full.
67086 }

FUEL IN TANKS No 1 3000 No 2 1000 TOTAL 4,000

CHAS RUEL OIL ETC 51192 - 51198
56354 56337

51196 - 51177 - 51569 50668
56336 56351 50932 59100
50721

Woods! - 40143 S/C 47537 S/C 47202 F/I 25146 F/I 25136 F/I
Bombs fitted.

Stock: - 35459 - 25983 - 25840 - 16163 - 25797 - 25890 - 35182

51569: - TRAVELING FAULT ON AIR LINE CURR FOUND WHILE DIS SECTION OF HAMPDEN
AND SHORTING OUT CURR ALSO BLOOM DIDO CURR REPAIRS AND CARRS REPAIRS.

56336: ATTENTION TO FILTER 2 MADE TO WOODS

50721: ~ ~ ~ ~

D. Hill. M. PRICE.
CAR'S PUZZLED. ETC. -

50929

56269.

LOCO'S PUZZLED ETC.:-

25308(F) 25133(S) 25164(F).

CALL TO STATION. 56337. JR REPORTED. NO TRAIN LIGHTS.
+ HEATERS NOT WORKING. FOUND BATTERIES LOW
BROUGHT ON SHED. PUT ON CHARGED LIGHTS +
HEATERS TESTED. R.H. GLOW PLUG CHANGED.

25133. SANDERS MADE TO WORK.

25164. A.W.S. NO 1 WIND ISOLATED. DISOLATED + TESTED.
FOUND RESET. BUTTON. TIPS NOT MAKING.
TIPS CLEANED RESET. + TESTED.

50929. NO 2 LONG EXHAUSTOR + ALTERNATOR BELTS
OPE PULLEY BELTS REPLACED + ADJUSTED.

56269. MARKING LIGHT. L.H. SIDE NOT WORKING NOW BULB
FITTER + TESTED.

67056 RAIL TANK UNLOADED 8,140 GALLS TOPS INFORMED

SAT 11-12-82

CAFOLVER P. COX

P/Unit	MILES
51569	31310
50932	31350
51177	64670
51202	25150
51920	73390
50206	H/P
51198	155670
50721	14690
50668	91910

FUEL IN TANKS No1 5,500 No2 5,300 TOTAL 10,800

CHAS FUEL OIL WATER 137 51920 - 50206 - 51198
56504 56058 56337

50721 51569 - 51177 - 51202
59100 50932 56351 56349
50668

Loco's :- 40143 F/I 47439 F/I 25136 S/C 25308 S/C

STEEL: 81180 - 26011 - 16175 - 25975 - 25725 - 26015 - 38295

47439 BRAKE BLOCKS THIN T.C.I INFORMED ONCE TRIP ONLY.

56349 : DRIVING CABS WINDOW BROKEN.

50206 : ATTENTION TO UNLOADED VALVE SUFFERING LOSS OF CONTROL AND.

50668 : REPORTED VACUUM LOSS VACUUM PRESSURE RES. FOUND DRAWERS
BRAKE VALVE NOT IN LIFT RES. ALSO REPAIRS TO BUSSTOP UNIT.

S. HILL. 197-102 M. PRICE.

CAR'S FUELLED ETC.:

51189.

51186.

56343

56357.

LOCO FUELLED ETC.:-

25164 (S)

40049 (R)

40061 (E)

50929 CALL TO STATION. ~~EXHAUSTOR~~ NOT WORKING. NEW GLOW PLUG FITTED & TESTED.

50206 CALL TO QUANDUANO BUZZER NOT WORKING ADJUSTED ALSO. R. H. GLOW PLUG CHANGED & TESTED.

56343 FLAT BATT'S CHANGE ETC.:-

40049. HORN NO 2 AND 2ND. MAINS SIDE DETECTIVE - VALVE REMOVED STRIPPED CLEANED REPAIRED. REPLACED & TESTED.

51186. NO 2 AND EXHAUSTOR & ALTERNATOR BELTS MISSING. NEW BELTS FITTED & ADJUSTED.

40061 SANDERS MADE TO WORK.

51185. CALL TO STATION. L. H. HEATER GLOW PLUG CHANGED & TESTED.

51786. CALL TO STATION. NO 2 AND WILL NOT START. WINDING & P/R ISOLATED & FUEL SYSTEM. DETECTIVE SUSPECT. FUEL PUMP DETECTIVE. F. H. A.

MONDAY DEC 13TH 82

	PICAR	MILEAGES
	50933	—
	57566	93350
	57174	21520
	50938	19960
	57186	57500

R.T. 67056 M.T.
u 65710 Full.

FUEL IN TANKS N°1 5-500 N°2 3-600 TOTAL. 9.100.

P.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 50933 57174 50938 57186
57566 56333 56411 56357
57181 57920 56668
56346 56584 59100
50721

WOLVS FUELLED ETC: 47451 S/C 40143 A-EX. 40061 S/C
25308 F11 25736 F11 40049 S/C.

STOCK EXAM. 25890 25797 16163 25840 25983
35459 35782.

35182 FLAT BATTERS PUT ON CHARGE. ETC.

50933 N°1 ENG EXHAUSTER & ALTERNATOR BELTS OFF.
AND BELTS REPLACED & ADJUSTED.

40143 ALXAM CARRIED OUT.

MON 13 - 12 - 82

CHARCOLES P. COX

CARS PULLED ON WAGON BTL 51200 - 51186
56359 56357

Locos 25308 P/I 25164-P/I 25136 P/I

40061 CAMEL APT TO FIND DRIVER REPORTED UNABLE TO
GET POWER COMPRESSURE COX CUT IN SWITCH STANDING POWER
TESTED POWER ALL ON TEST.

25164 loco worked with Flat BATT (SUN) FOUND BATT
CELLS EMPTY FILLED WITH WATER PUT ON CHARCO.
CHARCOING CURC TESTED FOUND OK. IT SMOED.

56359 ATTENTION TO HORNERS MADE TO WORK.

D. HILL. M. PRICE. 2000. P. COX

CARS PULLED ETC. -

51191

51177.

56343

56351.

Loco's PULLED ETC. -

25134 (P) 47520 (P).

51189. CALL TO LHANDUDNO HORNS NO 6 PUSST CHANGED
L.H GLOW PLUG CHANGED

51191 NO 2 WND + P/DL ISOLATED PAN BOLTS MISSING.

NEW BOLTS FITTED WND + P/DL DISISOLATED + FITTED

56343 FLAT BATT'S PUT ON CHANGED ETC. -

47520 DR REPORTED BRAKES TO LITAM. WND STOPPED.
FOR BRAKE BLOCKS ALSO RETURN SPRING MISSING.
NO 2 WND R.H SIDS FRONT.

51185 CALL TO LHANDUDNO PANEL LIGHTS FOR NO 2 + NO 3
CARS MISSING NEWSBULBS FITTED ALSO L.H
ITERATOR ON T/CAR GLOW PLUG CHANGED

51177 NO 1 ENG EXHAUSTER + ALTERNATOR BELTS MISSING
NEW BELTS FITTED.

TUESDAY DEC 14TH 82

	P/CAR	MILEAGES
	51202	25100
	50933	—
	51566	93650
	50668	92410
	50721	14680
	51200	50270
	51177	65260
	51191	11740
R.T. 67056 M.T		
u 65710 Full.		

FUELED IN TANKS N^o1 5.500 N^o2 1.900 TOTAL 7.400

B.A. ROBERTS. M. PRICE.

CARS FUELED ETC: 57202 58668 59100 58933 51200
 56349 50721 51566 58359
 51177 51191
 56351 56340

LOCOS 25136 S/C 25164 S/C 25308 S/C 40143 F1
 47543 F11

25134 A. EXAM CARRIED OUT LOCO STOPPED FOR
 BRAKE BLOCKS.

STOCK EXAM 35295 26015 25725 25975
 16175 26011 81180

25134 BRAKE BLOCKS. CHANGED. ETC:-

TUE 14-12-82

CAFOULDES P. COX B. HILL.

25134 A EXAM AND BRAKE BLOCKS TO CHANGE ALL
ROUND. ✓

25140 S/C 47462 (S)

CHAS FULL OIL WATER REC! - 51181
56346

47520 A EXAM AND BRAKE BLOCKS TO CHANGE ALL
ROUND 2 BRAKE SLACK ADJUSTERS WANTED
ON ORDER FROM CROWE. BRAKE RETURN SPRING FITTED

25140 A EXAM WHEN LOCO COMES IN

47520 A EXAM CARRIED OUT.
BRAKE BLOCKS CHANGED.
2 BRAKE SLACK ADJUSTERS REMOVED ONE
REPAIRED & REPLACED. NOW SLACK ADJUSTED.
WANTED SEIZED ON ORDER.

25140. A EXAM CARRIED OUT.
BRAKE BLOCKS CHANGED.
ONE SLACK ADJUSTOR REMOVED REPAIRED
REPLACED & TESTED.
SANDERS MADE TO WORK.

52062 CALL TO STATION WIPOR REPAIRED.

WEDNESDAY 15-12-82

	P/CAR	MILEAGES
	50933	—
	51566	93450
	50668	92660
	50721	14680
	51181	494380
	50228	609910
	51177	65510
	51947	13670
	52062	78470

~~ATTN: M. PRICE~~

u 65710 FULL

FUEL IN TANKS NO 1 5400 NO 2 400 TOTAL 5800

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 50933 50668 59100 51181 51177
 51566 50721 56346 56356
 51947 50228
 52062 56055

WOCOS. 25140 FI 25308 FI 25136 FI 40143 SIC
 47462 A EX. 47430 FI

STOCK EXAM 35182 25880 25797 16163 25940
 25985 35459

47462 A. EXAM CARRIED OUT & BRAKE BLOCKS CHANGING.

50228 NO 1 ENG EXHAUST MANIFOLD JOINTS RENEWED
 51947 NO 1 ENG SHUTDOWN SOLENOID REPAIRED.
 25136 NO 1 END DR SIDE WIPER ARM REPAIRED
 35459 FRAT BATT BUT ON CHANGE ETC NO 2 DYNAMIC
 FIELD FUSE RENEWED & BATTS CELLS TOPPED UP.

59100 REPAIRS TO LIGHTING SWITCH.

CAFOLLER P. COX

47462 Brake Blocks in Round and A Exam

47134 Fuel/INS 47538 (F)

47520 - 2 SHOCK ADJUSTERS TO REPAIR. AND BOLTS TO ADJUST.

CHAS FUEL ON WATER CHUCK.	51197	51194.	50929
	56361	56345	56269.

2 Brake Shock Adjusters from Station.

47134 Two Tons Horn No 2 and stuck. VALVE REMOVED CLEANED REPLACED & TESTED

51197. No 2 ENGINE EXHAUSTION & ALTERNATOR BOLTS OFF PULLEY. ALL BOLTS REPLACED & ADJUSTED

51177 CALL TO STATION. BUZZER IN CAB ADJUSTED & TESTED

56345 FLAT BATT'S. PUT ON CHARGES ETC.

51200. CALL TO LANDROVER WIPER ARM BROKEN WIPER TAKEN FROM 2ND MAN'S SIDE FITTED & ADJUSTED DR'S SIDE

50939. CALL TO STATION RED MARKER LIGHT NOT WORKING. NOW BULBS FITTED & TESTED

THURSDAY 16-12-82

	P/CAR	MILEAGES
	50933	-
	57566	94250
	50668	92900
	50721	14690
	57197	5240
	57194	134910
	50929	33710
	57191	12130

R.T. 65710 Full.

FUEL IN TANKS N^o1 3.900 N^o2 400 TOTAL 4.300

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 50668
 50933 59100 57197 57194
 57566 50721 56361 56345.
 50929 57191
 56269. 56340.

LOCOS FUELLED ETC: 25308 S/C 25736 S/C 25140 S/C
 40143 F/1 47538 S/C 25218 S/C

STOCK EXAM. 35295 26015 25725 25975 16175
 26011 81180

- 81180 DYNAMO BELT MISSING NEW BELT CUT & FITTED.
- 25308 W.H. SIDE SETTLING TANK GAUGE BROKEN NEW GAUGE FITTED
- 57191 W.H. HEATER FUEL PIPE BROKEN. REMOVED REPAIRED
 FUEL SYSTEM BLED & HEATER MAKING TO WORK.
- 50668 N^o1 ENG FLEX EXHAUST PIPE BROKEN. NEW PIPE
 FITTED
- 50721 N^o1 ENG THROTTLE MOTOR STUCK, STRIPPED & CLEANED
 GREASED OILED & TESTED.

THUR 16 - 12 - 82

CARFOLKES P. COX.

CARS FUELED ETC 51197 - 51194
56361 56345

25308 - CAME OUT TO YARD DOWN REPORTED UNABLE TO
GET POWER IN MOVENTS FOUND AIR PRESSURE CONTROL
AIR SWITCH CUT IN SET TO HIGH READJUSTED.

25140 S/C

51181 AT BANGOR MAINT PAULI UNKNOWN (SEE BELOW).
56346

25136 Insr. Reported SEARS WANTED NONE ON HAND TO FR.

D. HILL P. COX. M. PRICE 20.00.

CARS FUELED ETC.

50929. 150206

56269. 36058

Loco's. 47419 Boiler 1977.

51181 } CALL TO BANGOR SET FAILED. DRIVER REPORTED
56346 } BOTH ENGINES DEFECTIVE SET FLOATED BOTH
ENGINES R/D'S & D.S.D. HAULED TO SITE.

47538. CALL TO STATION DR REPORTED LOW IN POWER TO
FIELD DIVERTS NOT COMING IN. UNABLE TO
REPAIR @ STATION LOCO WORKED TO M/STATION
CREW MAINT. INFORMED

51181. BOTH ENGINES TESTED ON SITE NO.1 GASSET
BLOWN. NO.2 ENGINES SMOKING BAD ENGINES
FOUND SET TO BE HAULED TO CRESTON.

50409 CALL TO STATION ITEMS NOT WORKING NO. 5
FUSE CHANGED & TESTED REPAIRS CARRIED
OUT @ LLANDUDNO

56340 AT LLANDUDNO BUZZER NOT WORKING IN
VAN AS TESTED & TESTED

FRIDAY 17-12-82

	PI CAR	MILEAGES
	50933	—
	57566	94550
	50668	93170
	50721	14690
	50929	33880
	57194	135080
	50938	20710
	50206	—
	57181	494640
R.T. 65710 Full		

FUEL IN TANKS N^o1 2.700 N^o2 400 TOTAL 3.100

B.A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 50933 57566 50721 50929 57194 50206 56411 56058

LOCOS FUELLED ETC: 47419 S/C 47289 S/C 40143 S/C 25308 F/I 25136 F/I 25740 F/I

STOCK EXCH 35182 25880 25797 16163 25840 25985 35459

50721 EXHAUSTER USING EXCESSIVE OIL. ALL OIL PIPE CONN LOOSE & LEAKING. SCREWED UP & TESTED

47289 2 MANIFOLD JOINTS BROWN OUT ON PRESSURE CHARGER NEW JOINTS FITTED.

50938 N^o1 ENG FAN BELTS MISSING NEW BELTS FITTED & 2 NEW STUDS FITTED TO FAN MOTOR BED PLATE.

M Foulkes P. Cox

CARS RUN ON WATER BKT. 50927 - 50938
56214 56411

50927 } UNIT RAN IN SERVICE DUE TO FUEL BATT ON P/LMA AND T/CAR
56214 } BROUGHT ON SHED PUT ON CHARGE C/WL CHECKED
T/CAR NO 3 FUEL FUSE FOUND BLOWN REPAIRED.

RAN TANKS 65810 EMPTY.

CHANGED OUT TO STATION REPORTED KNOWING FROM UNDER BOGIE
ON PK 13592 SEE C/W REPORT. SHUT DOWN

D. HILL. P. COX. M. PRICE. CAR'S ROLLLED ETC:-

51203 51178
36339 36335

LOCO'S ROLLLED ETC:-

40131 (S). 25152 (F) 47440 (F)

50938 CALL TO STATION DA REPORTED ONLY ONE
TONE FROM HORN. ADJUSTED & TESTED

40131. DA REPORTED SANDONES NOT WORKING REPAIRED

25152. " " BAD BLOW IN LMC ROOM EXAM
& FOUND EXHAUST PIPE JOINTS ON PRESSURE
CHARGING UNCOUPLED NOW JOINTS FITTED
& TESTED.

47440 A.W.S. ISOLATED W/2 AND EXAM + FOUND
ROSET BUTTON TIPS NOT MAKING ROSET CLAMPED
& TESTED

SATURDAY 18-12-82

	PICAR	MILEAGES
	50929	34190
	51192	-
	50933	-
	57566	94850
	50668	93430
	50721	14690
	50927	16980
	57178	14310
	51203	17190
	57181	49460
R.T. 65710. H.T.		

FUEL IN TANKS N^o 1 4.400 N^o 2 5000 TOTAL 9.400

B. A. ROBERTS. M. PRICE.

CARS FUELED ETC). 50929 57192 50933 50668
 56269 56354 57566 50721
 50927 57178 51203
 56214 56335 56339.

LOCOS 25136 S/C 25152 S/C 25308 S/C 47440 S/C
 40143 A EX

STOCK EXAM. 81180 26011 16175 25975 25725
 26015 35295.

40143 A. EXAMINATION CARRIED OUT 0

51192. FLEX AIR PIPE BURST NEW PIPE FITTED + 2 NEW BKT
 BOLTS FITTED

16175 LAMP HOLDER IN TOILET DAMAGED. NEW HOLDER
 FITTED

51203 N.H. HEATER NOT WORKING FAULT TRACED TO
 WIRE BROKEN ON HEATER CONTROL PANEL WIRE
 REPAIRED + HEATER TESTED.

D HILL. P. COX

CAR'S. FUZZLED ETC:-

50948.	50938.	51194	51197	50206
56231.	56411	56345	56361	56058.

LOCO'S FUZZLED ETC:-

25140.(S) 47332.(S) 40126(S)

25140 SANDERS MADE TO WORK.

51192. CALL TO STATION. DR REPORTED. WIND SCRUW. WIPER.
NOT WORKING. REPAIRED & TESTED.

50948. NO 2 ENGINES. FAN BOLTS MISSING. ALSO STUDS.
IN FAN MOTOR. BROKEN. 2 NEW STUDS. FITTED.
FAN BOLTS FITTED & TESTED.

47332. HORN NO 2 AND 2ND MAIN SIDE. STUCK VALVE.
REMOVED. CLEANED REPLACED & TESTED.

56345. PLAT BATT'S CHARGED ETC:-

51197. EXHAUST MANIFOLD JOINTS BLOWING. NEW JOINTS.
FITTED & TESTED. NO 1 ENG

SUNDAY 19-12-82

		PLCAR	MILEAGES
02P02	P8112	57186	58700
02P02	JP112	50933	—
02P02	JP112	57566	94940
048	P8P02	50668	93770
5044	FRAT BATTERS PUT ON CHARGE	50721	14690
	ALSO BATTERY CABLES	50938	21100
		57203	17386
53500	Nº1, 2 VES EXHAUSTER	57181	—
	BELTS FITTED		
57181	Nº1, 2 VES EXHAUSTER SYSTEM		
	ALSO FRAT BATTERS PUT ON CHARGE		
57566	STARTERS MADE TO WORK		

FUEL IN TANKS Nº1 Nº2 TOTAL

P. A. ROBERTS. M. PRICE.

			50668	
CARS FUELLED ETC:	51186	50933	59106	50938
	56357	57566	50721	56411
57203				
56339				

WCCOS 40143 FI1 47538 A-EXAM.

STOCK EXAM. 25890 25797 16163 (25840 25983
35459.

47538 A-EXAM CARRIED OUT

50668 FRAT BATTERS PUT ON CHARGE CIRC TESTED ETC;
ALSO VACUUM SHOW BLOWING UP. EXHAUSTER PETS
FITTED + NEW WASHER FITTED ON H.S. VAC PIPE.

50433 FRAT BATTERS PUT ON CHARGE CIRC TESTED.

57186 Nº2 EXHAUSTER + ALTERNATOR BEGS REPLAZED
+ ADJUSTED.

MONDAY. 20TH DEC. 82

		P/CAR NO	MILEAGE.
		51189.	20920.
		51196.	53930.
		52046.	72680.
		50939	840.
R/T 65710 M/T.			

FUEL IN TANKS. NO.1 3,100 NO.2 5,000 TOTAL. 8,100.
D. HILL. B. PRITCHARD.

CARS FUELED ETC:-

51189. 51196 52046 51186 50933
 56343. 56336. 50939. 56357. 51566.
 51203 50938. 50668/59100./50721.
 56339. 56411

LOCO'S FUELED ETC:-

40143 (S) 25308. (R) 25136 (F) 47332 (F)

- 56339. HEATERS MADE TO WORK.
- 51189. FLAT BATT'S CHARGED ETC.
- 51196. NO.2 LWB EXHAUSTOR & ALTERNATOR BELTS
 OFF ALL REPLACED & ADJUSTED.
- 52046 } BAD AIR LOCK. FOUND FORWARD W.P. VALVE
- 50939 } STUCK. REPAIRED & TESTED.

B.A. ROBERTS, M. PRICE.

CARS FURNISHED ETC. 50500 51181
50444 56346

WOCOS FURNISHED ETC. 47482 F11 25152 F11

50444 FLAT BATTERS PUT ON CHARGE CIRC TESTED.
AMM BATTERY CELLS TOPPED UP ON NO 9 FUSE WRENCHES

50500 NO 1 ENG EXHAUSTER BELTS MISSING NEW
BELTS FITTED.

51181. NO 1 ENG FUEL SYSTEM EXAMINED & BLENDED
ALSO FLAT BATTERS PUT ON CHARGE.

25152 SANDERS MADE TO WORK.

47471 CARRIED TO STATION I.T.H. NOT WORKING. E.T.H.
EARTH FAULT DELAY TRIPPED RESET & TESTED

51197 CARRIED TO A HANUDWNO NO 1 ENG FLEX
EXHAUST PIPE UNCOUPLED. 3 NEW NUTS
& BOLTS FITTED

50203 WINDIPER ARM UNCOUPLED REFITTED
& ADJUSTED.

TUESDAY. 21ST DEC. 62.

	P/CAR NO	MILEAGE.
	50721	14690.
	50668.	93990.
	50970	N/F.
	51192	N/F.
	50939.	860.
	52046.	72700.
	51194	135960.
R/T 65710 m/t.		

FUELIN TANKS. NO 1 1,600 NO 2 5,000 TOTAL 6,600.

D. HILL. B. PRITCHARD.

CAR'S FUELLED ETC:-

50721 50970. 51192. 50500 50939. 51194
 59100. 56264. 56345. 50444. 52046 56343.
 50668.

LOCO'S FUELLED ETC:-

25153 (F) 40143 (F) 47482 (S) 25308 (S).

25153 SANDOZ MADE TO WORK.

47482. AIR PIPE TO WINDSCREEN WIPER MOTOR, DR'S SIDE NO 1 AND BROKEN PIPE REPAIRED & TESTED

50970. NO 2 AND EXHAUSTOR & ALTERNATOR BELTS MISSING NOW BELTS FITTED & ADJUSTED.

56345. FLAT BATT'S CHARGED ETC:-

STOCK EXAM ETC.

81180. 26011 16175. 25975. 25725 26015. 35295

25725 FLAT BATT'S PUT ON CHARGE ALSO DYNAMO BOLT MISSING NOW BOLT FITTED.

B. A. ROBERTS. M. PRICE.

CARS FUELED ETC: 51174
56358

WAGONS FUELED ETC. 25279 FI 25140 SIC 25752 SIC
40153 FI 40170 SIC.

Stock EXAM 38182 F/WAT BATHS PUT ON CHARGE - CIRC
TESTED.

51203 CAME TO WHANDUENO BOTH HEATERS REPAIRED
NO. 6 PIPE RENEWED - 1 NEW GLOW PLUG FITTED.

40153 HEADER TANK GAUGE GLASS BROKEN NEW
GAUGE GLASS FITTED.

51174 HORNS NOT WORKING HORN VALVE REMOVED
STRIPPED - CLEANED OF SCALE - REPLACED.

51194 CAME TO STATION AIR & AXLE LIGHT BULB
BLOWN NEW BULB FITTED.

25140 NO. 1 & 2 EXHAUST MANIFOLD JOINTS BLOWING
NEW JOINTS FITTED.

25279 BRAKES EXAMINED - BRAKES STROKES
ADJUSTED.

08 22nd Dec 52.

P/CAR NO	MILSAGO
51188.	120220.
50228	111320.
50660	104940.
50729	91290.
51179.	10740.
52046	72840
50939	1000.
51177	67110.

PULL IN TANKS NO 1 700. NO 2 3,500 TOTAL. 4,200.

D. HILL. B. PRIESTLAND

CAR'S PULLLED ETC:-

51188. 50228. 51179. 52046. 51177.
 56348 56055 56358 50939. 56351

50660 / 59070 / 50729.

LOCO'S PULLLED ETC:-

40143 (S) 25327 (S) 25152 (F) 25279 (S)
 25140 (F) 47501 (S) 47437 (S)

47501 LOCO STOPPED FOR BRAKE BLOCKS CHANGE DA REPORTED
 BAD BRAKES.

51177. NO 1 ENG- EXHAUST PIPE UNCOUPLED FROM MANIFOLD.
 NUTS & BOLTS MISSING. NOW NUTS & BOLTS FITTED
 & TESTED.

50228 DA REPORTED NO 1 ENGINES ON FULL REV'S ENG
 & P/DR ISLOWED THROTTLE SPRING DEFECTIVE.
 NONE IN STOCK. CAR TO CHURCH FOR REPAIRS.

STOCK EXAM BLUET

35459. 25983 25240 16163 25797 25890.

B. A. ROBERTS. M. PRICE.

CARS FUELLED ETC: 50929
56269

WOCOS FUELLED 40030 F11

47501 BRAKE BLOCKS REWRENED. (2) BRAKE SLACK
ADJUSTERS REMOVED. STRIPPED + REPAIRED
REBUILT + REPLACED.

50929 CAB HEATER NOT WORKING. FUSE BLOWN
TESTED WIRE BROKEN ON MOTOR + SHORTING
OUT. REPAIRED + TESTED.

40030 HORN VALVE STUCK N^o 1 END DR. SIDE. VALVE
REMOVED, STRIPPED + CLEANED OF DIRT
+ SCARE REPLACED + TESTED.

RAM TANNER N^o 66715. UNLOADED.

THURSDAY. 23RD DEC. 82.

	P/CAR NO	MILEAGE
	51203	18020
	51194	136460
	51198	157990
	50929	34870
	50729	91290
	59070	
	50660	105190
	50939	1300
	52046	73150
R/T. 65531. Full.		
R/T. 65515 65715. m/c		

FULL IN TANKS NO 1 6,100 NO 2 5,200 TOTAL 11,300

D. HILL B. PRITCHARD.

CAR'S FUELLED ETC:-

50939. 50929. 51203. 51194 51198.
52046. 56269. 56339. 56345. 56337.

50660 / 59070 / 50729.

LOCO'S FUELLED ETC:-

47482.(S) 40143(F) 47501(F) 25279.(F) 25140(S) 25308.(S)

STOCK DAM. ELUCT.

35295 26015. 25725 25975. 16175 26011 81180.

52046. A.W.S. ISOLATED DEISOLATED + TESTED ALSO
FRONT LIGHT BULBS FOR LONG + AIR/AXLS NO 2.
CAR BLOWN. NOW BULBS FITTED + TESTED.

59070 FLAT BATT'S PUT ON CHARGED ETC:-

50660 " " " " " "

50729. L. H. INTRATOR MADE TO WORK.

47482 HOSE PIPE ABOVE FRONT END OF LONG CHANGED COOLANT
TOPPED UP + TESTED.

25140 STANDOFF MADE TO WORK.

26015 MK. FLAT BATT'S CHARGED ETC:-

51203. NO 1 LONG EXHAUSTOR + ALTERNATOR BOLTS MISSING
NEW BOLTS FITTED + ADJUSTED.

51194 INTRATORS MADE TO WORK.

B. A. ROBERTS. M. PRICE.

CARS FURNISHED ETC. 57196
56336

HOLOS EXAM 40150 S/C

57196 N°2 ENG MANIFOLD JOINTS BECOMING NEW JOINTS
FITTED.

57198 CANNED TO STATION HEATERS NOT WORKING N°6
FUSE RENEWED.

741818 } CANNED TO OLD YARD BUFFER LOCKED UNLOCKING
746192 } BUFFER WITH JACKS & PACKING.

25308 A-EXAM CARRIED OUT.

40050 CANNED TO STATION NO NIGHTS ON HOLO
NEW ISAMP LIGHTING FUSE FITTED

FRIDAY. 24TH DEC 82.

P/CAR NO	MILEAGE
51196.	54450.
50729	91290.
50660	105450
51186	59560
51203.	18310.
51191	13570.
52046	73470
50939	1610.

R/T 65531 Full.
" 65715. M/T.

FUEL IN TANKS. NO 1 6,100 NO 2 3,300. TOTAL. 9,400.

D. HILL. B. PRITCHARD.

CAR'S FUELLED ETC:-

51196. 51186. 51203. 51191 52046.
56336. 56357. 56339. 56340. 50939.

50729 / 59070. / 50660.

Loco's FUELLED ETC:-

40143.(S) 25279(S) 25308.(F) 25194(F)
47463. "A" EXAM CARRIED OUT

Stock EXAM W/OUT.

35459. 25983. 25840 16163. 25890. 25797 35182.

- 25890. DYNAMO BELTS MISSING. NEW BELT FITTED BATT'S CHARGED.
- 51196 NO 2 ENG EXHAUSTOR & ALTERNATOR BELTS REPLACED.
- 56336 MOTORS MADE TO WORK.
- 51191 NO 2 ENG EXHAUST MANIFOLD JOINTS CHANGED.
- 40143 HORN 2ND MAIN SIDE NO 2 ENG. HANDLE BROKEN. VALVE REMOVED REPAIRED REPLACED & TESTED.

B. A. ROBERTS. M. PRICE.

CARS TURNED ETC: 57192 57202 57183
56345 56349 56344

LOCOS 40104 FI 2 40135 SIC

57192 NO. 1 ENG ALTERNATOR & EXHAUSTER BELTS
MISSING. NEW BELTS FITTED

57192 NO. 1 ENG EXHAUST PIPE UNCOUPLED 3 NEW
NUTS & BOLTS & CONE JOINT FITTED.

40135 SANDERS MADE TO WORK.

50439 CARRIED TO WANDUWNO NO LIGHTS IN
TRAIN. NO. 6 LIGHTING FUSE RENEWED

50203 CARRIED TO STATION HEATER NOT WORKING
NEW GLOW PLUG FITTED.

25th Dec. 82.

P/car No MILEAGE

50939.	1920
52046.	73770.
51192	N/F
51183	48886
51202	27810
51198	158420.
51186	59840.
51182.	N/F

D. HILL. B. PRITCHARD.

CAR'S FUELLED ETC:-

50939.	51192.	51183.	51202.	51198.
52046.	56354.	56344	56349.	56337.

51186/56357. 51182/56341.

LOCO'S FUELLED ETC:-

47468 (S).

FROST PRECAUTIONS CARRIED OUT.

B. A. Roberts. M. PRICE 0800 - 2000

FROST PRECAUTIONS CARRIED OUT.

Nov 27-15-85

26th Dec. 82. *(mirrored text)*

D. HILL. P. COX.

STOCK EXAM

35295 26015 25725 25975 16175 26011 81180.

FROST PRECAUTIONS CARRIED OUT

25279 (S) 25308 (A) 47082 (E)

40104 Sawdust made to work

25279 No 2/Batt R.H. 25000L Sand P.P. 10000

25357 Batt BATT Put on 25000L

25349 Batt to station Hill 10000L made to work

2518 25000L Frost precautions carried out

25118 - 21505 - 21183 - 25321

25185 - 21182 - 25000L 25321 25321

25321 25321 25321 25321 25321

25321 25321 25321 25321 25321

Mon 27-12-82

CA BULLUS B. PRITCHARD

PLANT	MILES
51183	
51182	
51202	
51198	
51186	
51192	
52046	
50939	

River we have No1 6000 No2 2,100 TOTAL 8,100
 Frost Precautions Carried out

Chalk Creek etc. 51183 - 51202 - 51198
 56344 56349 56337

51182 - 51186 - 51192 - 52046
 56341 56357 56354 50939

Stock on 6: 81180 - 26011 - 16175 - 25975 - 26015 - 35295

Locos: 47468 fl 40104 fl 25194 fl

D. HILL P. COX.

CAR'S ROLLED ETC:-

51186.
56357.

Loco's ROLLED ETC:-

25279 (S). 25308 (F). 47082 (F)

40104. SANDER'S MADE TO WORK.

25279. N°2 BOGIE R.H. LEADING SAND PIPES RENEWED
& TESTED

56357. PLAT BATT'S PUT ON CHARGE ETC:-

56349. CALL TO STATION. L.H. WATER MADE TO WORK.

TUE 28-12-82

Chavannes B. PITCHNEID

	P/CH2	MILES
	51198	158480
	51202	27810
	51183	48910
	51192	N/A
	52046	73970
	50939	2110
	51186	59840

FUELIN TANKS No 1 6000 No 2 1,800 TOTAL 7,800

Locos Re - Post PREVENTIONS CARRIED OUT
 CHAS FUEL ON WATER TOW. 51198 - 51202
 56337 56349

51192 - 51183 - 52046 51186
 56354 56344 50939 56357

Loco's 25080 P/I L

STEEL - 35489 - 25983 - 25840 - 16163 - 25797 - 25890 - 35182
 50939 - DYNAMO BELT OFF REFITTED ON CHAS

- 50939 - ATTENTION TO AIR HOSE MADE TO WORK
- 51183 - ATTENTION TO HEADS ONLY RIGHT HAND WORKING.
 LEFT HAND FUELY FUEL SCINGER INSIDE HOUSING. P.H.D.A
- 51186 - 2 HEADS MADE TO WORK.
- 51183 - ATTENTION TO HEADS 2 MADE TO WORK.
- 56344 - ATTENTION TO HEADS ONLY ONE WORKING L.H. WILL NOT WORK.
- 52046 - ATTENTION TO BUSHES MADE TO WORK ALSO FRAME BUSHES FITTED.

D. Hill. P/COX.

Loco's FURLED ETC. -
40135. (F) 47082 (S). 25080 (S).

CAR'S FURLED ETC. -
51196
56336.

51196. Loco Hauled FROM HOLYHEAD. EXHAUSTOR + ALTERNATOR BELTS MISSING. ALSO THAT BATT'S, ENG'S + F/DRS D.S.D. ISOLATED. BROUGHT ON SITE. NEW BELTS FITTED. BOTH ENG'S. BATT'S PUT ON CHARGE. ALSO FOUND NO.1 ENG FAN BELTS SLACK. + STUDS IN FAN. MOTOR BROKEN REMOVED NEW STUDS. FITTED REPLACED. FAN BELTS ADJUSTED + TESTED. ENG'S + F/DRS. D.S.D. DEISOLATED.

47082 WINDSCREEN WIPER 2ND MAN'S SIDE NO.2 AND NOT WORKING MOTOR REMOVED STRIPPED REPLACED + TESTED.

43531. CALL TO STATION. EARTH FAULT. FLAG RESET + TESTED

56273. PLAT BATT'S CHARGED ETC. -

WED 29-12-82

CHARLES B. PRITCHARD

P/Unit	MILES
51196	54830
50723	60240
50674	264960
52046	74220
50939	2360
51186	59980
50940	M/F
51174	22650

FUEL IN TANKS No 1	6,200	No 2	900	Total	7,100
--------------------	-------	------	-----	-------	-------

CARS Fuel oil WATER Btz. 51196 - 52046
56336 50939

50723 - 51186 - 50940 - 51174
59064 56357 56273 56333
50674

STEEL: 35295-26015-25725-25975-16175-26011-81180

LOOS 47468 A EXAM COMPLETED AT 000746 MILES
30 Gals LUB OIL PUT IN ENGINE SUMP ALSO STEEL TAPPED UP.

47088 F/1

D. HILL P. COX.

CAR'S. FUELLED ETC:-

51178.

56.335.

Loco - FUELLED ETC:-

25308. (F). 25279 (S). 25194 (F) ~~40143~~ 40143.

25279. DR REPORTED. BRAKES WANT ADJUSTING
ALL BRAKE SLACK ADJUSTERS. ADJUSTED. L.H. BACK
NO.1 BOGIE SLACK ADJUSTOR. SEIZED REMOVED. STRIPPED.
REPAIRED REPLACED & ADJUSTED. BRAKE TEST CARRIED OUT.

25194. DR REPORTED BRAKES. WANT ADJUSTING.
ALL BRAKE SLACK ADJUSTERS. ADJUSTED & BRAKE TEST CARRIED OUT.

51178. L.H. HEATER. MADE TO WORK.

47463 CALL TO STATION. DR REPORTED LOSS OF POWER &
NO.3 T/MOTOR SMOKING BAD. LOCO TAKEN OUT OF
SERVICE BROUGHT ON SITE T/MOTOR EXAM FOUND
BRUSH GUAR & WIRING BURNT. NO.3 & NO.4 T/MOTORS
ISOLATED LOCO TO CROWD TOP'S & CROWD MAINT. INFORMED.

51196 CALL TO LLANVAUNO. DR REPORTED GEAR SLIP IN ALL
GUAERS NO.1 UNG. EXAM & FOUND FLOOR WITOUT
DEFECTIVE. UNG. I/DR ISOLATED TO UTATOR
FOR REPAIRS.

THUR 30-12-82

CHAROLLES S. PRITCHARD

PLATE	MILES
51196	54870
51191	14270
50716	34620
50675	34080
52046	74540
50939	2670
50203	126320
51189	22320

FUEL IN TANKS No1 5100 No2 700 TOTAL 5800

CHAS FUEL DEL WINTER. (32) 51196 - 51191
56336 56340

50716 52046 - 50203 - 51189
59275 50939 56080 56343
50675

Locos 47438 P/1

STOCK 35459-25983-25840-16163-25797-25890-35182

- 51191:- CAME OUT TO STATION DRIVER REPORTED NO 2 ENGINE KNOCKED OFF AND WAS NOT IN SINGI FORMS RAS RAN BELTS MISSING BRG AND FINDER DRIVE BEHIND FOR ATTENTION WHEN ON SHED NEW BELTS FITTED.
- 47438:- ATTENTION TO THE HIGH VALVE (SINGING ON) VALVE PIPES CLEANED AND VALVE SERVICED.
- 50939:- INTERNATIONAL BELTS OFF PULLEYS ALL REBUILT PRIOR ON CHARGE.

HILL P. COX.
CAR'S PUSLED ETC:-

51197 51189
56361 56343

Loco's PUSLED ETC:-
40158 (S) 40143 (F) 25194 (S) 25308 (S) 25279 (F)

- 40158. SANDOXS REPAIRED. = TESTED.
- 51189. DR REPORTED. NO1 ENG CUTTING OUT. TESTED @ LLANDUDNO. COOLANT TOPPED UP. THROTTLE ADJUSTED.
- 47347. CALL TO YARD. DR REPORTED. HORN STUCK NO2 ENG. VALVE ROYALTY STRIPPED REPLACED + TESTED.
- 50940. CALL TO LLANDUDNO. DR REPORTED NO2 ENGINE'S EXHAUST PIPE UNCOUPLED NUT + BOLTS MISSING NOW NUTS + BOLTS FITTED + TESTED.

Per 31-12-82

CITROUILLES B. PRITCHARD

PLATE	MILES
51197	7250
51189	22530
51905	N/R.
51191	14540
50695	639220
50739	42280
52046	74850
50939	2980

RUE IN TANKS No1 4,300 No2 700 Total 5,000

CHRS KEELS ON WATER etc. 51905 - 51191
56488 56340

51197 - 51189 - 52046 - 50739
56361 56343 50939 59261
50695

LOOS 47444 A EXAM COMPLETED MILES N/R.

STEEL: 81180 - 26011 - 16175 - 25975 - 25725 - 26015 - 35295

51189 RMT BATT PUT ON CHARGE UNABLE TO START ENGINE.

D. Hill. P. Cox.

CAR'S RAILLED ETC:-

50628
56353

LOCO'S RAILLED ETC:-

40143 (S) 25308 (F) 25279 (S) 25194 (F) 47341 (S)
47321 (S)

PLAT BATT'S PUT ON CHARGE ETC:-

WAGON NO 295917
278808

BOTH DERAILED. RERAILED WITH JACKS - PACKING

First in tank No 1 3000

22008 - 2112
22522 18522

2112 - 2500 - 2112 - 2112

2112 - 2500 - 2112 - 2112
22008 - 2112 - 2112 - 2112

22008 - 2112 - 2112 - 2112 - 2112 - 2112

2112 - 2112 - 2112

D. Hill P. Cox

CAR'S PULLED ETC:-

51193/56. 50940/56.273

4000'S PULLED ETC:-

47321 (F) 40143 (F) 25308 (S) 25279 (F)
25194 (S) 40181 (F)

N^o2 ENGINES. EXHAUSTOR & ALTERNATOR BOLTS MISSING
NOW BOLTS FITTED & ADJUSTED.

56273. FLAT BATT'S CHARGED ETC:-

51177. CALL TO L. WARDNO. UNABLE TO START N^o2.
ENGINE. FOUND STARTER MOTOR STUCK. REMOVED.
ENG. RUN UP & TESTED.

MAKOULES B. PRITCHARD

✓ 47321: Fuel Full Header Empty.	50628	2300
40143 " " 1/2 TANK.	51567	17780
25194 " " Full	50926	17760
2 25308 Fuel Full Header Full	51196	55300
	50939	3280
	52046	75160
	51184	146950
	50697	247320
	50655	25940

PLEASE NOTE: FUEL VALVE FOR MAIN LINE LOWS KEAKING RICE BAD ALSO SPLIT IN WATER PIPE CONNECTION FOR MAIN LINE LOWS. CENTRAL BANGOR T. OWAN. O.D.M

CARS ON WATER CHECK LIST. 50628 - 51567
56883 50926

51196 - 50939 - 51184 - 50697
56336 52046 56342 59263
50655

STOCK: 35295 - 26015 - 25725 - 25975 - 16175 - 26011 - 81180

LOCS 40050 S/c 47468 S/c

40050 FOUND Header Tank Empty BROUGHT ON PUMP Header Filled.
47468 ALSO Header Tank Empty BROUGHT ON PUMP Header Filled.
47321 UNABLE TO START LOCO DUE TO Header Tank FOUND Empty
NO DRIVERS TO MOVE LOCO ONTO HOUSROAD TO HAVE Header Filled.
50939: FLM BAIT PUT ON CHARGE.
25725: LOW LIGHTS DYNAMO BELT OFF PULLEY RELITTED PUT ON CHARGE. CURA CHECKED
25975: LOW LIGHTS PUT ON CHARGE CURA CHECKED BELT RISE BLOWN REPAIRED

Monday 3rd JAN 83

	P/CAR No	MILEAGE.
	50228.	872770.
	51193.	36300.
	50940.	N/F.
R/T. 65715. M/T.		
" 65531 Full.		

FUEL IN TANKS No 1 2,400. No 2 700. TOTAL 3,100.

D. HILL. M. PRICE.

CARS. FUELED ETC. -

50228. 51193. 50940. 51184
 56055. 56502 56273 56342.

50655/59263/50697. 50926/51567. 50628/56353.

LOCO'S FUELED ETC. -

47434. (F)

STOCK EXAM.

35295 26015 25725 25975 16175 26011 81180.

50697. No 2. ENG + R/R ISOLA TOB. STARTER MOTOR.
 DEFECTIVE. F. H. S.

50228 NO 1 ENG MANIFOLD JOINTS BLOWING NOW JOINTS
 FITTED + TESTED.

47434. Dr Rotor TOB. EXHAUST PIPE JOINT ON PRESSURE
 changed TOP BLOWING NOW JOINT FITTED + TESTED.

MON 3-9-83

WROUGHTS B. PRITCHARD

CARS RUN ON WATER DTC 51178 - 51905
56335 56488

51905 } Hauled from Heymond down reported no air with
56488 } Isolating engines and final drives tracing
all the setting up of micro control switches etc.
- core repaired unit or for service

Locos 47321 Header tank empty filling tank reported
water draining off from system tracing for water
leaks etc. A number of hose pipe clips screwed up.

Locos 40181 S/C 47321 S/C 40143 S/C 46050 P/I
25308 P/I 25194 P/I

All locos Header tanks topping up. brought on Pump Road.